



भारत सरकार
GOVERNMENT OF INDIA
खान मंत्रालय
MINISTRY OF MINES
भारतीय खान ब्यूरो
INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय
OFFICE OF REGIONAL CONTROLLER OF MINES



दूरभाष: (080) 39505368 / 29720499
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर,
बेंगलुरु -560022

सं/No.KNT/BLR/FE/150/BNG/VOL-II Mine-code:30KAR03017दिनांक/Dated: 05/09/2022

To,

Dr. Meda Venkataiah,
Nominated Owner & Whole Time Director
Vyasnakere Iron Ore Mine
M/s. MSPL Limited
Baldota Enclave, Abheraj Baldota Road,
Hosapete, Ballari- 583 203
Email id-meda.venkataiah@mspllimited.com, email@mspllimited.com, madhusudhan.k@mspllimited.com,
pvrao@mspllimited.com

विषय/Subject: **Violation of provisions of MCDR 2017 read with MCDR(Amendment),2021 in respect of your Vyasnakere Iron ore Mine, ML 2416 of M/s.MSPL Ltd.over an extent of 354.71 ha, inVyasnakereVillage, HosapeteTaluk, Ballari District of Karnataka State.**

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 read with Mineral Conservation and Development (Amendment) Rules, 2021 were found violated in your above mine during inspection on 19.08.2022by undersignedin presence of Shri P. Venkateswara Rao, Mine Manager, Shri Domic Savio J, Mining Engineer, Shri Prashant Laharia, Geologist and other mining officials:

Rules	Nature of Violations observed
11 (1)	Review and updation of Mining Plan was approved by IBM vide letter no. 279/143/90/BNG dated 04/11/2016, for the period 2017-18 to 2021-22& Final Mine Closure Plan was approved vide IBM letter no 279/143/90/BNG/FMCP dated 25/02/2021. The deviations observed in mining operation vis-à-vis approved documents are given below. i) It was observed during inspection that the height and width of the few benchesof North & A block at North western portion have not been maintained as per the proposal between Section NA-NA' to NC-NC'. Also, the vertical extent(mRL) of Block-B at Sec J-J' have been developed beyond the proposed vertical limit of 683 mRL. ii) The waste dumping at dump no 3 at South eastern portion have been carried out beyond the proposed extent. (Actual N-1681966 E-649317).
26(2)	The yearly report as required under Rule 26(2) of MCDR 2017 setting forth the extent of protective and Rehabilitative works carried out as envisaged in the approved final mine closure plan and if there are any deviations, reasons thereof shall be submitted before 1 st of

	July every year. The yearly report has not been submitted as per the provision of this rule and FMCP approval condition.
31(4)	The plans and sections required under these rules shall be maintained up to date showing also the respective proposal of approved mining plan for various activities pertaining to that year, within three months in case of category 'A' mines as referred to in clause (a) of sub-rule (2) of rule 55. It was observed during inspection that the plans maintained have not shown the respective proposal of approved mining plan as per the provision of this rule.
34(A)(1)	The processed output [digital elevation model (DEM) and Orthomosaic] have not been submitted in accordance with the Standard Operating Procedures under sub rule (5) of rule 34A of MCDR, 2017 for carrying out drone survey and submission of Digital Aerial Images of Mining areas. i)The DEM resolution is 36 cm which should be 15 cm per pixel or better for DEM. ii)The GCP co-ordinates have not been submitted in degrees, minutes and seconds. iii)The shp files under map of the mining lease area i.e., Actual excavation, backfilled area, waste dump, afforestation etc. have not been prepared as per the data output and format for SOP. The backfilled area is overlapping with the actual excavation area. Also, the extent of dump no D-3 have not been prepared correctly. The afforestation, Reclaimed & Rehabilitated area shp files have not been prepared correctly in line with approved document. The nomenclature has also not been prepared/maintained as per the approved plan. iv)The shp. file of Boundary pillars has not been provided in polygon type. Additionally, the co-ordinates have not been provided in UTM as per SOP. v)The output data submission form for the drone survey i.e., Annexure-I with all details as per SOP have not been submitted in the soft copy.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR (Amendment), 2021
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty-Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-
(Sandeep Kumar Singh)
Assistant Controller of Mines
Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sd/-
(Sandeep Kumar Singh)
Assistant Controller of Mines
Indian Bureau of Mines