



**GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
OFFICE OF THE REGIONAL CONTROLLER OF MINES**



Tel No.080 23371027
Fax No.080 23373287
Email ID: ro.bangalore@ibm.gov.in, rcombng@rediffmail.com

29, Industrial Suburb, II Stage
Tumkur Road, Goruguntapalya
Yeshwantpur, Bangalore-560022

No. KNT/BLR/Fe/397/BNG/

Dated: 22/3/2016

To,

The Managing Director

M/s Mysore Minerals Limited

Subbarayanahalli Iron Ore Mines

Bellary District, Karnataka.

Fax- 080-22213172/ 08395-260401

Subject:- Violation of provisions of MCDR 1988 in respect of Subbarayanahalli Iron Ore Mine (ML No. 2629) over an extent of 80.06 ha in Sandur Taluk & Bellary District, Karnataka State...Reg.

Sir,

The following provisions of Mineral Conservation and Development Rules 1988 were found violated in your above mine during the inspection on 13/8/2015 & 14/8/2015 by undersigned in the presence of Mines Manager Shri Ningappa & Geologist Shri. Rameshappa.

Rule 13(1)	The Scheme of Mining was approved vide letter No. 279/466/95/BNG dated 16/17.04.2015 for the period from 2015-16 to 2019-20. The deviations observed in mining operations vis-a-vis approved document are given below: (i) In part-A, under future exploration proposals, it is proposed to drill 28 nos. of RC/Core drill during the year 2015-16, with the grid interval of 100 x 100 for 3000 meterage. The proposed exploration drill holes & locations are marked in the plate No. 4 & 5 respectively. But the proposed drill holes are not carried out as proposed in the approved documents.
Rule 45	(i). While scrutinizing the annual returns for the year 2014-15, the production reported from the open cast working is 49,06,248 tonnes and from the dump workings 1,28,776.51 tonnes, but as per the approved document, there is no such proposals of production from dump workings. During the inspections, no such dumps were shown in the field for reference.
Rule 27(4)	The plans & sections required under these rules shall be maintained up to date within three months in case of category 'A' mine. But, the same are not maintained. During the inspection, it was informed that the plans & sections are maintained, up to June, 2015. But the new additional pit and its locations on the western side, as indicated in the above violation were not brought out in the updated plans, the new pit reveals, were operated for some long periods.

02. In this connection, it is to bring to your notice that the above violations constitute an

offence punishable under Rule 58 of MCDR 1988. Further, the violation of Rule 13(1) of MCDR may also attract provision of Rule 13(2) of MCDR 1988 regarding suspension of mining operations till the compliance of the violations.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty five) days from the date of issue of this letter.

Yours faithfully,

(C. Parameshwaran)
Dy. Controller of Mines

Copy for kind information to :

1. The Controller of Mines (SZ), IBM, Bangalore.
2. The Director, Dept. of Mines & Geology, Govt. of Karnataka, Khanij Bhavan, Race Course Road, Bangalore 560 001.

Yours faithfully,

(C. Parameshwaran)
Dy. Controller of Mines