



भारत सरकार Government of India

खान मंत्रालय Ministry of Mines

भारतीय खान ब्यूरो Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines

100, ओल्डनेहरू कालोनी, देहरादून (उत्तराखंड) 248001 /100 Old Nehru Colony, Dehradun (U.K.)248001

TEL- 0135-2676350 / 2671896, E-mail - [ro.dehradun@ibm.gov.in](mailto:ro.dehradun@ibm.gov.in)

Violation-Letter  
E-MAIL / REGD A.D.



फाईल संख्या File No: HP/SRM/LST-42

Mine Code: 38HPR10037

दिनांक, 21-03-2023

सेवा में To : श्री राजेन्द्र सिंह  
खान मालिक

E-mail: [gauravnegi14@gmail.com](mailto:gauravnegi14@gmail.com)

बरवाना चूनापत्थर खान, गांव-रनफुआ, पोओ-अंधेरी,  
तहसील-सांग्रह, जिला-सिरमौर, हि.प्र. 173001

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Barwana Limestone Mine, Mining Lease over an area of 2.94 ha located near Village: Barwana Tehsil: Renuka Ji, District-Sirmour, H.P State.

महोदय Sir,

उपरोक्त खान का निरीक्षण दिनांक 24.02.2023 को श्री नारायण सिंह राणा खान प्रबंधक व श्री गौरव नेगी, खान मालिक प्रतिनिधि की उपस्थिति में अधोहस्ताक्षरी द्वारा किया गया था एवं निरीक्षण के दौरान खनिज संरक्षण एवं विकास नियमवाली 2017 के निम्न प्रावधानों का उल्लंघन पाया गया।

| RULE NO. | NATURE OF VIOLATION OBSERVED   |
|----------|--|
| 11(1)    | Mining operation were not carried out in accordance with the approved Review & Updation of mining plan with PMCP vide letter no 614(2)/MP-B-216/12 - DDN dated 26.07.2022 to the following extent:<br>i. Para2.2.5.5, Page no.26 during the year 2022-23, it was proposed to carry out 04 core bore holes with total 80 metrage but during the inspection it was observed no boreholes was carried out during the year 2022-23.<br>ii. Para 4.2.2.2 Page no 33 As per proposal during year 2022-23, it was proposed to carry out Mining Operations by formation of Benches of 5 mtr height from 1440 mRl to 1415mRl but during the inspection no such benches formed found. Also Benches height of existing benches found more than proposals.<br>iii. Para 6.2.2.2 Page 55 as per proposals during year 2022-23, it was proposed to be erected 40 meter fencing in mine but during the inspection same was not found.<br>iv. Para 4.2.1.3 Page no 32 as per proposals along the Dumps, 165 meter retaining wall to be erected during year 2022-23 but same was not found during the inspection. |
| 55       | Every holder of mining lease shall employ a Mining Engineer in the mine. But Mining engineer has not been appointed in the Mine.   |

2. इस संबंध में, यह आपके संज्ञान में लाया जाता है कि नियम 11(1) का उल्लंघन नियम 62(1) एमसीडीआर नियम, 2017 के तहत दंडनीय अपराध है व नियम 55 के उल्लंघन पर एमसीडीआर संशोधन नियम, 2021 की अनुसूची 3 में निर्धारित नियम 62 (2) के तहत दंडनीय होगा।
3. इसके अतिरिक्त नियम 11(1) की पालना निर्धारित समयावधि में न होने पर नियम 11(2) के तहत खनन कार्य स्थगन करने की अनुसंशा की जा सकती है, और / या आपके विरुद्ध अभियोग दायर किया जा सकता है।
4. अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का तत्काल सुधार कर इसकी सूचना इस पत्र के जारी होने की तिथि से 45 (पैंतालीस) दिनों के अंदर इस कार्यालय को भेजे।

भवदीय Yours faithfully,

(दामोदर प्रसाद शर्मा / D P Sharma)

सहायक खान नियंत्रक /Assistant Controller of Mines  
भारतीय खान ब्यूरो / Indian Bureau of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- 2- निदेशक उद्योग निदेशालय, हि0 प्र0 सरकार, उद्योग भवन, शिमला (हि0 प्र0). (geologicalwing@gmail.com)
- 3- गार्ड फाइल

०१८  
21.03.2023  
सहायक खान नियंत्रक /Assistant Controller of Mines

| RULE NO. | NATURE OF VIOLATION OBSERVED  |
|----------|---|
| 110)     | Many proposals were not carried out in accordance with the approved Plans & Schemes of the mine. The last one (110) was dated 26.07.2022 to the following extent:<br>i. Para 1.1.2 Page no. 26 during the year 2022-23, it was proposed to carry out the work of 1000 sq. m. but only 500 sq. m. was carried out during the year 2022-23.<br>ii. Para 1.1.2 Page no. 27 As per proposal during year 2022-23, it was proposed to carry out Mining Operations by formation of benches of 2.5 m height from 14-18 m to 14-18 m. But during the inspection no such benches were found. Also benches of existing benches found more than proposed.<br>iii. Para 1.1.2 Page 27 As per proposals during year 2022-23, it was proposed to be started 40 meter fencing in mine for during the inspection same was not found.<br>iv. Para 1.1.2 Page no. 28 As per proposals along the Pumping for water retaining wall to be started during year 2022-23 but same was not found during the inspection. |
| 21       | Every holder of mining lease shall employ a Mining Engineer in the mine. But Mining engineer has not been appointed in the Mine.  |

प्रतिलिपि सूचनार्थ प्रेषित :-  
1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)  
2- निदेशक उद्योग निदेशालय, हि0 प्र0 सरकार, उद्योग भवन, शिमला (हि0 प्र0). (geologicalwing@gmail.com)  
3- गार्ड फाइल

Assistant Controller of Mines  
Indian Bureau of Mines