

भारत सरकार / GOVERNMENT OF INDIA
खान मंत्रालय / MINISTRY OF MINES
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES,
GANDHINAGAR

File No.: MCDR-MiFL0BXT/144/2022-GNR-IBM_RO_GNR

Date : 18/02/2026

To: Shri/M/s. N/A, Nominated Owner,
ALIMIYA, 16, SAMRUDHHI COMPLEX
,NYAY MANDIR, HIMATNAGAR,
Dedhrota Village & Mandal, Sabar Kantha
district, Gujarat,- 383001

Subject: Violation of provision of Mineral Conservation and Development Riles, 2017 in respect of your
07GUJ14023(07GUJ14023) over an extent of 20 ha in Dedhrota in , Sabar Kantha, Gujarat

महोदय, आपकी उपरोक्त खान का रव्यू ऑफ माइनिंग प्लान, एमसीडीआर तथा स्टार रेटिंग नरीक्षण स्नेहलकुमार पटेल, सहायक खनन अभियंता द्वारा दिनांक 19-11-2025 को श्री हरष त्रिवेदी (क्यूपी), श्री सुखानंदी प्रतीक (भू-वज्जिजानी) एवं टीम की उपस्थिति में किया गया तथा उक्त नरीक्षण के समय खनजि संरक्षण एवं विकास नियमावली, 2017 के नमिन्लखिति नियमों का उल्लंघन पाया गया-

Summary of Violations :

Items for Reporting	As Per Plan	Actual	Deviation	Rule	Reason
Boundary Pillar	20 no of boundary pillar are proposed in mining plan.	During inspection no boundary pillar are found except 6 pillars.	14 boundary pillars are not found.	Rule 11(1),	Boundary pillars not maintained
Drone Data	Drone data submitted on 04-07-2025	The Submitted output/details of the drone survey were not found as per the SOP issued by under rule 34A(5). The Orthomozai c.tif is not a valid or recognised data source; all mining features	Data not attached as per SOP.	Rule 34A(1),	Data not attached as per SOP.

		have not been indicated in mining feature.shp file.			
The following mining operations were not carried out as per the Approved Review of Mining plan No MCDR-MPCP0CaFI/34/2022-G NRIBMROG NR MP-467 dated 29-03-2023 :-	As per approved Mining Plan Mining operation shall be carried out leaving behind 7.5 m from lease boundary.	Excavation was found in the 7.5 m boundary zone and outside the lease area near Boundary pillars no. 1,2, 4,5,6,7, 9,10,11,12, 15,16,17,18, 19,20 and other places. Co-ordinates details are attached.	Excavation deviated from the approved proposal.	Rule 11(1),	Excavation deviated from the approved proposal.
Annual Return: Scrutiny of Annual return on sale value, Ex. Mine price & production cost	Sale value:Rs. 86 519478.02/522630.270 tonn Ex. Mine price: Rs. 653.13/tonn Production cost: Rs. 465.94/tonn	Sale value: Rs.165.54/tonn	Sale value too low. Esigned by: Sunil Date: 19/02/2026 11:23:07 AM	Rule 45(7),	Sale value too low.
Environment: Plantation & Survival rate	Plantation : 200, Survial Rate : 60	About 50 plants were seen in the proposed area.	The plants did not survive as per the proposal.	Rule 11(1),	Plantation work not done.

1. In this connection, it is brought to your kind notice that :- a) the above violations constitute an offence punishable under Rule 62 of MCDR 2017 and/or; 2. Mining operations can be suspended as per rule 11(2) of MCDR 2017 in case of non-compliance of above rules as these violations also affects provisions of Rule11(1) of MCDR 2017 and/or; 3. In case of violation of Rule 34(A), you are advised to rectify the above violations immediately and upload the data online on DDMS portal within 45 (Forty Five) days from the date of issue of this letter. 4. This letter is being issued with the approval of Regional Controller of Mines.

Yours faithfully,

(Sunil Kumar Sharma, GANDHINAGAR)
SR ACOM