

Show Cause Notice Letter

By e-mail

**भारत सरकार / GOVERNMENT OF INDIA
खान मंत्रालय / MINISTRY OF MINES
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES,
GANDHINAGAR**

File

Date : 10/04/2026

**No.: MCDR-MiFL0BXT/144/2022-GNR-
IBM_RO_GNR**

To: Shri/M/s. N/A,
Nominated Owner,
ALIMIYA, 16, SAMRUDHHI
COMPLEX ,NYAY
MANDIR, HIMATNAGAR,
Dedhrota Village & Mandal,
Sabar Kantha district,
Gujarat,- 383001

Subject : Violation of provision of Mineral Conservation and Development Riles, 2017
in respect of your 07GUJ14023(07GUJ14023) over an extent of 20 ha in Dedhrota in ,
Sabar Kantha, Gujarat

महोदय, आपकी उपरोक्त खान का रव्यू ऑफ माइनगि प्लान, एमसीडीआर तथा स्टार
रेटगि नरीक्षण स्नेहलकुमार पटेल, सहायक खनन अभियंता द्वारा दनांक 19-11-2025 को
श्री हरष त्रिविदी (क्यूपी), श्री सुखानंदी प्रतीक (भू-वज्जिजानी) एवं टीम की उपस्थिति में
किया गया तथा उक्त नरीक्षण के समय खनजि संरक्षण एवं वकिस नयिमावली, 2017 के
नमिन्लखिति नयिमों का उल्लंघन पाया गया-

Summary of Violations :

Items for Reporting	As Per Plan	Actual	Deviation	Rule	Reason	Status
Boundary Pillar	20 no of boundary pillar are proposed in mining plan.	During inspection no boundary pillar are found except 6 pillars.	14 boundary pillars are not found.	Rule 11(1),	Boundary pillars not maintained	Not Complied
Drone Data	Drone data submitted on 04-07-2025	The Submitted output/details of the drone survey were not found as per the SOP issued by under rule 34A(5). The Orthomosaic.tif is not a valid or recognised data source; all mining features have	Data not attached as per SOP.	Rule 34A(1),	Data not attached as per SOP.	Not Complied

		not been indicated in mining feature. shp file.				
The following mining operations were not carried out as per the Approved Review of Mining plan No MCDR-MPCP0 CaFI/34/2022-G NRIBMROG NR MP-467 dated 29-03-2023 :-	As per approved Mining Plan Mining operation shall be carried out leaving behind 7.5 m from lease boundary.	Excavation was found in the 7.5 m boundary zone and outside the lease area near Boundary pillars no. 1,2, 4,5,6,7, 9,10,11, 12, 15, 16,17,18, 19,20 and other places. Co-ordinates details are attached.	Excavation deviated from the approved proposal.	Rule 11(1),	Excavation deviated from the approved proposal.	Not Complied
Annual Return: Scrutiny of Annual return on sale value, Ex. Mine price & production cost	Sale value:Rs. 86519478.02/522630.270 tonn Ex.	Sale value: Rs.165.54/tonn	Sale value too low.	Rule 45(7),	Sale value too low.	Not Complied

	Mine price: Rs. 653.13/tonn Production cost: Rs. 465.94/tonn					
Environment: Plantation & Survival rate	Plantation : 200, Survival Rate : 60	About 50 plants were seen in the proposed area.	The plants did not survive as per the proposal.	Rule 11(1),	Plantation work not done.	Not Complied

2. On examination of office records, it is found that you have not submitted any reply, thus it has been considered that you do not intend to comply the above violated rule and the violation of such Rules of MCDR, 2017 still persists. 3. In this connection, it is brought to your kind notice that a. the above violations constitute an offence punishable under Rule 62 of MCDR 2017, and/or; b. Mining operations can be suspended as per rule 11(2) in case of noncompliance of rule 11(1) and any other relevant rules of MCDR 2017 as these rules ensures systematic scientific and responsible mining, and/or; 4. You are advised to rectify the above violations immediately and intimate the compliance position to this office within 30 days from date of issue of this letter. 5. You are therefore directed to show cause within a period of thirty (30) days from the date of issue of this letter, as to why you should not be prosecuted and / or why the mining operation should not be suspended under relevant statutory provisions and/or why not any other appropriate action can be initiated in accordance with rules and/or any competent orders/directives. 6. Please note that no further notice will be given to you in this regard. 7. This letter is being issued with the approval of Regional Controller of Mines.

Yours faithfully,

प्रतलिपि (मूल पर नही) -

१. खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर को सूचनार्थ प्रेषति।
२. आयुक्त, भू वज्जिज्ञान एवं खनन, गुजरात सरकार, पुराना सचवालय, ब्लॉक न.- 15, डा जीवराज मेहता भवन, सैक्टर- 10, गांधीनगर को सूचनार्थ प्रेषति।
३. रक्षति पत्रावली।

Esigned by: Sunil
Date: 17/04/2026 10:32:29 AM