

Show Cause Notice Letter

By e-mail

**भारत सरकार / GOVERNMENT OF INDIA
खान मंत्रालय / MINISTRY OF MINES
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES,
GANDHINAGAR**

File

Date : 23/04/2026

No.: MCDR-MiFL0FLSP/2/2022-GNR-IBM_RO_GNR

To: Shri/M/s. Mr Roopwant
Singh IAS, Nominated Owner,
GUJARAT MINERAL
DEVELOPMENT
CORPORATION LIMITED,
Khanij Bhavan, ,132 Ft Ring
Road, Gujarat University
ground,, Ahmedabad,
Ambadungar Village &
Mandal, Chhotaudepur
district, Gujarat,- 380052

Subject : खनजि संरक्षण एवं विकास नियम, 2017 के प्रावधानों का उल्लंघन — आपके अंबाडूंगर खनन क्षेत्र (24GUJ18002), क्षेत्रफल 63.2 हे., ग्राम अंबाडूंगर, जिला छोटोटाउदेपुर, गुजरात के संबंध में।

महोदय, उक्त खदान के स्टार रेटिंग प्रमाणीकरण के संबंध में दिनांक 03/02/2026 को हस्ताक्षरकर्ता अधिकारी द्वारा, खदान के प्रतिनिधि श्री नागेन्द्र सहि राठौड़ (माइन मैनेजर) की उपस्थिति में निरीक्षण किया गया तथा खनजि संरक्षण एवं विकास नियम, 2017 (MCDR, 2017) के अंतर्गत नीचे उल्लिखित नियमों के संबंध में पत्र संख्या MCDR-MiFL0FLSP/2/2022-GNR-IBM_RO_GNR दिनांक 09/04/2026 द्वारा MTS पोर्टल पर उल्लंघन पत्र जारी किया गया।

Summary of Violations :

Items for Reporting	As Per Plan	Actual	Deviation	Rule	Reason	Status
OB / Waste Dumps details: Stabilization Technique (Terracing, plantation, geo-textiles etc.)	Garland drain (420 meter) and Toe wall (420 meter) is proposed near Waste Dump 1 & 2	Not as per proposal	The garland drain and toe wall of 420 meter each to be prepared to stabilize the Dumps.	Rule 11(1),	Not as per proposals given in Approved Mine plan in FY 24-25	Not Complied
OB / Waste Dumps details: Separate dumping of topsoil, OB & mineral rejects, fines, tailings (Rule 36,37)	113021 cu.mt waste proposed	No waste generated as per Annual return	113021 cu.mt	Rule 11(1),	Not as per proposals given in Approved Mine plan in FY 24-25	Not Complied
Development - Opencast: Quantity of overburden generation in m3	113021.00	Nil	113021.000	Rule 11(1),	Not as per proposals given in Approved Mine plan in FY 24-25	Not Complied
Exploration: Number of Core Boreholes	As per mine plan 10 core bore holes are proposed	No exploration is done in the FY 24-25	10 holes need to be drilled	Rule 11(1),	Not as per proposals given in Approved Mine plan in FY 24-25	Not Complied

The reply submitted by you vide your letter dated 15/04/2026 has been examined and found unsatisfactory. 1)It is brought to your notice that the above violations constitute an offence punishable under Rule 62 of the Mineral Conservation and Development Rules, 2017 (MCDR, 2017). 2)Mining operations may be suspended under Rule 11(2) if compliance with Rule 11(1) is not found satisfactory. 3)You are hereby directed to show cause within 30 days from the date of issue of this letter as to why action should not be taken against you for the above violations. 4)No further notice will be issued in this regard. This letter is issued with the approval of the Regional Controller of Mines.

Yours faithfully,

(Mandha Gunasekhar Reddy, GANDHINAGAR)
Assistant Controller of Mines

प्रतिलिपिसूचनार्थ:- 1. खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर.
(zo.udaipur@ibm.gov.in)
2.आयुक्त, भूवर्ज्ञान एवं खनन वभिाग, ब्लॉक 15, डॉ० जविराज मेहता भवन, जूना
सचवालय, सेक्टर 10-बी,
गांधीनगर, गुजरात – 382010. (commissioner-cgm@gujarat.gov.in)
3. भूवैज्ञानिक (प्रभारी) भूवर्ज्ञान एवं खनन वभिाग एफ-1, प्रथम तल, कलेक्टर
कार्यालय मछोटा उदेपुर – पनः391165 दूरभाषः 0265-2423126 फैक्सः 0265-2420465 ई-
मेलः geologist-cho@gujarat.gov.in
4.एमसीडीआरफाइल 5.गार्डफाइल

Esigned by: Mandha
Date: 24/04/2026 12:04:25 PM