

MCDR Report	
Part-I: General Information	
1.1.1 Mine Details	
Name of the Mine:	Mokhana Limestone Mine
Lease Area (Ha):	58.68
Forest Area (Ha):	Nil
Mine Code:	38GUJ07012
Registration Number:	IBM/95/2011
Name of lessee:	M/s Shree Digvijay Cement Co. Limited
Address of lessee:	Digvijaygram, District: Jamnagar, State: Gujarat Pin code - 361140,
Phone of lessee:	0288-2344272-75
Email of lessee:	mines@digvijaycement.com
Fax Number:	Fax 0288-234
Village:	Mokhana
Taluka / Mandal:	Bhanvad
District:	Devbhumi Dwarka
Pin code:	360510
State:	Gujarat
Post Office:	Pachhtar
Nearest Police Station:	Bhanvad
Nearest Railway Station:	Bhanvad
Date of Grant of Mining Lease:	06.06.1983
Date of Mining Lease Execution:	07.11.1983
Date of opening in the mine:	01.03.1987
Nominated Owner Details	
Name of the Nominated Owner:	Shri Amit Arora
Address of Nominated Owner:	Shree Digvijay Cement Co. Ltd. Digvijaygram, Jamnagar
Nominated Owner Mobile:	7861880790
Nominated Owner Email:	mines@digvijaycement.com
Nominated Owner Fax Number:	0288 -2344092
Date of Nominated Owner Appointment:	17.06.2026
Mining Engineer Details	
Name of the Mining Engineer:	NA
Qualification of Mining Engineer:	
Address of Mining Engineer:	
Phone of Mining Engineer:	
Email of Mining Engineer:	
Fax Number of Mining Engineer:	
Date of Mining Engineer Appointment:	
Geologist Details	
Name of the Geologist:	NA
Qualification of Geologist:	
Address of Geologist:	
Phone of Geologist:	
Email of Geologist:	
Fax Number of Geologist:	
Date of Geologist Appointment:	
Mine Manager Details	
Name of the Mine Manager:	NA
Qualification of Mine Manager:	
Address of Mine Manger:	NA
Phone of Mine Manger:	
Email of Mine Manger:	

Fax Number of Mine Manger:	
Date of Mine Manger Appointment:	
Date of Approval of Mining Plan / Modified Mining Plan / ROMP with five-year period:	Vide letter no - 682(23)(311)/2004-UDP , Dtd. 24.06.2004
Mineral(s) granted in lease and proved for mining:	Limestone
Method of mining:	Opencast
Category:	Fully Mechanised
Nature of Use:	Captive

Part-II: Other Information

2.1.1: Inspection Details

Inspecting Officer	Shri Udit Dadhich
Designation	Assistant Mining Engineer
Name of the Accompanying Official from Mine	Shri Manish Kumar Upadhyay
Designation of the Accompanying Official	Agent & Head Mining
Type of Inspection	MCDR
Date of Inspection	12/06/2026
Review year considered for MCDR Inspection	2025-2026

2.2: Exploration Details

SN	Items for Reporting As Per Approved Mining Plan		Proposals	Actual work	Remarks
1	Number of Core Boreholes		No Proposals	Nil	Mining lease is non-operational since 07.08.2004 (22 Years)
2	Number of DTH Boreholes				
3	Number of exploratory pits / trial pits				
4	Number of exploratory Trenches				
5	Lateral exploration status for the lease area	G1	No Proposals	Nil	G1 = 58.68 Ha
		G2			
		G3			
		G4			
6	UNFC category wise reported Resources/Reserves as per MP/MMP/ROMP Total Reserves (111, 121 & 122) and Total Mineral Resources (331, 332 & 333 upto 334)		111	6.98 Million Tonne	Balance reserves as on 01.04.2004 (In Million Tons)

2.3.1: Development-Opencast

SN	Items for Reporting As Per Approved Mining Plan	Proposals	Actual work	Remarks
1	Location of development w.r.t. lease area	No Proposals	Nil	Nil
2	Quantity of overburden generation in m ³	Proposals		

3	Separate benches in topsoil, overburden and mineral (Rule 15)	No Proposals	Nil	
4	Quantity of topsoil generation in m ³			
5	Stripping ratio or ore to OB ratio			

2.4.1: Exploitation Opencast Mine Details

SN	Item Items for Reporting As Per Approved Mining Plan	Proposals	Actual work	Remarks
1	Number of pits/Blocks proposed for production	No Proposals	Nil	Mining lease is non - operational since 07.08.2004 (22 Years)
2	Quantity of ROM mineral production proposed(in T)			
3	Recovery of saleable/usable mineral from ROM production (in T)			
4	Quantity of mineral reject generation			
5	Grade of mineral reject generation and threshold value declared			
6	Quantity of sub-grade mineral generation			
7	Grade of sub-grade mineral generation			
8	Manual / Mechanised method adopted for segregating from ROM			
9	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM			
10	Any analysis or beneficiation study proposed & carried out for sub-grade mineral and reject			

2.4.3: Exploitation Dump working Details

SN	Item	Proposals	Actual work	Remarks
1	Number of dumps proposed for production	No Proposals	Nil	Nil
2	Quantity of dump material handling Proposed (in Tonne)			
3	Recovery of salable/usable mineral from dump production (in Tonne)			
4	Production from dump(s) during the year			
5	Quantity of mineral reject generation			
6	Grade of mineral reject generation and threshold value declared			
7	Any analysis or beneficiation study proposed & carried out for mineral reject	Nil		
8	Manual / Mechanized method adopted for dump working	N/A		

2.5: OB/Waste Dumps Details

SN	Item	Proposals	Actual work	Remarks
1	Separate dumping of topsoil, OB & mineral rejects, fines, tailings (Rule 36,37)	No Proposals	Nil	Nil
2	Location of Topsoil, OB/Waste, Mineral Reject dumps Tailings and Fines			

3	Number of active & Inative dumps			
4	Number of dead dumps			
5	Number of dumps proposed for stabilished			
6	Stabilization Technique (Terracing, plantation, geo-textiles etc.)			

2.6.1 Solid Waste Management - Backfilling (Opencast) Details

SN	Item	Proposals	Actual work	Remarks
1	Status on part or full extraction of mineral from mined out area before starting backfilling	No Proposals	Nil	Nil
2	Year-wise area under backfilling of mined out area			
3	Year-wise topsoil generation, Utilization and Stored proposal (in m3)			
4	Total area fully reclaimed & rehabilitated			
5	Locations of proposed reclamation & rehabilitated			

2.7: Progressive Mine Closure Plan (PMCP) Details

SN	Item	Proposals	Actual work	Remarks
1	Compliance on reclamation and rehabilitation by backfilling/Other means. Total area and numbers of plantation proposed.	No Proposals	Nil	Total No of Plants = 1970 Fencing = 400 M (Till 01.04.2004) DCF Porbandar has cannot granted the permission for carry out FMCP related work, vide letter no - K/JMN/Te.7/45/2026-27, Dtd.15.05.2026
2	Rehabilitation by making water reservoir			
3	Compliance of Rehabilitation of waste land within lease i) Afforestation ii) Area rehabilitated (ha) iii) Method of rehabilitation			
4	Compliance of Environmental monitoring (core zone & buffer zone)			

2.8: Mineral Conservation Details

SN	Item	Proposals	Actual work	Remarks
1	ROM Mineral dispatch or grade-wise sorting within lease area	No Proposals	Nil	Mining lease is non - operational since 07.08.2004 (22 Years)
2	Different grade of mineral sorted out at mines			
3	Any beneficiation process at mines			
4	Utilization of Mineral Rejects or			

	Subgrade (Blending at ROM stage, Blending after Processing etc.)			
--	--	--	--	--

2.9: Environment Details

SN	Item	Proposals	Actual work	Remarks
1	Separate removal and utilization of topsoil	No Proposals	Nil	Total No of Plants = 1970 Fencing = 400 M (Till 01.04.2004) DCF Porbandar has cannot granted the permission for carry out FMCP related work, vide letter no - K/JMN/Te.7/45/2026- 27, Dtd.15.05.2026
2	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use			
3	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)			
4	Plantation & Survival rate			
5	Water sprinkling on roads to control airborne dust			

2.10: Annual Return Details

S N	Item	Proposals	Actual work	Remarks
1	Submission of Online Monthly and Annual returns in prescribed period or not	No Proposals	Nil	Mining lease is non - operational since 07.08.2004 (22 Years)
2	Appointment of Mining Engineer & Geologist as per provisions of Rule 55 of MCDR,2017			
3	Whether incomplete or false or wrong returns submitted (Rule 45(7))			
4	Status of Approval of FMPCP u/r 24, 25 of MCDR,2017			
5	Notices and Returns for the lease area submitted or not where fine applicable			
6	Scrutiny of Annual return on sale value, Ex. Mine price & production cost			

2.11: 1. Details of violations observed during current inspection: Violation of Rule 21(4) and Rule 27(1) as there is no valid Mining plan and Bank Guarantee available with the office. Violation given on date 22.07.2026

2. compliance position of earlier violation pointed out: No Violation.

Vdix
04/08/2026.