



भारत सरकार / Govt of India
खान मंत्रालय / Ministry of Mines
भारतीय खान ब्यूरो / Indian Bureau of Mines
हैदराबाद क्षेत्रीय कार्यालय / Hyderabad Regional Office



Phone No. : (040)-27539992/2753993

Fax No.(TF): (040)-27539991

E-Mail : ro.hyderabad@ibm.gov.in

F. No. AP/KNL/MP/DOL-4/HYD

Room No.603, CGO Towers,

6th Floor, Kavadiguda,

Secunderabad-500 080.

Date: 01.04.2022.

To

Smt D Venkata Subbamma,
W/o D Krishna Reddy,
H.No 6-62,Subbareddy Colony
Chinna Malkapuram(Post) 518222,
Dhone Mandal
Kurnool District,AP

Sub: Submission of Review of Mining Plan in respect of Hanuman Dolomite and Iron ore Mine of Smt D Venkata Subbamma over an extent of 12.662 ha. in Valasala Village, Dhone Mandal, Kurnool District of AP State submitted under Rule 17(2) of MCR, 2016.

Ref: Your Email dated 25.03.2022.

Sir,

With reference to your letter cited above on the subject, the site inspection was carried out on 30.03.2022 by Sri. D.P.Ravi Kumar, AMG accompanied by Sri.M.Pratap Reddy, Qualified Person and Sri V.Balaram, Mines Manager. The draft Review of Mining Plan has been examined and the scrutiny comments have already been forwarded to you and your Qualified Person on respective e-mail id's i.e dvs2208@gmail.com and reddypratap1959@gmail.com as submitted in the document.

02. You are advised to attend these deficiencies as per the annexure and resubmit the document, complete in all respects, in three bound copies along with soft copy in the form of CD (4Nos.). In this regard, you are directed to submit the Financial Assurance in the form of Bank Guarantee for the area put on use for Mining and allied activities @ Rs.Five lakhs/hectare for category 'A' mines provided that the minimum amount shall be Rs.Ten lakhs as per the provision of Rule 27(1) of MCDR, 2017 at the time of submission of final copies of the document within 15 (fifteen) days from the date of issue of this letter, failing which the document will be disposed without giving any further opportunity.

03. The para-wise clarification & the manner in which the deficiencies are attended should be given while forwarding modified document.

Yours faithfully,

Shilendra Kumar
01/4/22

(Shailendra Kumar)

Regional Controller of Mines

Copy to:

Sri. M.Pratap Reddy, Qualified Person, Flat No. 404, House No: 3-3-66, Shikara Heights, Besides SVS Nuro Hospital, Kachiguda, Hyderabad – 500 027, TS., Qualified Person for information & necessary action.

Shilendra Kumar
01/4/22

(Shailendra Kumar)

Regional Controller of Mines

मूल पति पर नही

खान नियंत्रक (द), भारतीय खान ब्यूरो, बेंगलुरु।

Shilendra Kumar
01/4/22

(शैलेन्द्र कुमार)

क्षेत्रीय खान नियंत्रक

GENERAL:

On cover page :

- i) The Mine code, rule for progressive Mine closure Plan should be mentioned.
- ii) The IBM registration number, type of land, Qualified Person address with phone number and mail ID should be mentioned.

CHAPTER NO.1: GENERAL INFORMATION:

1. At para 1.1: The details of lease code, name of associated mineral and nature of use of the mineral are not mentioned. The same should be mentioned. Further, as per the GOMs No. 124 dated 28.05.2007, The Iron Ore and calcite minerals were also included as additional minerals in the lease deed, but Dolomite and Iron Ore minerals only mentioned. Please clarify it and also mention the calcite mineral name at all the required places in the document and plans and sections.
2. At para 1.1.1: The date of lease registration details are not mentioned. The same should be mentioned.
3. Para 1.2: The details regarding list of mining leases held by Shri D.Venkata Subbamma is already held / applied area should be indicated.
4. Para 1.3: The date of execution of the lease area is not matching with the details mentioned at para 1.1.1, so the correct details of lease execution dates should be furnished at all relevant places.
5. Para: 1.3.1: The details of approval of earlier mining plan & its subsequent review in chronological order are furnished, but at some places, the year of proposals for approvals of the documents are not mentioned correctly. The correct details should be mentioned at required places.
6. At para 1.3.7. Qualified Person Details as per M(OAHCEM)CR, 2016: A copy of PAN of Qualified Person shall be submitted as Annexure.
7. Instead of leaving blank any Column /Row, NA or any information may be given appropriately.

CHAPTER NO.2: GEOLOGY AND EXPLORATION

8. At para, 2.2.1.1: The details of Geological Mapping are not furnished properly (year and scale). The same should be furnished correctly. Further, the geological mapping of the mining lease area should be done in 1:2000 scale for the detailed exploration as specified in the MEMC Rule, 2015.
9. Para 2.2.1.5: It is mentioned that the number of pits are 30, but the details are furnished for 31 pits. During the inspection, it was observed that 30 nos. of pits were existed in the lease area. Accordingly, pit details may be furnished at all relevant places.
10. At para 2.2.1.7: Log sheets of boreholes shall be attached as annexure as mentioned in the draft review of Mining Plan. Further, the total meterage is furnished may be corrected.
11. At para 2.2.1.10: The details of radical with grade in % of Iron Ore mineral is not furnished and also not mentioned the annexure number for NABL chemical analysis report. The same may be attended.
12. At para 2.2.2.10: The details of chemical analysis are not furnished. The same should be furnished.
13. At para 2.2.2.14: Area Covered under Exploration: All the required information under this column to be furnished. Further, please mention the year i.e. 2022-23 instead of year 1, year 2 year etc.
14. At para 2.2.3. Chemical parameters for various radicals shall be submitted.

15. At para 2.2.4.2, 2.2.4.11 & 2.2.4.12 : The depth of the area is not mentioned at relevant column while calculating the resources and reserves respectively. The same needs to be furnished.
16. At para 2.2.4.11: The columns for total volume (m³) and total resource quantity for Iron ore and dolomite are missing in the table. The standard / prescribed table may be followed to fill the required information at relevant places in the table / text of the document.
17. At para 2.2.4.12: The columns for total volume (m³) and total reserves quantity for Iron Ore and dolomite are missing in the table. The standard / prescribed table may be followed to fill the required information at relevant places in the table / text of the document
18. The total reserves and resources furnished may be verified since the figures are not matching with the recent document which was approved on 29.07.2021. The same may be clarified and corrected at 2.2.4.13.

CHAPTER 4: MINING OPERATIONS

19. At para 4.2.1.2, the location of the existing dumps should be mentioned clearly.
20. At para 4.2.2.2: ROM quantity is not furnished The same should be furnished.
21. Para 4.2.2.3: details of all the transportation and hauling equipments should be given.
22. At para 4.3.3, the details pertains to proposed dump handling quantity (t), proposed recovery of saleable Mineral (t), proposed waste quantity (t), grade range (%) have not been furnished. The same may be furnished.
23. At para 4.3.4: All details under calculation summary is not furnished. The same should be furnished all required information.
24. During the inspection it was observed that at two places i.e. North East side & North West side, the workings have breached the 7.5m barrier zone relevant reclamation proposals to be incorporated.
25. During the inspection it was noticed that the dumps have extended to 7.5m barrier zone. Prepare re-handling proposals to be incorporated towards South East side of the lease area.
26. Suitable exploration proposals to be made in the production for upgrading the G3 area and to G1 level.
27. The quantity of the mineral lying in the stack yard to be furnished.
28. All the plans such as surface plan surface geological plan, conceptual plan etc to be submitted in the .KML or shape files with an attributes both existing & proposed.

CHAPTER 6: PROGRESSIVE MINE CLOSURE PLAN:

29. At para 6.2.3.1: The details of cumulative work done (upto end of previous block of five years) for green belt development are not furnished. The same should be furnished.

CHAPTER 9: IMPACT ASSESSMENT

30. At para 9.3.2.1: The table given for base / present status of the lease area, is not filled all the required columns / furnished. The same should be furnished properly in the table.

ANNEXURE

31. All the annexures must be numbered and enclosed serially.
32. Colour photographs should be enclosed as annexure for easy reference pertaining to Lease Boundary Pillars, Working Pits, Afforestation, Ground Control Points.

PLANS / PLATES AND SECTIONS

33. Highest and lowest RL of topography may be verified.
 34. Bore hole locations should be shown in Geological KML plan as a point feature.
 35. The relevant Plans and sections should be signed with date by certified surveyor, qualified person, mines manager, mining engineer, and Geologist as per provision of Rule 34 of MCDR 2017.
 36. Wind direction may be shown in wind rose diagram at the top right of the relevant plans. Further, colour code given for different features in plans and sections to be same.
 37. All the plans and section should be signed by the Lessee.
 38. The photo-identity card of lessee is not visible- good quality of Photo Id card should be enclosed.
-