

भारतसरकार/Government of India

खानमंत्रालय/Ministry of Mines

भारतीयखानब्यूरो/Indian Bureau of Mines

क्षेत्रीयखाननियंत्रककाकार्यालय/Office of the Regional Controller of Mines

File No:MAH/BHD/MN-42/NGP

Date: 08/09/2021

To,
M/s,MOIL. LTD, (A Government Undertaking).
MOIL Bhawan,-A-K, Katol Road,
Nagpur-440013.

Sub:- Sub:- Violation of provision of Mineral Conservation and Development Rule 2017 in respect of your Dongri Buzurg Manganese Mine for two leases an area of 46.5 Hectares situated near village Balapur Hamesha, Teh- Tumsar, District- Bhandara of Maharashtra State in connection with Mineral Conservation and Development Rules, 2017

Dear Sir,

The following provisions of Mineral Conservation and Development Rule, 2017 (MCDR, 2017). I the undersigned proposed to inspect your mine undersigned along with Shri Sachin Ramtekey and Miss Mrinal Tembhurne on **17-18/08/2021**. Provision of MCDR 2017 were found violated.

11(1). No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by State pursuant to the proviso to clause (b) of sub section (2) of section 5. The mining operation are not done /carried out as per approved mining plan BHD/MN/MPLN-621/NGP-2017dated 22/02/2018. To extend indicated below.

1(a).Overburden

S.L.No.	Year	Targat		Achievement
1	2020-2021	4183945 Cu.M	10459862 T	8457348 T
2	2019-2020	4494239 Cu.M	1235597 T	12527135 T
3	2018/2019	4172943 Cu.M	10432357 T	9007338 T
		Total	22127816 T	29991821 T
				Deviation + 36% more

(b).Ore

S.L.No.	Year	Targat in tonne	Achievement
1	2020-2021	500000 T	250678 T
2	2019-2020	500000 T	273641 T
3	2018/2019	487500 T	409049 T
	Total	1487500 T	933368 T
			Deviation -37% less

Thus it seen that overburden is + 36% more and in ore production there is deviation of -37% thus leading to not maintaining to ore to overburden ratio as envisaged in the AMP, thus leading to unsystematic development.

II).During inspection it is observed that dump mining was carried out change at 15-16.This was not proposed in the approved mining plan.

III).It was envisaged to form the bench of 10 M height and width not same was not found.

IV).The tailing of IMD plant is dumped on H/W side while was not proposed in the AMP.

03. In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under Rule 62 of MCDR, 2017.

04. The mining operations can be suspended under Rule 11(2), if compliance of MCD Rules 2017 is not found satisfactory, or prosecution can be made, or both can be done.

05. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (Forty five) days from the date of issue of this letter.

Yours faithfully,


8/9/21

R.R.Dongre

Regional Controller of Mines
NR Office ,Nagpur

o/c

Copy to.

1. The Controller of Mines (CZ), Indian Bureau of Mines, Nagpur.
2. The Director, Directorate of Geology & Mining, Government of Maharashtra, Khanij Bhwan, 27-Shivaji Nagar, Cement Road, Nagpur-440010 (MS).

Issued
Rve
09.09.21

o/c


8/9/21

(R. B. Dongre)

Regional Controller of Mines