

**INDIAN BUREAU OF MINES
MINERALS DEVELOPEMMENT AND REGULATION DIVISION**

MCDR INSPECTION REPORT

Nagpur regional office

Mine file No : MAH/CND/FE-10/NGP

Mine code : 30MSH08001

- (i) Name of the Inspecting : **219**) **Rajesh M Khadse**
Officer and ID No.
- (ii) Designation : Assistant Mining Engineer
- (iii) Accompanying mine : Shri M Bavai, mines manager
Official with
Designation
- (iv) Date of Inspection : 20-Sep-21
- (v) Prev.inspection date : 16-Nov-18

PART-I : GENERAL INFORMATION

1. (a) **Mine Name** : **GUNJEWAHI**
- (b) **Registration NO.** : **IBM/314/2011**
- (c) Category : B Manual
- (d) Type of Working : Opencast
- (e) Postal address
- State : MAHARASHTRA
- District : CHANDRAPUR
- Village : GUNJEWAHI
- Taluka : SINDEWAHI
- Post office : PATHRI
- Pin Code : 441215
- FAX No. : N.A.
- E-mail : N.A.
- Phone : (O)-640350,640540, (R)-529:
- (f) Police Station : PATRI
- (g) First opening date : 06-Jan-84
- (h) Weekly day of rest : FRI
2. Address for : HABIB NAGAR, TEKE,
correspondance NAGPUR-440017
3. (a) Lease Number : MSH0037
- (b) Lease area : 15.07
- (c) Period of lease : 50
- (d) Date of Expiry : 21-Mar-33
4. Mineral worked : IRON ORE Main

5. Name and Address of the

Lessee : M/s Gahra Minerals
 Habib Nagar , Teka, Nagpur
 Distt. Nagpur (MS) NAGPUR
 MAHARASHTRA
 Phone:
 FAX :

Owner : M/s Gahra Minerals
 Habib Nagar, Teka, Nagpur
 Distt. Nagpur (MS) NAGPUR
 MAHARASHTRA
 Phone:
 FAX :

Mining Engineer

Name : SHRI RAMAKANT SINGH, Full Time
 Qualification : B. E. MINING
 Appointment/ : 01-May-00
 Termination date

6. Date of approval of Mining	:	Renewal under rule 22 MCR1960	02-May-03
Plan/Scheme of Mining		Mining Scheme rule 12 MCDR1988	30-Oct-12
		MP modif under 17(3) MCR 2016	24-Mar-17
		MP review under 17(1) MCR 2016	21-May-18

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
1b	Exploration over lease area for geological axis 1 or 2	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
1c	Exploration Agencies and Expenditure in lakh rupees during the year	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
1d	Balance area to be explored to bring Geological axis in 1 or 2	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
1e	Balance reserve as on 01/04/20	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.

1f	General remarks of inspecting officers on geology, exploration etc	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
----	--	---	---	---

Development :

Sl.No.	Item	Propasals	Actual work	Remarks
2a	Location of development w.r.t.lease area	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
2b	Separate benches in topsoil, overburden and minerals (Rule 15)	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
2c	Stripping ratio or ore to OB ratio	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
2d	Quantity of topsoil generation in m3	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
2e	Quantity of overburden generation in m3	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.

2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
----	---	---	---	---

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
3b	Quantity of ROM mineral production proposed	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
3c	Recovery of sailable/usable mineral from ROM production	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
3d	Quantity of mineral reject generation	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
3e	Grade of mineral rejects generation and threshold value declared.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.

3f	Quantity of sub grade mineral generation.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
3g	Grade of sub grade mineral generation	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
3h	Manual / Mechanised method adopted for segregating from ROM	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
3j	Provision of drilling and blasting in mineral benches	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
3k	Provision of mining machineries in mineral benches	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
3l	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.

3m	Total area covered under excavation/pits	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
3n	Ore to OB ratio for the pit/mine during the year.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
3o	Total area put in use under different heads at the end of year	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
3p	Production of ROM mineral during the last five year period as applicable	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
3q	General remarks of inspecting officers on method of mining etc.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.

Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.

4b	Location of topsoil, OB and mineral reject dumps	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
4c	Number of dumps within lease area and outside of lease area	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
4e	Number of active and alive dumps.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
4f	Number of dead dumps.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
4g	Number of dumps established.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
4h	Whether Retaining wall or garland drain all along dumps are there.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.

4i	Length of Retaining wall or garland drain all along dumps	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
4j	Number of settling ponds	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
4k	Specific comments of inspecting officer on waste dump management	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
5b	Area under backfilling of mined out area	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.

5d	Total area fully reclaimed and rehabilitated	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
5e	General remarks of inspecting officers on backfilling and reclamation etc.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.

Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
6a	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
6b	Area available for rehabilitation (ha) .	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
6c	afforestation done (ha).	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
6d	No. of saplings planted during the year	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.

6e	Cumulative no .of plants	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
6f	Any other method of rehabilitation	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
6g	Cost incurred on watch and care during the year	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (Lx B x D	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
6j	Compliance on reclamation and rehabilitation by backfilling (iii)Afforestation on on backfilled area	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.

6l	Compliance on reclamation and rehabilitation by backfilling (v) any other specific means.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
6m	Compliance of rehabilitation of waste land within lease (i) afforestation	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
6n	Compliance of rehabilitation of waste land within lease (ii) Area rehabilitation (ha)	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
6o	Compliance of rehabilitation of waste land within lease (iii) Method of rehabilitation	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
6p	Compliance of environmental monitoring (core zone and buffer zone)	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
6q	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.

Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
--------	------	-----------	-------------	---------

7a	ROM Mineral dispatch or grade-wise sorting within lease area	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
7b	Method of grade-wise mineral sorting i.e. manual or mechanical.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
7c	Different grade of mineral sorted out at mines.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
7d	Any beneficiation process at mines .	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.

Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.

8b	Concurrent use or storage of topsoil	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
8g	Survival rate	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.

8h	Water sprinkling on roads to control airborne dust	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
9d	Scrutiny of Annual return on afforestation	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.

9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
9f	Scrutiny of Annual return on ROM stock and/or graded ore	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
9h	Scrutiny of Annual return on fixed assets	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.
9k	Scrutiny of Annual return on mining machineries	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.	Mining operation were discontinued & mine pit was filled with rain water mine is not working.

Details of violations observed during current inspection and compliance position of violation pointed out

Violation observed		Show cause position	
Rule NO.	Issued on Compliance on	Rule NO.	Issued on Compliance on

Date :

(Rajesh M Khadse)

Indian Bureau of Mines