



भारत सरकार
GOVERNMENT OF INDIA
खान मंत्रालय
MINISTRY OF MINES
भारतीय खान ब्यूरो
INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय
OFFICE OF REGIONAL CONTROLLER OF MINES



दूरभाष: (080) 39505368 / 29720499
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर,
बेंगलुरु -560022

सं/No.KNT/BLR/FE/492/BNG Mine-code:30KAR03183 दिनांक/Dated: 04/07/2022

To,
Shri Sunil Kumar Singh,
Agent & Vice President (Mines)
M/s. JSW Steel Limited
Devadari Iron ore Mines
JSW Mining Office, Near Talur Cross
Vidyanagar (Post), Toranagallu, Sandur taluk
Bellary District, Karnataka-583275
Email id-sunil.singh@jsw.in, sharma.nishant@jsw.in

विषय/Subject: **Violation of provisions of MCDR 2017 read with MCDR(Amendment),2021 in respect of your Devadari Iron ore Mine, ML 006 of M/s. JSW Steel Ltd. over an extent of 100.54ha, in Lakshmipura Village, Sandur Taluk, Bellary District of Karnataka State.**

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 read with Mineral Conservation and Development (Amendment) Rules, 2021 were found violated in your above mine during inspection on 15.06.2022 by undersigned in presence of Shri Nishant Kumar Sharma, Mine Manager, Shri BP Umapati, Mining Engineer, Shri Vivek G, Geologist and other mining officials:

| Rules | Nature of Violations observed |
|--------|--|
| 11 (1) | Modification to the approved Mining Plan was approved by IBM vide letter no. 279/1091/2017/BNG dated 21/10/2020, for the period 2020-21 to 2022-23. The deviations observed in mining operation vis-à-vis approved document are given below. i) It was observed during site inspection that development of upper benches i.e. 930, 922 & 914 mRL as proposed between Section S6-6' to S-8-8' (N-1666008 E-669597 to N-1666200 E-669579) at Southern side were not advanced as per the proposal. |

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR (Amendment), 2021
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty-Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(Sandeep Kumar Singh)

Assistant Controller of Mines
Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sd/-

(Sandeep Kumar Singh)

Assistant Controller of Mines
Indian Bureau of Mines