



भारत सरकार
GOVERNMENT OF INDIA
खान मंत्रालय
MINISTRY OF MINES
भारतीय खान ब्यूरो
INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय
OFFICE OF REGIONAL CONTROLLER OF MINES



दूरभाष: (080) 39505368 / 29720499
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर,
बेंगलुरु -560022

सं/No.**KNT/BLR/FE/498/BNG** Mine-code:30KAR03190 दिनांक/Dated: 04/07/2022

To,
Dr. Meda Venkataiah,
Nominated Owner and Whole time Director,
Jaisingpur Iron Ore Mine
M/s. MSPL Ltd.
Baldota Enclave, Abheraj Baldota Road,
Hosapete, Ballari-583203
Karnataka
Email id-meda.venkataiah@mspllimited.com,madhusudhan.k@kmspllimited.com
sandeep.m@mspllimited.com

विषय/Subject: **Violation of provisions of MCDR 2017 read with MCDR(Amendment),2021 in respect of your Jaisingpur iron ore Mine, ML 0015 of M/s. MSPL Ltd over an extent of 56 ha, in Jaisingpur Village, Sandur Taluk, Ballari District of Karnataka State.**

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 read with Mineral Conservation and Development (Amendment) Rules, 2021 were found violated in your above mine during inspection on 14.06.2022 by undersigned in presence of Shri Sandeep R Manakeshwar, Mine Manager, Shri Dhruva Kumar B.Y., Geologist, Shri Prashant Gali, Mining Engineer and other mining officials:

Rules	Nature of Violations observed
11 (1)	Mining Plan was approved by IBM vide letter no. 279/1106/2020/BNG dated 28/07/2020, for the period 2020-21 to 2024-25. The deviations observed in mining operation vis-à-vis approved document are given below. i) It is proposed that mine development for the year 2021-22 will be carried out between Sec A-A' to E-E', 3 Nos. of benches with top 900 mRL and bottom 870 mRL. It is found during inspection that at certain section likes D-D', the benches have been developed beyond the proposed vertical limit of 870 mRL i.e. till 853 mRL.

	ii) It was observed during site inspection that waste dumping at South western portion of the waste dump AD-1 between Sec C-C' & D-D' is carried out beyond the proposed extent. Also, at the Northern portion of the dump AD-1(N-1679400, E-658000), waste dumping has been carried out beyond the proposed extent. The waste dumping has not been carried out as per the proposal.
--	--

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR (Amendment), 2021

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty-Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(Sandeep Kumar Singh)

Assistant Controller of Mines

Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sd/-

(Sandeep Kumar Singh)

Assistant Controller of Mines

Indian Bureau of Mines