



भारत सरकार/ GOVERNMENT OF INDIA  
खान मंत्रालय/ MINISTRY OF MINES  
भारतीय खान ब्यूरो/ INDIAN BUREAU OF MINES  
क्षेत्रीय खान नियंत्रक कार्यालय/  
OFFICE OF REGIONAL CONTROLLER OF MINES



फैक्स: (080) 23371027 / 23373287

दूरभाष: 080-23371027 / 23375366/67

Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब II स्टेज, तुमकुर रोड,

गोरगुंटापाल्या येशवंतपुर,

बेंगलुरु -560022

सं/No.:KNT/BLR/FE/52/BNG/VOL-VII

दिनांक/Date: 01/06/2022

सेवार्में/ To,

M/s.P BalasubbaSetty& Son,  
D. No: 2078, P. B. No-03, 22<sup>nd</sup> ward,  
J. P. Nagar, Bellary Road, Hosapete,  
Bellary, Karnataka- 583201.

**विषय/Sub:** Violation of provisions of MCDR, 2017 in respect of your Karadikolla(Suresh) Iron Ore mine, ML No. 2502, over an extent of 42.10 Ha. situated near Karadikolla Village, Sandur Taluk, Ballari District, Karnataka State.

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection on 09/05/2022 by the undersigned alongwith Shri. Gangadhar Bhakat, Assistant Mining Engineer accompanied by Sri Y. V Rama Krishna Reddy, Mines Manager and othermine officials.

Rule No.	Violations observed
11(1)	Modification to the Approved Review & Updation of Mining Plan was approved vide letter no. 279/125/89/BNG dated 02/08/2021. The deviations observed in mining operations vis-à-vis approved document are given below. <ul style="list-style-type: none"> <li>(i) As per the proposal for the year 2021-22 the lessee has to be constructed retaining wall 1000m &amp; garland drain of 1010m. However, it is observed during the inspection that only 660m of retaining wall &amp; 660m of garland drain has been constructed till the date of inspection.</li> <li>(ii) As per the proposal for the year 2021-22 the bench geometry to be maintained 8m of bench height &amp; 10m of bench width. However, it was observed during the inspection the benches of pit 1 at the section lines D-D' &amp; E-E' are not maintained as per the proposal.</li> </ul>

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.

03. You are advised to rectify/explain the valid reasons for the above violation immediately and intimate the position to this office within 45 (fortyfive) days from the date of issue of this letter.

भवदीय

/Yours faithfully,

Sd/-

(सुरेश प्रसाद /Suresh Prasad)

क्षेत्रीयखाननियंत्रक/Regional Controller of Mines  
भारतीयखानब्यूरो/Indian Bureau of Mines

सं/No.: KNT/BLR/FE/52/BNG/VOL-VII

प्रतिलिपि सूचनार्थ Copy for kind information to:

1. The Controller of Mines (SZ), IBM, Bangalore, for kind information.
2. The Director, Dept. Of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560 001.

Sd/-

(सुरेश प्रसाद /Suresh Prasad)

क्षेत्रीयखाननियंत्रक/Regional Controller of Mines

भारतीयखानब्यूरो/Indian Bureau of Mines