



भारत सरकार
GOVERNMENT OF INDIA
खान मंत्रालय
MINISTRY OF MINES
भारतीय खान ब्यूरो
INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय



OFFICE OF REGIONAL CONTROLLER OF MINES

दूरभाष: (080) 39505368 / 29720499
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर,
बेंगलुरु -560022

सं/No.: KRL/PAL/Lst-1/BNG

Mine-code: 38KRL08001

दिनांक/Dated: 11/07/2022

To,
Sri M. Mohamed Ali,
Managing Director ,
M/s Malabar cements Ltd
Walayar- 678 624
Palakkad Taluk & District, Kerala State.
E-mail id- ro@malabarcements.com, jtkmcl@yahoo.com

विषय/Subject: Violation of provisions of MCDR 2017 in respect of your Pandarathu Limestone Mine, over an extent of 234.9407 Ha situated in Pudussery & Malampuzha I Village, Palakkad Taluk and District of Kerala State.

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 17.06.2022 by the undersigned in the presence of Shri Venkatachalam, Mines Manager, Shri Sony Kuriakose, Mining Engineer, Shri Mohana Chanadran, Geologist and others.

Rules	Nature of Violations observed
11 (1)	<p>The approved Review and updation of Mining plan was approved by IBM vide letter no. 279/464/95/BNG dated 03/02/2021 for the period 2021-22 to 2025-26. The deviations observed in mining operation vis-à-vis approved document are given below:</p> <p>i) It was observed during site inspection that exploratory drilling of 5 core boreholes with 200m meterage has been proposed during the year 2021-22. The same has not been carried out.</p> <p>ii) It was observed during site inspection that against the proposed production of 5,99,998 tonnes, the actual production is reported as 3,99,019 tonnes during the year 2021-22. The deviation is 34% less production.</p> <p>iii) It was observed during the inspection that the waste of 79,776 tonnes has been generated against the proposed waste of 2,89,969 tonnes during the year 2021-22. There is a lagging of development with deviation of 72%.</p> <p>iv) It was observed during the inspection that during the year 2021-22, the construction of 200m length of retaining wall and 200m of Garland drain has been proposed. The same has not been carried out.</p>

46	As per the rule, every holder of mining lease shall send a notice of appointment of Mine Manager after the appointment or when the employment of any such person is terminated or any such person leaves the said employment; or when any change occurs in the address of any such person, within fifteen days from the date of such appointment, termination, leaving or change in address, give a notice in Form H of the Schedule. But, no such notice has been sent to this office, though the appointment of Mine Manager has been taken place on 01.06.2022.
-----------	--

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty-Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-
(K.Srinivas)
Junior Mining Geologist
Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, Kesavadasapuram, Pattom Palace (P.O), Thiruvananthapuram- 695 004 .

Sd/-
(K.Srinivas)
Junior Mining Geologist
Indian Bureau of Mines