

Regd. A/D / Speed Post

GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
OFFICE OF THE REGIONAL CONTROLLER OF MINES

No. TN/TNL/LST-4-MDS Vol. VIII

C-4-A, Rajaji Bhavan
CGO, Complex, Besant Nagar
Chennai -600 090.

Dated: 4/03/2014

To:
Sri R.K. Das
Director & Nominated Owner
M/s. India Cements Limited
Coromandal Towers
93 Santhome High Road, R.A. Puram
Chennai – 600 028.

Sub: Violation of provisions of Mineral Conservation and Development Rules, 1988, in respect of your Sethurayanpudur Limestone Mine over an area of 29.9 hectares (GO No. 762) in Sethurayanpudur Village, Tirunelveli District, Tamil Nadu State.

Sir,

The following provision of the Mineral Conservation and Development rules, 1988 were found violated in your above mine during the inspection on 24/02/2014 by the undersigned.

Rule No.	Nature of violations observed
27(4)	The surface plan has not been updated. It does not show any dump which are present within the mining leasehold. No boundary pillar has been marked on the southern side of the lease area.
28(5)(b)	The environment plan as required under this rule showing all the details including the land use upto 500 m. of the lease area has not been shown and maintained.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 58 of MCDR, 1988.

03. You are, therefore, advised to rectify the above said violations immediately and intimate the position to this office within a period of 45(forty-five) days from the date of issue of this letter.

Yours faithfully,

(T.K. RATH)
Regional Controller of Mines

Copy forwarded to:

- 1) The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore, for kind information.
- 2) The Commissioner of Geology & Mining, Department of Geology & Mining, Government of Tamilnadu, Guindy, Chennai – 600 032.

(T.K. RATH)
Regional Controller of Mines

