



**GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
OFFICE OF THE REGIONAL CONTROLLER OF MINES**



Tel No.080 23371027
Fax No.080 23373287
Email ID: ro.bangalore@ibm.gov.in, rcombng@rediffmail.com

29, Industrial Suburb, IInd Stage
Tumkur Road, Goruguntapalya
Yeshwantpur, Bangalore-560022

No. KNT/GLB/Lst-17 (Vol-3)/BNG/2015/

Dated: 04/12/2015

Shri KC Jain,
Nominated Owner,
Vasavadatta Cement,
M/s Kesoram Industries Ltd;
Crystal Tower, 10-3-316/2,
2nd/3rdFloor, Above Andhra Bank
Masab Tank, **Hyderabad**-500 028

Fax : 040-43344534

Subject:- Violation of provisions of MCDR 1988 in respect of your Injepalli Limestone Mine (ML No. 2475) over an extent of 897.86 hectares in Sedam taluk of Kalburgi District.....reg.

Dear Sir,

The following provisions of the Mineral Conservation & Development Rules 1988 were found violated in above mine during the inspection conducted by the undersigned in presence of Shri Rajesh Garg, AVP (Mines) & Agent on dated 25.11.2015.

Rule 13(1)	The Scheme of Mining was approved vide letter No. KNT/BLR/MS/Lst-180-SZ/027 dated 01.01.2013. The deviations observed in mining operations vis-a-vis approved document are given below:- (i) Production of limestone for last five years is consistently (including 2015-16) in the range of 40 to 50% of the proposals. (ii) Despite the lesser production, the development of benches & limestone excavation are not adhered to the proposed area for 2015-16. (iii) The environment data's are not being maintained in a bound paged register.
Rule 48	The particulars of boreholes drilled are not being maintained in a bound paged register as per form-K, as required under the rule.
Rule 59	The core samples of recent exploration have not been found preserved properly. A core library is to be maintained in core boxes in serial order with identification marks and other details to preserve the cores systematically.

- In this connection, it is to bring to your notice that the above violations constitute an offence punishable under Rule 58 of MCDR 1988. Further, the violation of Rule 13(1) of MCDR may also attract provision of Rule 13(2) of MCDR 1988 regarding suspension of mining operations till the compliance of the violations.
- You are advised to rectify the above violation immediately and intimate the position to this office within 45 (forty five) days from the date of issue of this letter.

Yours faithfully,

Sd/-
(**Pukhraj Nenival**)
Dy. Controller of Mines

Copy for kind information to:

- The Controller of Mines (SZ), IBM, Bangalore.
- The Director, Dept. of Mines & Geology, Govt. of Karnataka, Khanij Bhavan, Race Course Road, Bangalore 560 001.

Sd/-
(**Pukhraj Nenival**)