



Government of India
Ministry of Mines
Indian Bureau of Mines
Office of the Regional Controller of Mines, Jabalpur

VOILATION LETTER
Registered AD/Speed post

File No.MP/Sidhi/Lst-07

Mine Code: 38MPR41006

Date: 24/06/2019

To,
Shri Kailash Chand Jhanwar
Dy. Managing Director & Chief Manufacturing Officer
Ahire Centre
A Wing, 1st Floor
Mahakali Caves Road, Andheri (E)
Mumbai 400093, Maharashtra

Subject: Violation of provisions of Mineral Conservation and Development Rules, 2017, in respect to Majhgawan Extension Limestone Mine over an extent of 54.825 hect. in Sidhi District of M.P.

Sir,

Undersigned has inspected your mine in the presence of Mines officials and QP Shri R Purohit on 28/05/2019. Following provisions of MCDR 2017 were found violated in your mines at the time of inspection.

Rule No	Nature of violation observed in detail
---------	--

Rule 11(1) No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government.

The Modification in approved Mining Plan of above mentioned mine was approved vide letter No. MP/Sidhi/Limestone/MPLN/MOD-13/2016-17 dated 30/09/2016 incorporating proposals from year 2016-17 to 2020-21. During the inspection it was observed that mining operations in the mine was not carried out in accordance with the proposals given in the approved Review of Mining Plan. The extents of deviation observed during inspection are as under:

- a) In approved Modi Mining Plan in page no 11, it was proposed to drill 2 nos of core boreholes in year 2017-18 at the grid interval of 100X100. During the inspection it was observed that above mentioned proposal was not completed till the date of inspection which is 28/05/2019.
- b) It was proposed to maintained bench height of 8 meters in limestone, at the time of inspection it was observed that some places height of benches are not maintained as per proposal and irregular width of benches were observed.

-
2. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.
 3. The mining operations can be suspended under the rule 11(2) of MCDR-2017, if compliance of rule 11(1) of MCDR-2017 is not found satisfactory.
 4. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

Yours faithfully,

DEEPAK SHARMA
Senior Mining Geologist
Indian Bureau of Mines

Copy forwarded for information to:

- 1) The Controller of Mines (CZ), Indian Bureau of Mines, Nagpur.
- 2) The Director, Directorate of Geology and Mining, Khanij Bhawan 29-A Arera Hills Bhopal M.P.

DEEPAK SHARMA
Senior Mining Geologist
Indian Bureau of Mines