

e-mail/post



GOVERNMENT OF INDIA  
MINISTRY OF MINES  
INDIAN BUREAU OF MINES  
NAGPUR REGIONAL OFFICE



[www.ibm.gov.in](http://www.ibm.gov.in)

Tele Fax :-2565089

Mail: [rcom.nr@ibm.gov.in](mailto:rcom.nr@ibm.gov.in)

File No.MAH/NAG/Mn-137/NGP

Mine Code:-40MSH14053. 321

To: Shri Manoj Kumar Singh, Agent

M/s MOIL Limited,

IA-MOIL Bhavan, Katol Road,

Nagpur- 440013.

**Sub:** - Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Parsoda Mine, over an extent of 53.75. Situated in Parsoda-village, Teh-Ramtek, and Nagpur District of Maharashtra State.

6th Floor,'B & C'Block,  
Indira Bhavan, Civil Lines,  
NAGPUR-440 102.  
Date:12.11.2021

Sir,

The following provision of Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection on 17/09/2021(A/N), by Shri Kalmata. M.K, Regional Mining Geologist, in presence of Shri . SHRI D MOHANTA., Geologist.

Rule	Nature of Violation observed
11(1)	<p>No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5 or approved by the competent authority of the Atomic Minerals Directorate for Exploration and Research, in respect of minerals specified in Part B of the First Schedule to the Act where the grade of such atomic minerals is equal to or above the threshold value limits declared under Schedule-A of the Atomic Minerals Concession Rules, 2016.</p> <p>a) In the approved Review of Mining plan dated 01.03.2021; proposal was given to work between the co-ordinates N 12610 to N 12960 &amp; E 17050 to E 17290. In the year 2021-22, but working has been carried out b/w the co-ordinates N 12810 to N 12880 &amp; E 16940 to E 17010. Further, the pit location given in plans not matching with the field.</p> <p>b) In the approved Review of Mining plan dated 01.03.2021; there was a proposal to dump Waste between the co-ordinates, N13080 to N13160 &amp; E 16810 to E16910. And topsoil between the co-ordinates, N12956 to N13046 &amp; E16740 to E 16830, But waste dumping was made between co-ordinates N-12900 to N 12980 &amp; E 16840 to E 16900 and topsoil dumping was made between the co-ordinates N12910 to N 12955 &amp; E</p>

	<p><b>16835 to E 16890.</b></p> <p>If the mining operations are not carried out in accordance with the approved or certified mining plan or any information contained in the mining plan is found to be incorrect, misleading or non-compliant with applicable laws including these rules, the competent authority may by order, suspend all or any of the mining operations and permit continuance of only such operations as are required to restore the conditions in the mine as envisaged under the approved or certified mining plan or modified mining plan, for the purpose of restoration to the extent possible.</p>
45 (7)	<p>Following deficiencies were observed in the annual returns submitted for the year 2020-21.</p> <p>a) As per the data furnished in the star rating template about 34662 tones of OB is removed in the year 2020-21, but in the annual returns submitted for the year 2020-21, overburden removed is shown as 1769 tones only.</p> <p>b) In the annual returns submitted for the year 2019-20, Closing balance under Industrial was shown as <b>zero</b> and for plant and Machinery closing balance was shown as Rs, <b>8,72,441</b>, however in the annual returns submitted for the year 2020-21, Opening balance for Industrial is shown as Rs <b>5,74,800</b> and Under plant and machinery opening balance is shown as Rs <b>75,23,174</b>. And depreciation was shown Rs-305299 for Industrial and 242642 under Plant and machinery.</p> <p>c) At part VI (1) production of ROM from open cast working is shown as 24139T and closing stock for ROM was shown as Zero, but under grade wise production only 22,370 tones production is shown and nothing is shown for remaining 1769T. Generation of mineral reject is also shown as zero.</p>
55(c)(i)	<p>In category 'A' mines, a whole-time mining engineer and a geologist should be appointed. But Mr. <b>U BOTHRA</b>, who has shown as mining engineer for parsoda mine is also shown as mining engineer for Munsar mine and same cannot be considered.</p>

02. In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under Rule 62 of MCDR, 2017.

03. The mining operations can be suspended under Rule 11(2), if compliance of MCD Rules 2017 is not found satisfactory, or prosecution can be made, or both can be done.

04. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (Fourty five) days from the date of issue of this letter.

Yours faithfully,

  
12/11/21

(R.R. Dongre)

Regional Controller of Mines,  
Indian Bureau of Mines.


o/c

Copy forwarded to: -

1. The Controller of Mines, CZ, Indian Bureau of Mines, Nagpur.
2. The Director, Directorate of Geology & Mining, Govt. of Maharashtra, Khanij Bhavan, plot No-27, Shivaji Nagar, Cement Road, Nagpur-440010.

Issued  
R/R  
15.11.2024

o/c

  
(R.R. Dongre) 12/11/24  
Regional Controller of Mines,  
Indian Bureau of Mines.