

**INDIAN BUREAU OF MINES
MINERALS DEVELOPEMMENT AND REGULATION DIVISION**

MCDR INSPECTION REPORT

Dehradun regional office

Mine file No : HP/SRM/LST-40

Mine code : 38HPR10040

- (i) Name of the Inspecting : **002**) **DAMODAR PRASAD SHARMA**
Officer and ID No.
- (ii) Designation : Assistant Controller Mine
- (iii) Accompanying mine : Mr. Prakash Sharma, Representative of Owner
Official with
Designation
- (iv) Date of Inspection : 29-MAR-24
- (v) Prev.inspection date : 13-JUN-22

PART-I : GENERAL INFORMATION

1. (a) **Mine Name** : **BHIMGODA**
- (b) **Registration NO.** : **IBM/7423/2011**
- (c) Category : A Other than Fully Mech.
- (d) Type of Working : Opencast
- (e) Postal address
State : HIMACHAL PRADESH
District : SIRMUR
Village : BAGADHAR
Taluka : PAONTA SAHIB
Post office : SATAUN
Pin Code :
FAX No. : N.A
E-mail : k.n.cement@gmail.com
Phone : (01704) 262483
- (f) Police Station : PAONTA SAHIB
- (g) First opening date : 14-NOV-89
- (h) Weekly day of rest : SUN
2. Address for : M/S K.N. CEMENTS LTD.
correspondance : VPO - SATAUN
TEHSHIL - PAONTA SAHIB, DISTT- SATAUN (HP)
3. (a) Lease Number : HPR0022
(b) Lease area : 24.6
(c) Period of lease : 50
(d) Date of Expiry : 13-MAR-27
4. Mineral worked : LIMESTONE Main

5. Name and Address of the

Lessee : K.N.CEMENTS LTD.
 C/o Sh. NASILA KHAN V.P.O.
 SATAUN TEHSIL PONTA SAHIB
 SIRMUR HIMACHAL PRADESH
 Phone:(01704) 62483
 FAX :

Owner : K.N.CEMENTS LTD.
 VILL. SATAU P.O. SATAU
 DISTT. SIRMUR SIRMUR
 HIMACHAL PRADESH
 Phone: 62483
 FAX :

Agent : NASHEEM KHAN
 KHAN MINING TRG CO. VPO -
 SATAUN TEHSHIL - PAONTA
 SAHIB SIRMUR HIMACHAL
 PRADESH
 Phone:
 FAX :

6. Date of approval of Mining	:	Existing rule 11 MCDR1988	03-MAR-92
Plan/Scheme of Mining		Mining Scheme rule 12 MCDR1988	22-DEC-99
		Renewal under rule 22 MCR1960	28-MAR-07
		Mining Scheme rule 12 MCDR1988	21-SEP-12

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	no proposal was given	Not Applicable	Inspection was carried out for the submitted draft RMP, mine is closed since 2012 no valid document was available for teh reporting year 2023-24.
1b	Exploration over lease area for geological axis 1 or 2	ML area is explored upto G2 level	as per previous approved mining plan ML area was eplored upto G2 level	
1c	Exploration Agencies and Expenditure in lakh rupees during the year	Not Mentioned	Not Applicable	
1d	Balance area to be explored to bring Geological axis in 1 or 2	No exploration details provided	Mine is closed as per office records and as per previous approved mining plan ML area needs to be explored upto G1 level	
1e	Balance reserve as on 01/04/20	no proposal	as per approved mining plan dated 21.09.2012 121-10067175 Tonnes 122-1485000 Tonnes	

1f	General remarks of inspecting officers on geology, exploration etc	Mining lease is closed since 2012, no mining activity is seen in the ML area at the time of inspection. last approved mining plan was 21.09.2012. mine was inspected for submitted draft RMP.	Mining lease is closed since 2012, no mining activity is seen in the ML area at the time of inspection. last approved mining plan was 21.09.2012. mine was inspected for submitted draft RMP .
----	--	---	--

Development :

Sl.No.	Item	Propasals	Actual work	Remarks
2a	Location of development w.r.t.lease area	No proposal was given	Not Applicable	
2b	Separate benches in topsoil, overburden and minerals (Rule 15)	No proposal was given	Not Applicable	
2c	Stripping ratio or ore to OB ratio	No proposal was given	Not Applicable	
2d	Quantity of topsoil generation in m3	No proposal was given	Not Applicable	
2e	Quantity of overburden generation in m3	No proposal was given	Not Applicable	

2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc	Mining lease is closed since 2012, no mining activity is seen in the ML area at the time of inspection. last approved mining plan was 21.09.2012. mine was inspected for submitted draft RMP.	Mining lease is closed since 2012, no mining activity is seen in the ML area at the time of inspection. last approved mining plan was 21.09.2012. mine was inspected for submitted draft RMP.
----	---	---	---

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	No Proposal was given	Not Applicable	
3b	Quantity of ROM mineral production proposed	No Proposal was given	Not Applicable	
3c	Recovery of sailable/usable mineral from ROM production	No Proposal was given	Not Applicable	
3d	Quantity of mineral reject generation	No Proposal was given	Not Applicable	
3e	Grade of mineral rejects generation and threshold value declared.	No Proposal was given	Not Applicable	
3f	Quantity of sub grade mineral generation.	No Proposal was given	Not Applicable	
3g	Grade of sub grade mineral generation	No Proposal was given	Not Applicable	

3h	Manual / Mechanised method adopted for segregating from ROM	No Proposal was given	Not Applicable
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	No Proposal was given	Not Applicable
3j	Provision of drilling and blasting in mineral benches	No Proposal was given	Not Applicable
3k	Provision of mining machineries in mineral benches	No Proposal was given	Not Applicable
3l	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	No Proposal was given	Not Applicable
3m	Total area covered under excavation/pits	No Proposal was given	Not Applicable
3n	Ore to OB ratio for the pit/mine during the year.	No Proposal was given	Not Applicable
3o	Total area put in use under different heads at the end of year	No Proposal was given	Not Applicable
3p	Production of ROM mineral during the last five year period as applicable	No Proposal was given	Not Applicable

3q	General remarks of inspecting officers on method of mining etc.	Mining lease is closed since 2012, no mining activity is seen in the ML area at the time of inspection. last approved mining plan was 21.09.2012. mine was inspected for submitted draft RMP	Mining lease is closed since 2012, no mining activity is seen in the ML area at the time of inspection. last approved mining plan was 21.09.2012. mine was inspected for submitted draft RMP
----	---	--	--

Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	No proposal was given	Not Applicable	
4b	Location of topsoil, OB and mineral reject dumps	No proposal was given	Not Applicable	
4c	Number of dumps within lease area and outside of lease area	No proposal was given	Not Applicabe	
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	No proposal was given	Not Applicable	
4e	Number of active and alive dumps.	No proposal was given	Not Applicable	
4f	Number of dead dumps.	1	1	
4g	Number of dumps established.	None	None	

4h	Whether Retaining wall or garland drain all along dumps are there.	No proposal was given	Not Applicable
4i	Length of Retaining wall or garland drain all along dumps	No proposal was given	Not Applicable
4j	Number of settling ponds	None	None
4k	Specific comments of inspecting officer on waste dump management	Mining lease is closed since 2012, no mining activity is seen in the ML area at the time of inspection. last approved mining plan was 21.09.2012. mine was inspected for submitted draft RMP	Mining lease is closed since 2012, no mining activity is seen in the ML area at the time of inspection. last approved mining plan was 21.09.2012. mine was inspected for submitted draft RMP .

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	No proposal given	Not Applicabe	
5b	Area under backfilling of mined out area	No proposal was given	Not Applicable	
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	No proposal was given	Not Applicabe	

5d	Total area fully reclaimed and rehabilitated	No proposal was given	Not Applicable
5e	General remarks of inspecting officers on backfilling and reclamation etc.	Mine was temporarily discontinued since 2022. Mining Plan was expired since 2017.	Mine was temporarily discontinued since 2022. Mining Plan was expired since 2017.

Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
6a	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	No proposal was given	Not Applicable	
6b	Area available for rehabilitation (ha) .	No proposal was given	Not Applicable	
6c	afforestation done (ha).	No proposal was given	Not Applicable	
6d	No. of saplings planted during the year	No proposal was given	Not Applicable	
6e	Cumulative no .of plants	No proposal was given	Not Applicable	
6f	Any other method of rehabilitation	No proposal was given	Not Applicable	
6g	Cost incurred on watch and care during the year	No proposal was given	Not applicable	
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (Lx B x D	No proposal was given	Not Applicable	

6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	No proposal was given	Not Applicable
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	No proposal was given	Not Applicable
6l	Compliance on reclamation and rehabilitation by backfilling (v) any other specific means.	No proposal was given	Not Applicable
6m	Compliance of rehabilitation of waste land within lease (i) afforestation	No proposal was given	Not Applicable
6n	Compliance of rehabilitation of waste land within lease (ii) Area rehabilitation (ha)	No proposal was given	Not Applicable
6o	Compliance of rehabilitation of waste land within lease (iii) Method of rehabilitation	No proposal was given	Not Applicable
6p	Compliance of environmental monitoring (core zone and buffer zone)	Not Monintored	Not Monintored

6q	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.	Mining lease is closed since 2012, no mining activity is seen in the ML area at the time of inspection. last approved mining plan was 21.09.2012. mine was inspected for submitted draft RMP	Mining lease is closed since 2012, no mining activity is seen in the ML area at the time of inspection. last approved mining plan was 21.09.2012. mine was inspected for submitted draft RMP
----	---	--	--

Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	No proposal was given	Not Applicable	
7b	Method of grade-wise mineral sorting i.e. manual or mechanical.	No proposal was given	Not Applicable	
7c	Different grade of mineral sorted out at mines.	No proposal was given	Not Applicable	
7d	Any beneficiation process at mines .	No proposal was given	Not Applicable	
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues	No proposal was given	Not Applicable	

Environment:

Sl.No.	Item	Proposals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	No proposal was given	Not Applicable	
8b	Concurrent use or storage of topsoil	No proposal was given	Not Applicable	
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	No proposal was given	Not Applicable	
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	No proposal was given	Not Applicable	
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	No proposal was given	Not Applicable	
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	No Information given	No Information given	
8g	Survival rate	No proposal was given	Not Applicable	
8h	Water sprinkling on roads to control airborne dust	No proposal was given	Not Applicable	

8i	General remarks of inspecting officer on aesthetic beauty in and around mines area	Mining lease is closed since 2012, no mining activity is seen in the ML area at the time of inspection. last approved mining plan was 21.09.2012. mine was inspected for submitted draft RMP	Mining lease is closed since 2012, no mining activity is seen in the ML area at the time of inspection. last approved mining plan was 21.09.2012. mine was inspected for submitted draft RMP
----	--	--	--

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns	Return Submitted	Return Submitted	
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Not Appointed	Mine was not working since 2012.	
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	Not Mentioned	Mine was not working since 2012.	
9d	Scrutiny of Annual return on afforestation	Not Mentioned	Mine was not working since 2012.	
9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	Mine was not working since 2012.	Mine was not working since 2012.	

9f	Scrutiny of Annual return on ROM stock and/or graded ore	Mine was not working since 2012.	Mine was not working since 2012.
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost	No production was carried out during the year .	Mine was not working since 2012.
9h	Scrutiny of Annual return on fixed assets	Mine was not working since 2012.	Mine was not working since 2012.
9k	Scrutiny of Annual return on mining machineries	Mine was not working since 2012.	Mine was not working since 2012.

Details of violations observed during current inspection and compliance position of violation pointed out

Violation observed			Show cause position		
Rule NO.	Issued on	Compliance on	Rule NO.	Issued on	Compliance on

Date :

(DAMODAR PRASAD SHARMA)

Indian Bureau of Mines