



**GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
OFFICE OF THE REGIONAL CONTROLLER OF MINES**



Jabalpur

To,

**Shri Mordhwaj Mishra (Nominated Owner),
M/s Shri.Marutaye Balaji Steel Ltd,
Korigawan, Post Khamahariya,
Tehsil Kotar,Satna (M.P.)-485 001
[E-mail-smbsslkolkata@gmail.com](mailto:smbsslkolkata@gmail.com)**

Subject: - Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Bhatia Kala Limestone Mine over an area of 107.785 hect. having Mine Code 38MPR35294 situated in Satna district of M.P. State.

Sir,

Following provisions of MCDR 2017 were found violated in your above mine based on the examination of submitted Drone imagery and inspection by the Undersigned on 19/07/2024 in the presence of Shri Anil Kumar (Mines Manager), Shri Sushant Kumar Saha (Mine Geologist) & Mine officials:

Rule No	Nature of violation observed in detail
11(1)	<p>No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government.</p> <p>The Modification in approved Mining Plan of above mentioned mine was approved vide letter No.MP/Satna/Limestone/MPLN/MOD-25/2022-23 dated 13/09/2022 incorporating proposal of working from 2022-23 to 2023-24 and following deviations have been observed :</p> <p>(a) Only 74440 Tonnes of Limestone is generated against the proposal of 700010 Tonnes of Limestone for the year 2023-24.</p> <p>(b) Only 8049 m³ of overburden is generated against the proposal of 98874 m³ of overburden for the year 2023-24. Further only 3221 m³ of Topsoil is generated against the proposal of 87302 m³ of Topsoil for the year 2023-24.</p> <p>(c) Refer 4.2.2.2: Yearwise Opencast Development – I, during the year 2023-24 it was proposed to carryout development of Quarry 1 in the north between the coordinates N 2722797 – N 2722901 & E 486630 – E 486815 and in Quarry 2 in the south between the coordinates N 2722242 – N 2722347 & E 487717 – E 487867. But during the year, the development of Quarry 2 was not carried out.</p> <p>Hence the exploration, development & excavation were found lagging behind the approved proposals.</p>
33	<p>The holder of a mining lease shall, on or before the 30th day of June every year submit to the authorized Officer, as the case may be, and the State Government, a digital copy along with a print copy of the surface geological plans and sections maintained under rule 32.</p> <p>Copies of plans and sections under rule 32 of MCDR-2017 have not been submitted.</p>

- In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.
- The mining operations can be suspended under the rule 11(2) of MCDR-2017, if compliance of rule 11(1) of MCDR-2017 read with MCDR-2021 (Amendment) is not found satisfactory.
- You are advised to rectify the violations of abovementioned rules immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

Yours faithfully

(Robert Simon C)
Asst. Controller of Mines
For Regional Controller of Mines

Copy for kind information to:

01. The Director of Geology & Mining, Govt .of Madhya Pradesh, Khanij Bhavan, 29-A, Arera Hills, Bhopal (M.P.) for information and further necessary action please.
02. The Controller of Mines (CZ). IBM, Nagpur.

(Robert Simon C)
Asst. Controller of Mines
For Regional Controller of Mines