

1



भारत सरकार GOVERNMENT OF INDIA
खान मंत्रालय MINISTRY OF MINES
भारतीय खान ब्यूरो INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक के कार्यालय
OFFICE OF THE REGIONAL
CONTROLLER OF MINES



BY REGD POST A/

D

Phone: 0674-2352463

Tele Fax: 0674-2352490

E-mail:

ro.bhubaneshwar@ibm.gov.in

Plot No.149, Pokhariput

BHUBANESWAR-751020

दिनांक -

03/01/2025

प्रेषिति-

M/s Jagat Janani Services Private Ltd.,
At : Nambira,
Post : Bamebari
Distt. – Keonjhar (Odisha),
E-mail : jjsplnambira@gmail.com,
sanatanmahakud485@gmail.com,

विषय- ओडिशा राज्य के **क्योंझर** जिले में स्थित आपकी जुरुरी लौह अयस्क खदान 73.413 हे० में खनिज संरक्षण एवं विकास नियमावली 2017 के नियमों के उल्लंघन के संबंध में-

महोदय

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated during inspection of the above mine on 13.12.2024 by undersigned accompanied by Shri Govind Chandra Bhoi(Mine Manager) & Shri C.B.Das, QP.

Rule	Nature of Violation observed
11(1)	Mining operations should have been undertaken in accordance with the Mining Plan/ Review of Mining Plan. The Mining Plan was approved vide letter no. MP/A/28-ORI/BHU/2020-21/2249 dated 03.12.2020 and following deviation was observed during inspection - During mine visit it was observed that that bench parameters are not as per proposal. The benches not developed as per proposal. The maximum height of bench was proposed 6.0 meter and minimum width 6 meter but bench height in many places in both the pits(Top pit between BP-I to BP-J,BP-K1 to BP-J & Tata pit between BP-K3 to BP-L2) 15-20 meter(benches collapsed) and width also less than proposal. There are many places where undercuts in benches, overhang boulder observed. The mineral also stacked at the edge of the benches. - The production proposal was given ROM 515987 MT but actually 210900 MT done which is only 40% of the proposal. The dispatch of Iron ore was only 113690 MT. - The OB/waste generation is proposed 122200 m3 in 2023-24 but actual generation was 68698 m3. - The dumping was not done as per proposal in 2023-24. The dumping was proposed in flat area between BP-G1 and existing backfilled/waste dump area in northern side of ML.

- 2 इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है। एवम इस नियम का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) के अंतर्गत
- (क) खान की सारी खनन संक्रियाएं बंद की जा सकती है।
- (ख) आपके विरुद्ध अभियोग दायर किया जा सकता है।
- (ग) खनन पट्टे को निरस्त करने की सिफारिस राज्य सरकार से की जा सकती है।
- 3 अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का अतिशिघ्र सुधार करें एवम इसके सुधार की सूचना इस पत्र के जारी होने से 45 दिन के भितर इस कार्यालय को सूचित करें।

भवदीय

(राजेश कुमार दास)
उप खान नियंत्रक
भारतीय खान ब्यूरो, भुवनेश्वर

Copy forwarded for kind information to:

- (1) The Director of Mines, Directorate of Mines, Government of Odisha, Heads of Department Building, Bhubaneswar-751 001
- (2) The Controller of Mines (EZ), Indian Bureau of Mines, CP-13, Sector V Salt Lake City, Kolkata- 700 091.

(राजेश कुमार दास)
उप खान नियंत्रक
भारतीय खान ब्यूरो, भुवनेश्वर