

1



भारत सरकार GOVERNMENT OF INDIA
खान मंत्रालय MINISTRY OF MINES
भारतीय खान ब्यूरो INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक के कार्यालय
OFFICE OF THE REGIONAL
CONTROLLER OF MINES



BY REGD POST A/

D

Phone: 0674-2352463

Tele Fax: 0674-2352490

E-mail:

ro.bhubaneshwar@ibm.gov.in

Plot No.149, Pokhariput

BHUBANESWAR-751020

दिनांक -

13/01/2025

प्रेषित-

श्री आशीष गुप्ता, नोमीनटेड ओनर ,
नादिडीह लौह अयस्क खदान
M/s. ईएसएल स्टील लिमिटेड
Siyaljori, Po. Jogidihop. Bangaria, Ps.
Chandankiyari, Dist. Bokaro-828303
E-mail: ashishgupta3@ vedanta.co.in,
navanath.vhatte@vedanta.co.in

विषय- ओडिशा राज्य के सुंदरगढ़ जिले में स्थित आपकी नादिडीह मैंगनीज और लौह अयस्क खदान 117.206 हे० में
खनिज संरक्षण एवं विकास नियमावली 2017 के नियमों के उल्लंघन के संबंध में-

महोदय

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated during inspection of the above mine on 12.12.2024 by undersigned accompanied by Shri Vikil N.Kawale(Mine Manager) & Shri Abani Kumar Dash, Geologist.

Rule	Nature of Violation observed
11(1)	Mining operations should have been undertaken in accordance with the Mining Plan/ Review of Mining Plan. The Mining Plan was approved vide letter no. MCDR-MiFL/21/2022-BBS-IBM_RO_BBS dated 12.06.2024 and following deviation was observed during inspection 1. During mine visit it was observed that that bench parameters are not as per proposal. The benches not developed as per proposal. The maximum height of bench was proposed 9.0 meter and minimum width 10 meter but bench height in many places in both the pits(South Pit between BP-25 to BP-26,BP-13 to BP-17 & North pit northern direction) 12-15 meter(benches collapsed) and width also less than proposal. There are many places where undercuts in benches, overhang boulder observed. The mineral also stacked at the edge of the benches. 2. The Mineral Reject Generation was more w.r.t proposal given in 2023-24.The proposal of mineral reject generation was 1010804 MT but actually 1650558.39 MT generate. 3. The OB/waste generation is proposed 1600185.2 m3 in 2023-24 but actual generation was 480492.4 m3. 4. There was proposal of garland drain all around dump of 280 meter in 2023-24 but actually no garland drain done.
45(5)(c)	While scrutiny of Annual returns'24 few discrepancies observed 1. In part V it is observed that the mineral reject/subgrade from unprocessed ore & unprocessed ore avg grade mentioned same 45% Fe.

- 2 इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है। एवम इस नियम का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) एवम 45(7)(क) के अंतर्गत
(क) खान की सारी खनन संक्रियाएं बंद की जा सकती हैं।
(ख) आपके विरुद्ध अभियोग दायर किया जा सकता है।
(ग) खनन पट्टे को निरस्त करने की सिफारिस राज्य सरकार से की जा सकती है।
- 3 अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का अतिशिघ्र सुधार करें एवम इसके सुधार की सूचना इस पत्र के जारी होने से 45 दिन के भीतर इस कार्यालय को सूचित करें।

भवदीय

(राजेश कुमार दास)
उप खान नियंत्रक
भारतीय खान ब्यूरो, भुवनेश्वर

Copy forwarded for kind information to:

- (1) The Director of Mines, Directorate of Mines, Government of Odisha, Heads of Department Building, Bhubaneswar-751 001
- (2) The Controller of Mines (EZ), Indian Bureau of Mines, CP-13, Sector V Salt Lake City, Kolkata- 700 091.

(राजेश कुमार दास)
उप खान नियंत्रक
भारतीय खान ब्यूरो, भुवनेश्वर