

1



भारत सरकार GOVERNMENT OF INDIA
खान मंत्रालय MINISTRY OF MINES
भारतीय खान ब्यूरो INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक के कार्यालय
OFFICE OF THE REGIONAL
CONTROLLER OF MINES



BY REGD POST A/

D

Phone: 0674-2352463

Tele Fax: 0674-2352490

E-mail:

ro.bhubaneshwar@ibm.gov.in

Plot No.149, Pokhariput
BHUBANESWAR-751020

दिनांक -

25/11/2024

प्रेषिति-

Shri T V Narendran, Nominated Owner,
M/s Tata Steel Ltd,
Bombay House, 24 Homi Mody Street Fort,
Mumbai, E-mail :
gm.office@tatasteel.com,
sabyasachy@tatasteel.come-mail

विषय- ओडिशा राज्य के क्योझर जिले में स्थित आपकी तिरिंगपहाड़ मैंगनीज और लौह अयस्क खदान 643.71 हे० में खनिज संरक्षण एवं विकास नियमावली 2017 के नियमों के उल्लंघन के संबंध में-

महोदय

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated during inspection of the above mine on 29.10.2024 by undersigned accompanied by Shri Shambhu Nath Jha, Agent Mines & Shri Rakesh Kumar, Mines Manager.

Rule	Nature of Violation observed
11(1)	Mining operations should have been undertaken in accordance with the Mining Plan/ Review of Mining Plan. The Review of Mining Plan was approved vide letter no. RMP/A/07-ORI/BHU/2020-21, Dtd. 31.07.2020 and following deviation was observed during inspection - As per last approved document the exploration proposed in 2020-21 & 2021-22 was total 346 nos of bore holes of total meterage 17745 meter but till date only 257 nos bore holes of 13002.4 meterage reported in last proposed period. - The production proposed for 2023-24 was given for manganese ROM 238000 tons & Iron ore of 688999 Tons and against which only 55803 tons of manganese ROM and Nil Iron ore production reported which is only 23% for Manganese. - The production was proposed in two pits Garuda -A & Garuda-B for 2023-24 but actually production is done in Garuda-A. - There were proposals of 400m retaining wall and 400 meter Garland drain in 2023-24 but actually only 50 meter retaining wall constructed and Nil drainage.

- 2 इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है। एवम इस नियम का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) के अंतर्गत
- (क) खान की सारी खनन संक्रियाएं बंद की जा सकती हैं।
- (ख) आपके विरुद्ध अभियोग दायर किया जा सकता है।
- (ग) खनन पट्टे को निरस्त करने की सिफारिस राज्य सरकार से की जा सकती है।
- 3 अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का अतिशिघ्र सुधार करें एवम इसके सुधार की सूचना इस पत्र के जारी होने से 45 दिन के भीतर इस कार्यालय को सूचित करें।

भवदीय

(राजेश कुमार दास)
उप खान नियंत्रक
भारतीय खान ब्यूरो, भुवनेश्वर

Copy forwarded for kind information to:

- (1) The Director of Mines, Directorate of Mines, Government of Odisha, Heads of Department Building, Bhubaneswar-751 001
- (2) The Controller of Mines (EZ), Indian Bureau of Mines, CP-13, Sector V Salt Lake City, Kolkata- 700 091.

(राजेश कुमार दास)
उप खान नियंत्रक
भारतीय खान ब्यूरो, भुवनेश्वर