

उल्लंघन पत्र सह कारण बताओ नोटिस

भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खान नियंत्रक कार्यालय
कर्मयोगी भवन, चतुर्थ माला, ब्लॉक-2, सी विंग,
सेक्टर-10A, गांधीनगर, गुजरात, 382010



Government of India
Ministry of Mines
Indian Bureau of Mines
Office of Regional Controller of Mines
Karmayogi Bhavan, 4th Floor, Block-2, C Wing, Sec 10A
Gandhinagar, Gujarat-382010

Tel- 079 29750358 /29750359; ई-मेल/ E-mail: ro.gandhinagar@ibm.gov.in

पत्रावली संख्या: गुज/जाम/LST-024 Mine code 38GUJ07035 ID___ दिनांक : /12/2024

सेवा में :

मै. श्री दिग्विजय सीमेंट कंपनी लिमिटेड,
दिग्विजयग्राम,
जिला जामनगर, गुजरात-361140

M/s Shree Digvijay Cement Co. Ltd.,
Digvijaygram, District Jamnagar
Gujarat- 361140
मोबाइल न. 9875156625, 7861880790

ई-मेल: sdccmines@gmail.com, biswajit.kar@digvijaycement.com

विषय: गुजरात राज्य के देवभूमि-द्वारका जिले की भानवद तालुका में पछतर ग्राम के निकट स्थित आपकी पछतर चूना पत्थर खान, क्षेत्रफल- 52.6 हे. में खनिज संरक्षण एवं विकास नियमावली, 2017 के नियमों का उल्लंघन।

महोदय,

आपकी उपरोक्त खान का खनिज संरक्षण एवं विकास नियमावली, 2017 और स्टार रेटिंग निरीक्षण अधोहस्ताक्षरी द्वारा दिनांक 15.10.2024 को श्री मनीष कुमार उपाध्याय, खान के प्रतिनिधी और बिसवजित कर, खान प्रबन्धक की उपस्थिति में किया गया तथा उक्त निरीक्षण के समय खनिज संरक्षण एवं विकास नियमावली, 2017 के निम्नलिखित नियमों का उल्लंघन पाया गया-

नियम सं.	उल्लंघन के प्रकार का विस्तृत ब्यौरा				
34(A)	Every lessee having- (a) an annual excavation plan of one million tonne or more in a particular year; or (b) leased area of fifty hectare or more, shall carry out a drone survey of the leased area and up to hundred meters outside the lease boundary in the month of April or May every year and submit the processed output [digital elevation model (DEM) and Orthomosaic] images obtained from such survey or any other format as may be specified by the Indian Bureau of Mines in this regard to the Controller General on or before 1st day of July every year. In your case, the Digital Aerial Images submitted under Rule 34(A), it is observed that the processed Drone survey output data submitted to Indian Bureau of Mines does not meet the parameters specified in the SOP for submission of Digital Aerial Images under the said Rule. The deviations in the data submitted is as follows:-				
	S. No.	Data type	Check Point parameters as per SOP	Submitted in proper format (Yes/No)	Remarks
	1.	Exacavated Area, Roads, Infrastructures	.shp (UTM in WGS 84)	No	Polygons not closed. Area couldn't be determined.
	2.	There are 80 boundary pillars in the mines as per approved mining plan but only 46 boundary pillars are mentioned in .shp file.			
	3.	No permanent GCP was found at site.			

45(5)(c) read with 45(7)	The following deficiencies have been found in the scrutiny of the annual return submitted by you for 2023-24 – (i) In point no. 2 and 3 of Part-VI, the stock was reported at both ROM stock and cement grade limestone stock, but during inspection, only one stock was found. (ii) In Point No. 6 of Part-V, ripper is not mentioned in the list of machineries whereas ripper is being used in the mines.
--------------------------------	--

2. In this connection, it is brought to your kind notice that ;
 - a) the above violations constitute an offence punishable under Rule 62 of MCDR 2017 and/or;
 - b) Mining operations can be suspended as per rule 11(2) of MCDR 2017 in case of non-compliance of above rules as these violations also affects provisions of Rule11(1) of MCDR 2017 and/or;
3. In case of violation of Rule 34(A), you are advised to rectify the above violations immediately and upload the data online on DDMS portal **within 45 (Forty Five) days** from the date of issue of this letter
4. In case of violation of Rule 45, it is to inform you that;
 - a) You are also liable to pay such amount as prescribed under MCDR 2017 for delay of each day as per **Schedule-II**, read with Rule **45(7A)** in case of non- compliance of various provisions of Rule 45.
 - b) As per provision of Rule 45(7) and/or 45(7A)(ii) the Regional Controller of Mines may take appropriate action including order of suspension of all mining operations and dispatches on non-compliance of various provisions of Rule 45.
5. In context to the violations of Rule 45, this letter has been considered as show cause notice where you are advised to rectify above violation immediately. You are therefore directed to show cause within a period of 30 days for the violations of Rule 45 from the date of issue of this letter as to why the action under Rules 45(7) and/or 45(7A) shall not be taken against you. No further notice will be given to you in this regard.
6. In context to violation of other Rules, you are advised to rectify the above violation of above Rules immediately and intimate the compliance position to this office, within a period of 45 days for violated rules from date of issue of this letter.
7. This letter is being issued with the approval of Regional Controller of Mines.

भवदीय
Signed by Sunil Kumar
Sharma
 Date: 04-12-2024 17:19:14
 (सुनील कुमार शर्मा)
 वरिष्ठ सहायक खान नियंत्रक
 भारतीय खान ब्यूरो

प्रतिलिपि-

1. Controller of Mines(NZ), Udaipur
2. Commissioner of Geology and Mining, Gandhinagar
3. DDG, MMS Division, Nagpur
4. District Geologist, District: Devbhumi-Dwarka
5. Guard File

वरिष्ठ सहायक खान नियंत्रक
 भारतीय खान ब्यूरो