

स्पीड पोस्ट उल्लंघन पत्र

भारत सरकार  
खान मंत्रालय  
भारतीय खान ब्यूरो  
क्षेत्रीय खान नियंत्रक कार्यालय  
कर्मयोगी भवन, चतुर्थ माला, ब्लॉक-2, सी विंग,  
सेक्टर-10A, गांधीनगर, गुजरात, 382010



Government of India  
Ministry of Mines  
Indian Bureau of Mines  
Office of Regional Controller of Mines  
Carmayogi Bhavan, 4<sup>th</sup> Floor, Block-2, C Wing, Sec 10A  
Gandhinagar, Gujarat-382010

Tel- 079 29750358 /29750359; ई-मेल/ E-mail: ro.gandhinagar@ibm.gov.in

पत्रावली संख्या: JMNG/BXT-036

Mine Code: 07GUJ 0709 दिनांक:

To

M/s. Dalmia Refractories Limited  
Dalmiapuram, Post Office - Kallakudi , Kallakudi  
District- Tiruchirappalli, Tamil Nadu, 621651  
E-mail: k.sanjaykumar@dalmibharat.com

विषय: गुजरात राज्य के जिले- जामनगर की तालुका- कालाकुडी में स्थित आपकी Pilidhar Bauxite  
Mine [110/136], क्षेत्रफल- 121.405 हे. में खनिज संरक्षण एवं विकास नियमावली,  
2017 के नियमों का उल्लंघन।

महोदय,

आपकी उपरोक्त खान का संशोधित खनन योजना निरीक्षण अधोहस्ताक्षरी द्वारा दिनांक 07-08-  
2024 को श्री संजय कुमार तिवारी (खान प्रबन्धक) की उपस्थिति में किया गया तथा उक्त निरीक्षण के  
समय खनिज संरक्षण एवं विकास नियमावली, 2017 के निम्नलिखित नियमों का उल्लंघन पाया गया-

| नियम सं./<br>Rule No | उल्लंघन के प्रकार का विस्तृत ब्यौरा/ Detailed description of the type of<br>violation  |
|----------------------|--|
| 11(1)                | No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5 or approved by the competent authority of the Atomic Minerals Directorate for Exploration and Research, in respect of minerals specified in Part B of the First Schedule to the Act where the grade of such atomic minerals is equal to or above the threshold value limits declared under Schedule-A of the Atomic Minerals Concession Rules, 2016.<br>In your case, it was found that:-<br>a) Pit profiles and Bench design parameters are not being maintained in accordance with Approved Review of Mining Plan No. 684(4) (1) MP-214/2019-20-GNR dated 09.04.2019 as Bench height and levels are very erratic and irregular near co-ordinates 22.27218516N, 69.31531376E & 22.27292472N, 69.31942608E and in some other locations also.<br>b) Working has been found within 7.5 meters statutory limit near co-ordinates 22.27199755N,69.31122339E |
| 40                   | Precautions against Air pollution: - Every holder of prospecting or mining licence shall take all possible measures to keep air pollution to due fitness, dust, smoke or gaseous emissions during prospecting, mining beneficiation and related activities within permissible limit.   |

In your case during inspection, it was found that no preventive measures have taken up for suppression of airborne dust at Mine.

In this connection, it is brought to your kind notice that:-

- a) the above violations constitute an offence punishable under Rule 62 of MCDR 2017 and/or;
  - b) Mining operations can be suspended as per rule 11(2) of MCDR 2017 in case of non-compliance of above rules as these violations also affects provisions of Rule11(1) of MCDR 2017 and/or;
  - c) You are advised to rectify the above violation of above Rules immediately and intimate the compliance position to this office, within a period of 45 days for violated rules from date of issue of this letter.
1. This letter is being issued with the approval of Regional Controller of Mines.

भवदीय/ Yours faithfully,

**Signed by Sanjaya Kumar  
Sahoo  
Date: 18-02-2025 10:08:45**

संजय कुमार साहू/ Sanjaya Kumar Sahoo  
कनिष्ठ खनन भूविज्ञानी/ Junior Mining Geologist  
भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ हेतु प्रेषित/ Copy for favor and information:-

1. Controller of Mines(NZ), Udaipur
2. Commissioner of Geology and Mining, Gandhinagar
3. Guard File

कनिष्ठ खनन भूविज्ञानी  
भारतीय खान ब्यूरो