

भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खान नियंत्रक कार्यालय
कर्मयोगी भवन, चतुर्थ माला, ब्लॉक-2, सी विंग,
सेक्टर-10A, गांधीनगर, गुजरात, 382010



Government of India
Ministry of Mines
Indian Bureau of Mines
Office of Regional Controller of Mines
Karmayogi Bhavan, 4th Floor, Block-2, C Wing, Sec 10A
Gandhinagar, Gujarat-382010

Tel- 079 29750358 /29750359; ई-मेल/ E-mail: ro.gandhinagar@ibm.gov.in

File No: AMR/LST-016 Mine code 38GUJ02017

दिनांक:

To

M/s. UltraTech Cement Limited,
Narmada Cement- Jafarabad works
P.B. No: 10, Jafarabad – 365 540,
Dist. Amreli, Gujarat
E-mail id rajendra.goyal@adityabirla.com

विषय: गुजरात राज्य के जिले- Amreli की तालुका- Jafarabad में स्थित आपकी Babarkot Limestone Mine-II (Jafarabad ML 738) , क्षेत्रफल- 14.2045 हे. में खनिज संरक्षण एवं विकास नियमावली, 2017 के नियमों का उल्लंघन।

महोदय,

आपकी उपरोक्त खान का स्टार रेटिंग निरीक्षण अधोहस्ताक्षरी द्वारा दिनांक 19.12.2024 को Mr. Rajendra Kumar Goyal (खान अभिकर्ता) एवं Mr Arvind Singh Rathore (भूविज्ञानी) की उपस्थिति में किया गया तथा उक्त निरीक्षण के समय खनिज संरक्षण एवं विकास नियमावली, 2017 के निम्नलिखित नियमों का उल्लंघन पाया गया-

Rule No.	Nature of Violation observed
11(1)	The following mining operations were not carried out as per the Approved Review of Mining plan No. 684(4)(1)/MP-296/2020-21-GNR, Dated: 13.01.2021. At section 8.3 of the Progressive Mine Closure Plan (PMCP) proposal and in Plate No. 5C, there was a provision to plant 250 trees for afforestation (green belt development) over an area of 0.25 hectares and to install 120 meters of wire fencing during FY 2023-24 around ML boundary pillar no. 17 to 13. However, these proposed PMCP activities were not observed at the specified location during the inspection.
34(A)	Every lessee having— (a) an annual excavation plan of one million tonne or more in a particular year; or (b) leased area of fifty hectare or more, shall carry out a drone survey of the leased area and upto hundred metres outside the lease boundary in the month of April or May every year and submit the processed output [digital elevation model (DEM) and Orthomosaic] images obtained from such survey or any other format as may be specified by the Indian Bureau of Mines in this regard to the Controller General on or before 1st day of July every year. However, in your case, it is found that; The drone survey data you submitted on the DDMS portal of the Indian Bureau of Mines does not comply with the SOP under Rule 34(A). The discrepancies in the submitted data are as follows: the DEM, Orthomosaic, GCPs, and lease boundary pillar coordinates provided pertain to a different mining lease.

- In this connection, it is brought to your kind notice that :-
 - the above violations constitute an offence punishable under Rule 62 of MCDR 2017 and/or;
 - Mining operations can be suspended as per rule 11(2) of MCDR 2017 in case of non-compliance of above rules as these violations also affects provisions of Rule11(1) of MCDR 2017 and/or;

- c) You are advised to rectify the above violation of above Rules immediately and intimate the compliance position to this office, within a period of 45 days for violated rules from date of issue of this letter.
2. In case of violation of **Rule 34(A)**, you are advised to rectify the above violations immediately and upload data online on DDMS portal within 45 (Forty Five) days from the date of issue of this letter.
3. This letter is being issued with the approval of Regional Controller of Mines.

भवदीय/Yours faithfully,

Signed by Debajyoti Nayak

Date: 17-03-2025 18:05:38

Dr. Debajyoti Nayak
Junior Mining Geologist
Indian Bureau of Mines

प्रतिलिपि सूचनार्थ हेतु प्रेषित/ Copy for favor and information:-

1. Controller of Mines(NZ), Udaipur
2. Commissioner of Geology and Mining, Gandhinagar
3. DDG, MMS Division, Nagpur
4. Guard File

कनिष्ठ खनन भूविज्ञानी / Junior Mining Geologist