

भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खान नियंत्रक कार्यालय
कर्मयोगी भवन, चतुर्थ माला, ब्लॉक-2, सी विंग,
सेक्टर-10A, गांधीनगर, गुजरात, 382010

Government of India
Ministry of Mines
Indian Bureau of Mines
Office of Regional Controller of Mines
Karmayogi Bhavan, 4th Floor, Block-2, C Wing, Sec
10A
Gandhinagar, Gujarat-382010

Tel- 079 29750358 /29750359; ई-मेल/ E-mail: ro.gandhinagar@ibm.gov.in

पत्रावली संख्या: PORB/BXT-004/ Mine code: 07GUJ08004
2081

दिनांक: 28/3/25 ID: 9/25

To

M/s. Saurashtra Minerals Pvt. LTD. East Kadia Plots, Dist- Porbandar, Gujarat- 360575
Email- saurashtra1951@gmail.com, tannadipesh@yahoo.com

विषय: गुजरात राज्य के जिले- पोरबंदर में स्थित आपकी Palakhada Bauxite Mine (S No. 185,290 & 299) क्षेत्रफल- 65.3971 हे. में खनिज संरक्षण एवं विकास नियमावली, 2017 के नियमों का उल्लंघन।

महोदय,

आपकी उपरोक्त खान का निरीक्षण अधोहस्ताक्षरी द्वारा दिनांक 19-12-2024 को Shri Shailesh kumar V. Dave (खान प्रबन्धक एवं खनन अभियंता) एवं अन्य की उपस्थिति में किया गया तथा उक्त निरीक्षण के समय खनिज संरक्षण एवं विकास नियमावली, 2017 के निम्नलिखित नियमों का उल्लंघन पाया गया-

नियम सं./Rule No	उल्लंघन के प्रकार का विस्तृत ब्यौरा/ Detailed description of the type of violation
11(1)	No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines: However in your case it is found that; (i) There was proposal of 5 pits for F.Y. 2023-2024 in Review of Mining Plan: 684(4) (1)/MP-318/2020-21-GNR, Dated 02/03/2021; however it was found that exploration was not carried out. (ii) Excavation has been carried out outside the proposed area as given in the approved Review of Mining Plan vide No. 684(4) (1)/MP-318/2020-21-GNR, Dated 02/03/2021. Some locations of excavation done outside the proposed area are N21.76214329, E69.48663516 & N21.76291423, E69.48658362, N21.7605818, E69.4901561 etc.

2. In this connection, it is brought to your kind notice that :-

- the above violations constitute an offence punishable under Rule 62 of MCDR 2017 and/or;
- Mining operations can be suspended as per rule 11(2) of MCDR 2017 in case of non-compliance of above rules as these violations also affects provisions of Rule 11(1) of MCDR 2017 and/or;
- You are advised to rectify the above violation of above Rules immediately and intimate the compliance position to this office, within a period of 45 days for violated rules from date of issue of this letter.

Yours faithfully,

(Pushpender Gaur) 28/3/25
Regional Controller of Mines
Indian Bureau of Mines

प्रतिलिपि सूचनार्थ हेतु प्रेषित/ Copy for favor and information:-

- Controller of Mines(NZ), Udaipur
- Commissioner of Geology and Mining, Gandhinagar
- Guard File

Regional Controller of Mines