

INDIAN BUREAU OF MINES

--:-- Inspection Report --:--

Part-I : General Information

1.1.1 Mine Details

Name of the Mine :	38GUJ08078	Lease Area (Ha) :	1.00
Forest Area (Ha) :	N/A	Mine Code :	38GUJ08078
Registration Number :	IBM/9148/2012	Name of lessee :	BABUBHAI
Address of lessee :	OP.RELWESTESHAN ,AT. GADU, MALIYA HATINA	Phone of lessee :	-
Email of lessee :	Pranavjoshi335@gmail.com	Fax Number :	N/A
Village :	Khorasa Gir	Taluka / Mandal :	Malia Hatina
District :	Junagadh	Pincode :	362255
State :	Gujarat	Post Office :	N/A
Nearest Police Station :	N/A	Nearest Railway Station :	N/A
Date of Grant of Mining Lease :	1984-05-05	Date of Mining Lease Execution :	1984-05-05
Date of opening in the mine :	Nilsss		

Nominated Owner Details			
Name of the Nominated Owner :	N/A	Nominated Owner Address:	N/A
Nominated Owner Mobile :	N/A	Nominated Owner Email :	N/A
Nominated Owner Fax Number :	Nil	Date of Nominated Owner Appointment :	Nil
Mining Engineer Details			
Name of the Mining Engineer :	Ravi Patel	Qualification of Mining Engineer :	Graduate
Address of Mining Engineer :	Gujarat	Phone of Mining Engineer :	N/A
Email of Mining Engineer :	N/A	Fax Number of Mining Engineer :	N/A
Date of Mining Engineer Appointment :	Nil		
Geologist Details			
Name of the Geologist :	Mohak Jani	Qualification of Geologist :	Post Graduate
Address of Geologist :	Gujarat	Phone of Geologist :	N/A
Email of Geologist :	N/A	Fax Number of Geologist :	N/A
Date of Geologist Appointment :	Nil		
Mine Manager Details			
Name of the Mine Manager :	Ravi Patel	Qualification of Mine Manager :	Graduate
Address of Mine Manger :	Gujarat	Phone of Mine Manger :	N/A
Email of Mine Manger :	N/A	Fax Number of Mine Manger :	N/A
Date of Mine Manger Appointment :	Nil		

Mineral(s) granted in lease and proved for mining :	LIMESTONE	Date of Approval of Mining Plan / Modified Mining Plan / ROMP with five-year period :	2025-10-17 (2025 - 2028)
Method of mining :	Open Cast	Category :	OTHER_THAN_MECHANISED
Nature of Use :	Non Captive		

Part-II : Other Information

2.1.1 : Inspection Details

Inspecting Officer :	Debajyoti Nayak
Designation :	Inspection Officer
Name of the Accompanying Official from Mine :	Rakesh Dodiya
Designation of the Accompanying Official :	QP
Type of Inspection :	MCDR,MPAS
Date of Inspection :	20/07/2025
Review year considered for MCDR Inspection :	2024-2025

Final Submitted

2.2.1 : Exploration Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File	
1	Number of Core Boreholes	4	4	0.000	No Violation	04 Number of Boreholes were carried out in 2024-25 with a Borehole Meterage of 80 meters.	Nil	
2	Number of DTH Boreholes	0	0	0.000	No Violation	Not Proposed in 2024-25.	Nil	
3	Number of exploratory pits / trial pits	0	0	0.000	No Violation	Not Proposed in 2024-25.	Nil	
4	Number of exploratory Trenches	0	0	0.000	No Violation	Not Proposed in 2024-25.	Nil	
5	Lateral exploration status for the lease area	G1	1Ha	1 Ha	0.000	No Violation	The total lease area was explored in the G1 level of exploration.	Nil
6		G2	0	0	0.000	No Violation	Nil	Nil
7		G3	0	0	0.000	No Violation	Nil	Nil
8		G4	0	0	0.000	No Violation	Nil	Nil
9	UNFC category wise reported	111-78404,	111-78404,	100%	No Violation	The production	Nil	

	Resources/Reserves as per MP/MMP ROMP Total Reserves (111, 121 & 122) and Total Mineral Resources (331, 332 & 333 upto 334)	211-45324	211-45324			and dispatch of the mine were halted during this period. Hence, no depletion of Resources and Reserves reported during this period.	
--	--	-----------	-----------	--	--	---	--

2.3.1 : Development - Opencast Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Location of development w.r.t. lease area	Pit : Pit-1,2 & Direction : NORTH	No development work carried out.	Deviation found.	No Violation	No development work was carried out within the lease area during 2024-25.	Nil
2	Quantity of overburden generation in m3	0.00	0	0.000	No Violation	No proposal was given for the Quantity of overburden generation in m3.	Nil
3	Quantity of topsoil generation in m3	0.00	0	0.000	No Violation	No proposal was given for the quantity of topsoil generation in m3.	Nil
4	Stripping ratio : ore to OB ratio	NA	NA	0.000	No Violation	No overburden	Nil

						reported within the lease.	
--	--	--	--	--	--	----------------------------	--

2.4.1 Exploitation - Opencast Mine Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Number of pits / Blocks proposed for production	Pit ID : Pit-1,2	Pit-1,2	NA	No Violation	Two pits/blocks were proposed for production; however, no work was undertaken during this period.	Nil
2	Quantity of ROM mineral production proposed (in T)	23402.00	0	23402.000	No Violation	Production of ROM was not carried out during this period.	Nil
3	Recovery of salable/usable mineral quantity from ROM production in T)	23402.00	0	23402.000	No Violation	Production of ROM was not carried out during this period.	Nil
4	Quantity of mineral reject/Sub-grade generation	0.00	0	0.000	No Violation	No proposal was given for mineral reject/Sub-grade generation within the mine site.	Nil

5	Grade of mineral reject/sub-grade generation as per threshold value declared	0	0	0.000	No Violation	No proposal was given for the Grade of mineral reject/sub-grade generation as per the threshold value declared within the mine site.	Nil
6	Manual/Mechanised method adopted for segregating subgrade/mineral rejects from ROM	Manual	No work carried.	NA	No Violation	As no ROM production was undertaken during this period, the manual/mechanised method for segregating subgrade/mineral rejects from ROM was not applicable.	Nil
7	Whether height of benches in Overburden& mineral suitable for method of mining proposed in mining plan	Proposed Height-3m in mineral	Yes, Proposed Height-3m in mineral is suitable for method of mining proposed in mining plan.	NA	No Violation	Production and development work were not carried out during this period.	Nil
8	Any analysis or beneficiation study proposed & carried out for sub-grade mineral and reject	Not Proposed.	NA	NA	No Violation	No proposal was given in the submitted mining plan for the beneficiation study proposed & carried out for sub-grade mineral and reject.	Nil

2.4.3 : Exploitation - Dump Working Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Number of dumps proposed for production	Not Proposed.	NA	NA	No Violation	There is no proposal for Exploitation from Dump material handling.	Nil
2	Quantity of dump material handling Proposed (in Tonne)	Not Proposed.	NA	NA	No Violation	Nil	Nil
3	Recovery of salable/usable mineral from dump production (in Tonne)	Not Proposed.	NA	NA	No Violation	Nil	Nil
4	Production from dump(s) during the year	Not Proposed.	NA	NA	No Violation	Nil	Nil
5	Quantity of mineral reject generation	Not Proposed.	NA	NA	No Violation	Nil	Nil
6	Grade of mineral reject generation and threshold value declared	Not Proposed.	NA	NA	No Violation	Nil	Nil
7	Any analysis or beneficiation study proposed & carried out for mineral reject	Not Proposed.	NA	NA	No Violation	Nil	Nil
8	Manual / Mechanized method adopted for dump working	Not Proposed.	NA	NA	No Violation	Nil	Nil

2.5.1 : OB/Waste Dumps Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Separate dumping of topsoil, OB & mineral rejects, fines, tailings (Rule 36,37)	Not Proposed.	NA	NA	No Violation	No topsoil or overburden was reported within the lease area, so no proposal was given.	Nil
2	Location of Topsoil, OB/Waste, Mineral Reject dumps, Tailings and Fines	Not Proposed.	NA	NA	No Violation	Nil	Nil
3	Number of active & Inative dumps	Not Proposed.	NA	NA	No Violation	Nil	Nil
4	Number of dead dumps	Not Proposed.	NA	NA	No Violation	Nil	Nil
5	Number of dumps proposed for stabilished	Not Proposed.	NA	NA	No Violation	Nil	Nil
6	Stabilization Technique (Terracing, plantation, geo-textiles etc.)	Not Proposed.	NA	NA	No Violation	Nil	Nil

2.6.1 : Solid Waste Management - Backfilling (Opencast) Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Status on part or full extraction of mineral from mined out area before starting backfilling	Not Proposed.	NA	NA	No Violation	No proposal was given for Solid Waste Management and Backfilling in this plan period.	Nil
2	Year-wise area under backfilling of mined out area	Not Proposed.	NA	NA	No Violation	No proposal was made for backfilling the mined-out area in this plan period.	Nil
3	Year-wise topsoil generation, Utilization and Stored proposal (in m3)	Not Proposed.	NA	NA	No Violation	No topsoil reported within the lease period.	Nil
4	Total area fully reclaimed & rehabilitated	Not Proposed.	NA	NA	No Violation	Nil	Nil
5	Locations of proposed reclamation & rehabilitated	Not Proposed.	NA	NA	No Violation	Nil	Nil

Final Submitted

2.7.1 : Progressive Mine Closure Plan (PMCP) Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Compliance on reclamation and rehabilitation by backfilling/Other means Total area and numbers of plantation proposed.	Plantation : Location :Statutory Boundary barrier, Area : 0.04, No. of Plant : 40 Plantation : Location :Statutory Boundary barrier, Area : 0.04, No. of Plant : 40	Plantation: Location: Statutory Boundary barrier, Area covered: 0.01, No. of Plant :10	Deviation reported	Rule 11(1)	There is a proposal for a plantation around the Statutory Boundary barrier of an area of 0.04Ha and 40 plants, but the lessee has done only 10 plants in a 0.01Ha area. So a violation has issued.	Nil
2	Rehabilitation by making water reservoir	Not Proposed	NA	NA	No Violation	No proposal was given for rehabilitation by making a water reservoir during this plan period.	Nil
3	Compliance of Rehabilitation of waste land within lease i) Afforestation ii) Area rehabilitated (ha) iii) Method of rehabilitation	Fencing- 157-meter, Location: 21:43:08.00 21:42:55.00 69:41:47.00 69:41:59.00	No fencing in the said area found.	Deviation found	Rule 11(1)	Fencing - 157 meters. Coordinates: 21:43:08.00, 21:42:55.00, 69:41:47.00, 69:41:59.00. Fencing proposal was given, but no work was carried out in the stated area during this	Nil

						plan period. So a violation of 11(1) was issued.	
4	Compliance of Environmental monitoring (core zone & buffer zone)	Nil	Nil	Nil	No Violation	Nil	Nil

Final Submitted

2.8.1 : Mineral Conservation Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	ROM Mineral dispatch or grade-wise sorting within lease area	ROM Mineral dispatch-0.0	0	NA	No Violation	Production and dispatch of material were not carried out during this plan period.	Nil
2	Different grade of mineral sorted out at mines	Proposed	0	NA	No Violation	Production of material was not carried out during this plan period. Hence, Different grades of minerals are not sorted out at mines	Nil
3	Any beneficiation process at mines	Not Proposed	NA	NA	No Violation	Nil	Nil
5	Utilization of Mineral Rejects or Sub-grade (Blending at ROM stage, Blending after Processing etc.)	Not Proposed	NA	NA	No Violation	Nil	Nil

Final Submitted

2.9.1 : Environment Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Separate removal and utilization of topsoil	Not Proposed	NA	NA	No Violation	Nil	Nil
2	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	Not Proposed	NA	NA	No Violation	Nil	Nil
3	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	Not Proposed	NA	NA	No Violation	Nil	Nil
4	Plantation & Survival rate	Plantation : 40, Survial Rate : 70	Plantation: 10, Survial Rate: 50	Deviation reported.	Rule 11(1)	During the field inspection, it was observed that both the plantation density and the sapling survival rate were low. Hence, a violation was issued.	Nil
5	Water sprinkling on roads to control airborne dust	Proposed	Not Carried out.	NA	No Violation	No mining operation was carried out during this year, so Water sprinkling on roads to control airborne dust was not carried out.	Nil

2.10 : Annual Return Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Submission of Online Monthly and Annual returns in prescribed period or not	Last Annual Returns : Yes, Last Monthly Returns : Yes - June 2024 - Submitted on : 2024-07-05	Last Annual Returns: 2024-25 submitted on 27/06/2025. Monthly Returns: All monthly reruns were Submitted during 2024-25.	No deviation	No Violation	Nil	Nil
2	Appointment of Mining Engineer & Geologist as per provisions of Rule 55 of MCDR,2017	Geologist : Mohak Jani Mine Engineer : Ravi Patel.	Geologist: Mohak Jani and Mining Engineer-Ravi Patel.	No deviation	No Violation	Nil	Nil
3	Whether incomplete or false or wrong returns submitted (Rule 45(7))	Incomplete and wrong information submitted in Annual returns 2024-25. (Rule 45(7))	1. The plantation numbers are incorrect, and the KML file for PMCP works is missing. 2. Trees planted- survival rate data given in the table is incorrect. 3. The lessee has not paid the dead rent for the year 2024-25 as per the annual return	Deviation found.	Rule 26(2) Rule 45(7)	The PMCP Annual Report contains an incorrect plantation figure, and the attached KML file is incomplete as it does not include the polygon shapefile for PMCP work carried out during 2024–25. 2. In Part V,	Nil

			submitted.			Table No. 5 (Trees Planted – Survival Rate), the data provided is inaccurate. Please correct the figures and resubmit the Annual Return. 3. Since no royalty, DMF, or NMET payments were made due to the absence of mining activity in 2024–25, the lessee is required to pay the Dead Rent for the same year.	
4	Status of Approval of FMPCP u/r 24, 25 of MCDR,2017	Not Applicable	Not Applicable	Not Applicable	No Violation	Nil	Nil
5	Notices and Returns for the lease area submitted or not where fine applicable	Nil	Nil	Nil	No Violation	Nil	Nil
6	Scrutiny of Annual return on sale value, Ex. Mine price & production cost	Annual return on sale value, Ex. Mine price & production cost is reported zero.	Annual return on sale value, Ex. Mine price & production cost is reported zero.	NA	No Violation	No production and dispatch were carried out during this period.	Nil

Final Submitted

2.11 : SDF Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Start Ratings accorded for mine during last 3 years	Year of Submission : 2023-2024 , Rating : 3 Stars. In 2024-25-Not submitted.	The lessee has not submitted the Start Rating for 2024-25 as per the MTS star rating portal record.	Deviation found.	Rule 35(2)	The lessee has not submitted the Star Rating for 2024-25, as per the records of the MTS Star Rating portal.	Nil

Part-III : Other Reports**3.1.1 : Upload Other Reports**

S.N.	Reports File	Remark File Description
1	Nil	Nil

Final Submitted

Part-IV : Summary Details

4.1 : Summary of Violations

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	<p>Progressive Mine Closure Plan : Compliance on reclamation and rehabilitation by backfilling/Other means</p> <p>Total area and numbers of plantation proposed.</p>	<p>Plantation : Location :Statutory Boundary barrier, Area : 0.04, No. of Plant : 40 Plantation : Location :Statutory Boundary barrier, Area : 0.04, No. of Plant : 40</p>	<p>Plantation: Location: Statutory Boundary barrier, Area covered: 0.01, No. of Plant :10</p>	Deviation reported	Rule 11(1)	There is a proposal for a plantation around the Statutory Boundary barrier of an area of 0.04Ha and 40 plants, but the lessee has done only 10 plants in a 0.01Ha area. So a violation has issued.	Nil
2	<p>Progressive Mine Closure Plan : Compliance of Rehabilitation of waste land within lease</p> <p>i) Afforestation ii) Area rehabilitated (ha) iii) Method of rehabilitation</p>	<p>Fencing- 157-meter, Location: 21:43:08.00 21:42:55.00 69:41:47.00 69:41:59.00</p>	No fencing in the said area found.	Deviation found	Rule 11(1)	<p>Fencing - 157 meters. Coordinates: 21:43:08.00, 21:42:55.00, 69:41:47.00, 69:41:59.00. Fencing proposal was given, but no work was carried out in the stated area during this plan period. So a violation of 11(1) was issued.</p>	Nil

3	Environment : Plantation & Survival rate	Plantation : 40, Survival Rate : 70	Plantation: 10, Survival Rate: 50	Deviation reported.	Rule 11(1)	During the field inspection, it was observed that both the plantation density and the sapling survival rate were low. Hence, a violation was issued.	Nil
4	Annual Return : Whether incomplete or false or wrong returns submitted (Rule 45(7))	Incomplete and wrong information submitted in Annual returns 2024-25. (Rule 45(7))	1.The plantation numbers are incorrect, and the KML file for PMCP works is missing. 2. Trees planted- survival rate data given in the table is incorrect. 3. The lessee has not paid the dead rent for the year 2024-25 as per the annual return submitted.	Deviation found.	Rule 26(2) Rule 45(7)	The PMCP Annual Report contains an incorrect plantation figure, and the attached KML file is incomplete as it does not include the polygon shapefile for PMCP work carried out during 2024–25. 2. In Part V, Table No. 5 (Trees Planted – Survival Rate), the data provided is inaccurate. Please correct the figures and resubmit the Annual Return. 3. Since no royalty, DMF, or NMET payments were made due to the absence of mining activity in	Nil

Final Submitted

						2024–25, the lessee is required to pay the Dead Rent for the same year.	
5	SDF : Start Ratings accorded for mine during last 3 years	Year of Submission : 2023-2024 , Rating : 3 Stars. In 2024-25-Not submitted.	The lessee has not submitted the Start Rating for 2024-25 as per the MTS star rating portal record.	Deviation found.	Rule 35(2)	The lessee has not submitted the Star Rating for 2024–25, as per the records of the MTS Star Rating portal.	Nil
6	Digital Aerial images of Mining Lease	Every lessee shall carry out a drone survey of the leased area and submit to the Indian Bureau of Mines on or before 1st day of July every year.	The submitted drone survey data does not comply with the SOP.	Deviation found.	Rule 34A(2)	- The submitted drone survey data is not in compliance with the SOP. In the DDMS portal, the data has been referred back; please correct it and reupload as per the SOP.	Nil
7	Notice of Temporary discontinuance of work in mines.	Form -E not submitted.	The mine has discontinued its operations for more than 90 days, yet the lessee has not submitted Form-E for temporary discontinuance to this office.	Deviation found.	Rule 28(1)	The mine has discontinued its operations for more than 90 days, yet the lessee has not submitted Form-E for temporary discontinuance to this office.	Nil

Esigned by:  Debajyoti Nayak
Date: 25/11/2025 12:09:24 PM