

MCDR INSPECTION REPORT

1.0 GENERAL

SN	Particulars	Details
1	Name of the Mine	Khorasa Limestone Mines
1 (a)	Name of the lessee	Sh. Babubhai Kalabhai Vaja
1(b)	Name of Inspecting Officer & Designation	Jigneshkumar Parmar, AME
1(c)	Accompanying Mines Representatives	Sh. Jagatbhai Joshi & Team
1(d)	Type of Inspection	MCDR
1(e)	Date of Inspection	26-12-2024 (FN)
2	Total Lease Area (Ha) with breakup of Non-forest and forest land	Non-Forest-1.00 Ha
3	Minecode	38GUJ08078
4	IBM Registration Number under rule 45 of MCDR, 2017	IBM/9148/2012
5	Name of the lessee, Address, phone, email and fax number	Sh. Rudabhai Devshibhai Vadher Near Railway Station, Gadu-Sherbagh, Ta.-Maliya-Hatina, Dist. Junagadh, Gujarat-362255 Mob. 9879765339 E-mail: pranavjoshi335@gmail.com
6	Village	Khorasa
7	Taluka/Mandal	Maliya-Hatina
8	District	Junagadh
9	Pincode	362255
10	State	Gujarat
11	Post office	Khorasa
12	Nearest police station	Khorasa
13	Nearest Railway station	Khorasa
14	Date of Grant of Mining Lease	23-02-1984
15	Date of Execution	05-05-1984
16	Date of opening of Mine	05-05-1984
17	Date of first Renewal, if applicable and its period & expiry	N/A
18	Date of second Renewal, if applicable and its period & expiry	N/A
19	Date of submission of renewal application if Mining Operations are continuing under deemed extension	ML valid from 05-05-1984 to 04-05-2034 vide MCR-1583-(V-19)-196-CHH.1, Date-15/06/2017
20	Name of the Nominated Owner with Address, phone, email, fax number and date of appointment	Sh. Rudabhai Devshibhai Vadher Near Railway Station, Gadu-Sherbagh, Ta.-Maliya-Hatina, Dist. Junagadh, Gujarat-362255 Mob. 9879765339 E-mail: pranavjoshi335@gmail.com
21	Name of the Mine Agent with Address, phone, email, fax number and date of appointment	Sh. Jagatbhai Joshi Near Railway Station, Gadu-Sherbagh, Ta.-Maliya-Hatina, Dist. Junagadh, Gujarat-362255 Mob. 9909692840 E-mail: pranavjoshi335@gmail.com
22	Name of the Mines Manager with Address, phone, email, fax number and date of appointment in mines	Shri Ravi Patel, Manager (Mines) Near Railway Station, Gadu-Sherbagh, Ta.-Maliya-Hatina, Dist. Junagadh, Gujarat-362255
23	Name of the Mining Engineer, Qualification and total experience with Address, phone, email, fax number and date of appointment in mine	Shri Ravi Patel, Manager (Mines) Near Railway Station, Gadu-Sherbagh, Ta.-Maliya-Hatina, Dist. Junagadh, Gujarat-362255
24	Whether Geologist and Mining Engineer appointed in mines satisfy the rule 55 & carrying out	Yes, Geologist – Sh. Mohak Jani Mining Engineer- Sh. Ravi Patel

	their duties as per rule 56 & 57.	
25	Date of Approval of Mining Plan/Modified Mining Plan with five-year period and specific condition in approval letter, if any.	682(23)(285)/2003-MCCM(N)UDP, Date – 17-09-2003 682(23)(286)/2003-MCCM(N)UDP, Date – 02-05-2016 684(4)(1)/MP-247/2019-20-GNR-Dated 23-10-2019 684(4)(1)/MP-292(247) /2020-21-GNR- Dated 05-11-2020(MoMP) MCDR-MPCP0CaFI/45/2023-GNRIBMROG NR-MP-512 Dated:10-01-2024 (RoMP)
26	Date of Approval of Scheme of Mining/Modified Scheme of Mining with five-year period and specific condition in approval letter, if any.	N/A
27	Mineral(s) granted in lease and proved for mining	Limestone
28	Method of Mining(Open cast, Underground)	Open cast
29	Category (Fully Mechanised, Others or Manual)	'A' Mechanised.
30	Captive/Non Captive	Non Captive

Scientific Mining: Compliance of proposals of approved mining plan/scheme of mining. –

1.0 Exploration

SN	Item	Proposals (2023-24)	Actual work (2023-24)	Remarks
1a	Backlog of previous year	No Proposal	N.A.	
1b	Exploration over lease area for Geological axis 1 or 2.	4 Nos. (2023-24)	04 Number of Boreholes were carried out in 2023-24 with a Borehole Meterage of 80 meters.	
1c	Exploration Agency & Expenditure in lakh Rupees during the year	NA	NA	
1d	Balance area to be explored to bring Geological axis in 1 or 2	N.A.	N.A.	
1e	Balance reserves as on 01.04.2022	111- 78404 T 211- 45324 T	111- 78404 T 121-45324 T	As per annual returns
1f	General remarks of inspecting officer on geology, exploration etc.	Nil		

2.0 Development

SN	Item	Proposals (2023-24)	Actual work (2023-24)	Remarks
2a	Location of development w.r.t. lease area	Pit 1	Pit 1	
2b	Separate benches in topsoil, overburden and mineral (Rule 15)	N.A.	N.A.	There is no O/B and there is also no any generation of rejects as a result of the mining operations.
2c	Stripping ratio or ore to OB ratio	1:0	1:0	
2d	Quantity of topsoil generation in m3	Nil	Nil	
2e	Quantity of overburden generation in m3	Nil	Nil	

2f	General remarks of inspecting officer on development of pit w.r.t. type of deposit etc.	The deposit is flat bedded deposit and There is no O/B and there is also no any generation of rejects in the lease area.
----	---	--

3.0 Exploitation

SN	Item	Proposals (2023-24)		Actual work (2023-24)		Remarks
3a	Number of pits proposed for production	Pit No. 1		Pit No. 1		
3b	Quantity of ROM mineral production proposed	11482 Tonne		00 Tonne		No Production carried out.
3c	Recovery of salable/usable mineral from ROM production	100%		00		
3d	Quantity of mineral reject generation	NIL		NIL		No mineral reject
3e	Grade of mineral reject generation and threshold value declared	NIL		NIL		No mineral reject
3f	Quantity of sub-grade mineral generation	NA		NA		No Sub-grade Mineral
3g	Grade of sub-grade mineral generation	NA		NA		No Sub-grade Mineral
3h	Manual / Mechanised method adopted for segregating from ROM	Mechanised		Mechanised		
3i	Any analysis or beneficiation study proposed & carried out for sub-grade mineral and reject	N.A.		N.A.		
3j	Provision of drilling & blasting in mineral benches	No drilling & blasting. Eco-Friendly mining by use of rock breaker.		NA		
3k	Provision of mining machineries in mineral benches	rock breaker with combination of loader with Truck/Excavator/Dumpers		Yes		
3l	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	Yes O/B-NA Ore-3.0M		Yes O/B-NA Ore-3.0M		
3m	Total area covered under excavation/pits	0.770 Ha		Approx 0.5 Ha		
3n	Ore to OB ratio for the pit/mine during the year	1:0		1:0		
3o	Total area put in use under different heads at the end of year	Pit-0.770 Ha.		Approx 0.5 Ha		
3p	Production of ROM mineral during last five-year period, as applicable (MT)	Year	Proposed production (in ton)	Year	Achieve production (in ton)	
		2019-20	20252	2019-20	Nil	
		2020-21	5000	2020-21	Nil	
		2021-22	35000	2021-22	5135	
		2022-23	25000	2022-23	1200	
		2023-24	11482	2023-24	Nil	

3q	General remarks of inspecting officer on method of mining etc.	There is no Overburden in mining area and height of benches in mineral is suitable for method of Mining proposed in Plan.
----	--	---

4.0 Solid Waste Management-Dumping

SN	Item	Proposals (2023-24)	Actual work (2023-24)	Remarks
4a	Separate dumping of topsoil, OB & mineral reject (Rule 32, 33)	No Proposal,	No OB & mineral reject	
4b	Location of topsoil, OB & mineral reject dumps	N.A.	OB & mineral reject	
4c	Number of dumps within lease area and outside lease area	Nil	Nil	There is no Overburden in mining area.
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	N.A.	N.A.	
4e	Number of active & alive dumps	N.A.	N.A.	
4f	Number of dead dumps	N.A.	N.A.	
4g	Number of dumps stabilised	N.A.	N.A.	
4h	Whether Retaining wall or garland drain all along dumps are there	No	No	
4i	Length of Retaining wall or garland drain all along dump	N.A.	N.A.	
4j	Number of settling ponds	N.A.	N.A.	
4k	Specific comments of inspecting officer	There is no Overburden in mining area as the limestone is outcropping in the area.		

5.0 Solid Waste Management-Backfilling

SN	Item	Proposals (2023-24)	Actual work (2023-24)	Remarks
5a	Status on part or full extraction of mineral from mined out area before starting backfilling	No Proposal	NA	
5b	Area under backfilling of mined out area	NA	NA	
5c	Concurrent use of topsoil for restoration or rehabilitation of mined out area (Rule 32)	NA	NA	
5d	Total area fully reclaimed & rehabilitated	NA	NA	
5e	General remarks of inspecting officer on backfilling, reclamation etc	There is practically no soil covering in this area. So provision for separate stacking of topsoil also has not been made and area is not matured for backfilling.		

6.0 Progressive Mine Closure Plan

SN	Item	Proposals (2023-24)	Actual work (2023-24)	Remarks
6a	Whether Annual report on PMCP submitted on time and correctly - Rule 23E(2). Details should be given in the format as given in Annexure-20.	PMCP report submitted in time.	Submitted.	
6b	Management of worked/mined out benches i) Area available for rehabilitation (ha) ii) Afforestation done (ha) iii) No. of saplings planted during the year iv) Cumulative no. of plants v) Any other specific method of rehabilitation vi) Cost incurred on watch & care during the year	i) Nil Ha. ii) 0.10 Ha. iii) 50 Nos. iv) 150 Nos v) Nil vi) 5000/-	i) Nil Ha. ii) 0.01 Ha. iii) Approx 10 Nos. iv) 10 Nos. v) Nil vi) Approx. Rs. 2000/-	

6c	Compliance on reclamation and rehabilitation by backfilling i) Voids available for backfilling (L X B X D) ii) Void filled by waste/tailings iii) Afforestation on the backfilled area iv) Rehabilitation by making water reservoir v) Any other specific means	No proposed	No proposed	
6d	Compliance of Rehabilitation of waste land within lease i) Afforestation ii) Area rehabilitated (ha) iii) Method of rehabilitation	No proposed	No proposed	
6e	Compliance of Environmental monitoring (core zone & buffer zone)	Air quality monitoring was done as per CCOM's circular 3/92 during mining.	Yes	
6f	General remarks of inspecting officer on PMCP compliance & progressive	The PMCP returns are submitted on time as per the provision of Rule 26 of MCDR 2017.		

7.0 Mineral Conservation

SN	Item	Proposals (2023-24)	Actual work (2023-24)	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	Total ROM to be dispatched.	Total ROM to be dispatched.	
7b	Method of grade-wise mineral sorting i.e. manual or mechanical	NA	NA	
7c	Different grade of mineral sorted out at mines	NA	NA	
7d	Any beneficiation process at mines	NA	NA	
7e	General remarks of inspecting officer on Mineral conservation & beneficiation issues	Found Satisfactory.		

8.0 Environment

SN	Item	Proposals (2023-24)	Actual work (2023-24)	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	NA	NA	
8b	Concurrent use or storage of topsoil	NA	NA	
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	NA	NA	
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	NA	NA	
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	50 Nos of sapling to be planted every year.	Approx. 10 Nos of sapling planted up to 2023-24.	
8f	Baseline information on existence of plantation & additional plantation done (Rule 41)	NA	NA	
8g	Survival rate	As per proposal.	Approx. 50%	
8h	Water sprinkling on roads to control airborne dust	Regular water sprinkling is done on haul road and loading and unloading point.	Regular water sprinkling is done on haul road and loading and unloading point to control fugitive	

			emission.	
8i	General remarks of inspecting officer on aesthetic beauty in and around mines are	The aesthetic environment in and around lease is beautiful.		

9.0 Compliance of Rule 45

S.N	Item	COMMENTS		Remarks
	Status of submission of Online Monthly and Annual returns	M.R. Submitted up to till date - Yes A.R. submitted up to till date- Yes		
S.N	Item	Details given in A.R 2022-23 & 2023-24	Observation of I/Officer /Actual reported in Returns	Remarks
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Yes	Found in order	
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	Yes	Found in order	
9d	Scrutiny of Annual return on afforestation	Yes	Found in order	
9e	Scrutiny of Annual return on mineral reject generation (Grade & quantity)	Yes	Found in order	
9f	Scrutiny of Annual return on ROM stock and/or graded ore	Yes	Found in order	
9g	Scrutiny of Annual return on sale value, Ex. Mine price & production cost	Yes	Found in order	
9i	Scrutiny of Annual return on fixed assets	Yes	Found in order	
9k	Scrutiny of Annual return on mining machineries	Yes	Found in order	

10- Details of violations observed during current inspection and compliance position of earlier violation pointed out:-

Jigneshkumar Parmar
Assistant Mining Engineer
