

भारत सरकार / GOVERNMENT OF INDIA
खान मंत्रालय / MINISTRY OF MINES
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES,
DEHRADUN

File No.: MCDR-MiFL0LST/16/2022-DDN-IBM_RO_DDN

Date : 11/05/2026

To: Shri/M/s. Mr Vinod Bahety, Nominated
 Owner, ACC Limited, Adani Corporate
 House, Shantigram ,SG Highway, Khodiyar,
 Khodiyar, Gandhinagar, Gandhinagar,
 Barmana (128) Village & Mandal, Bilaspur
 district, Himachal Pradesh,- 382421

Subject: Violation of provision of Mineral Conservation and Development Rules, 2017 in respect of your GAGAL(38HPR01003) over an extent of 334.25 ha in Barmana (128) in DEHRADUN, Bilaspur, Himachal Pradesh

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated during inspection of the above mine on 18.03.2026 by undersigned accompanied by Shri Sanjeev Soni, Mines Manager.

Summary of Violations :

| Items for Reporting | As Per Plan | Actual | Deviation | Rule | Reason |
|---------------------|------------------------------|---------------------------|---|-------------|--------|
| Rule 11(1) | 410m Retaining wall proposed | only 90 meter constructed | During mine visit it was observed that low grade stack is very near to lease boundary(BP 13,14,15,16) but still no protective measures taken to stabilised or protect the rolling of material from dump. | Rule 11(1), | |

इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनन संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है। एवम इस नियम का उल्लंघन की अनुपालना नहीं होने पर खनन संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) के अंतर्गत (क) खान की सारी खनन संक्रियाएं बंद की जा सकती है। (ख) आपके विरुद्ध अभियोग दायर किया जा सकता है। (ग) खनन पट्टे को नरिस्त करने की सफारिस राज्य सरकार से की जा सकती है। अतः आपको सलाह दी जाती है कि

आप उपरोक्त उल्लंघनो का अतशुधिर सुधर करे एवम इसके सुधर की सूचना इस पत्र के जारी होने से 45 दिन के भतिर इस कार्यालय को सूचति करे।

Yours faithfully,

(RAJESH DAS RO DEHRADUN, DEHRADUN)
DCOM

1. The Controller of Mines (NZ), Indian Bureau of Mines, Udaipur. (udaipur@ibm.gov.in)
2. The Director, Directorate of Industries, H.P. Government, Udyog Bhawan, Bemloe, Shimla, H.P. – 171001.
(geologicalwing@gmail.com)
3. MCDR File

Esined by: RAJESH DAS
Date: 19/05/2026 12:21:31 PM