

भारत सरकार / GOVERNMENT OF INDIA
खान मंत्रालय / MINISTRY OF MINES
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES,
DEHRADUN

File No.: MCDR-MiFL0QU/1/2026-DDN-IBM_RO_DDN

Date : 20/05/2026

To: Shri/M/s. N/A, Nominated Owner,
 Manmohan, House No. 196-P ,HUDA
 Sector - 1, Narnaul, Bayal (258) Village &
 Mandal, Mahendragarh district, Haryana,-
 123001

Subject: Violation of provision of Mineral Conservation and Development Rules, 2017 in respect of your Bayal Quartz & Feldspar Mine having mine code 49HRN58001 over an extent of 76.75 ha in Bayal Village, Mahendragarh District, Haryana

The following provision of the MCDR, 2017, were found violated in your above mine during the inspection on 21/04/2026 by undersigned in presence of mine official Mr Abhishek Sharma, Owner's Representative, Mr D C Yadav, Geologist & Mr Sananand Behera, Mining Engineer:

Summary of Violations :

Items for Reporting	As Per Plan	Actual	Deviation	Rule	Reason
Number of active & Inative dumps	3 active dumps, no inactive dump proposed	4 active dumps, no inactive dump observed	Number of dumps not tallying with proposals made in approved mining plan	Rule 11(1),	Number of dumps not tallying with proposals made in approved mining plan
Location of Topsoil, OB/Waste, Mineral Reject dumps, Tailings and Fines	Waste Dump - 1 in Southern side of South Block, Waste Dump - 2 in northern side of South Block, Top soil dump - North-Western portion of South Block	Waste Dump - 1 in Southern side of North Block, Waste Dump - 2 in northern side of South Block, Waste Dump - 3 in the western side of South	Dumps were found not located as locations proposed in the approved mining plan.	Rule 11(1),	Dumps were found not located as locations proposed in the approved mining plan.

		Block, Top soil dump - North of Waste Dump-3 in South Block			
Separate dumping of topsoil, OB & mineral rejects, fines, tailings (Rule 36,37)	Separate dumping of TS & OB proposed	Separate dumping of TS & OB carried out. However, the OB & Top soil dump were found to have been merged.	Separation must be maintained in between OB & Top soil dumps	Rule 11(1),	Separation must be maintained in between OB & Top soil dumps
Whether height of benches in Overburden & mineral suitable for method of mining proposed in mining plan	10 m high & wide benches proposed	Benches as high as 20 metres were observed along the South Eastern portion of the South Block of the mine	Bench heights must be restricted to proposals made in approved mining plan	Rule 11(1),	Bench heights must be restricted to proposals made in approved mining plan
Quantity of ROM mineral production proposed (in T)	Quartz - 5,00,000; Feldspar - 3,00,000; Quartzite/Stone - 46,64,000; Total - 54,64,000	Quartz - 19,872.25; Feldspar - 11,796.99, Quartzite - 2,706,427.26; Stone - 1,454,170.77; Total - 41,92,267.27	Quartz & Feldspar production was significantly lower than proposals	Rule 11(1),	Development proposals not achieved during the FY.
Number of pits / Blocks proposed for production	3 pits in 2 blocks proposed	2 pits in 2 blocks worked	Deviations in lateral & vertical extents of mining from proposals in the approved mining plan.	Rule 11(1),	Development proposals not achieved during the FY.
Location of development w.r.t. lease area	Pit 1- Northern portion of North Block - 435 to 295 mRL; Pit 2 - Southern portion of North Block - 363-303 mRL; Pit 3 - South Block - 426 - 336 mRL	Pit 1 - 435 to 336 mRL; Pit 2 - No working; Pit 3 - 426 - 336 mRL	Deviations in lateral & vertical extents of mining from proposals in the approved mining plan.	Rule 11(1),	Development proposals not achieved during the FY.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62(1) of Mineral Conservation and Development (Amendment) Rules, 2021, with imprisonment for a term which may extend to two years or with fine which may extend to rupees five lakhs, or with both, and in the case of a continuing contravention, with additional fine which may extend to rupees fifty thousand for every day during which such contravention continues after conviction for the first such contravention. 03. The mining operation can be suspended under Rule 11(2), if the compliance of Rule 11(1) is not found satisfactory. 04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty five) days from the date of issue of this letter.

Yours faithfully,

(Matiul Islam, DEHRADUN)
Sr ACOM

1. The Controller of Mines (NZ), Indian Bureau of Mines, Udaipur. (zo.udaipur@ibm.gov.in)
2. The Director General, Directorate of Mines & Geology, Panchkula, Harayana (dmg.mines-hry@nic.in; me.mines-hry@nic.in)
3. The Director(Mining), Directorate General of Mines Safety, Ghaziabad Region (mbidari@dgms.gov.in)

Signed by: Matiul Date: 25/05/2026 03:06:20 PM
