

भारत सरकार / GOVERNMENT OF INDIA
खान मंत्रालय / MINISTRY OF MINES
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES,
DEHRADUN

File No.: MCDR-MiFL0LST/27/2023-DDN-IBM_RO_DDN

Date : 15/05/2026

To: Shri/M/s. Mr MOINUDDIN Sheikh,
 Nominated Owner, A.Dean & co, H no 12
 ,Gandhi Road, Dehradun, Chitli (244)
 Village & Mandal, Sirmaur district,
 Himachal Pradesh,- 248001

Subject: Violation of provision of Mineral Conservation and Development Riles, 2017 in respect of your 38HPR10021(38HPR10021) over an extent of 4.4 ha in Chitli (244) in , Sirmaur, Himachal Pradesh

Sir, The above mine was inspected on 29.04.2026 by the undersigned in the presence of Shri S N Pandey, Mine Manager and Shri Attar Singh, Agent, during the inspection, the following provisions of the Mineral Conservation and Development Rules, 2017 were found to be violated.

Summary of Violations :

Items for Reporting	As Per Plan	Actual	Deviation	Rule	Reason
Progressive Mine Closure Plan: Compliance on reclamation and rehabilitation by backfilling/Other means Total area and numbers of plantation proposed.	Plantation : Location :Pamta Chitli block SBZ, Area : 0.07, No. of Plant : 100 Plantation : Location :Pamta Chitli block SBZ, Area : 0.09, No. of Plant : 100	no new plantation has been done during the reporting year.	yes	Rule 11(1),	
Exploitation - Opencast Mine: Whether height of benches in Overburden& mineral suitable for method of mining proposed in mining plan	6 m	no bench has been seen during the inspection	yes	Rule 11(1),	Violation has been pointed out for not carrying out scientific mining as per the proposals in the approved Mining Plan. during the inspection steep cliff has been seen. The lessee is required to undertake corrective measures to reduce the height of the cliff in order to form the benches as per the approved mining plan.
Development - Opencast: Location of development	Pit : PP-2 & Direction :	In pit PP-2 developmen	Yes	Rule 11(1),	

w.r.t. lease area	E, Pit : PC-1 & Direction : E	ts of 2 benches have been proposed- Bench-I RL 1567- 1561 Bench-II RL 1561- 1556, No bench has been seen during the inspection. In pit PC-1 developmen ts of 2 benches have been proposed- Bench-I RL 1571- 1565 Bench-II RL 1565- 1559- No bench has been seen during the inspection			
Exploration: Number of Core Boreholes	No borehole proposed	7 boreholes have been proposed during the year 2024-25 however no borehole have been done till date	yes	Rule 11(1),	During the inspection, it was observed that no boreholes have been drilled to upgrade the mineralized area to the G1 level of exploration, as stipulated in the approved Mining Plan.

1) In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017. 2) The mining operations can be suspended under the rule 11(2) of MCDR-2017, if compliance of rule 11(1) of MCDR-2017 is not found satisfactory. 3) You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

Yours faithfully,

(NITIN SINGH, DEHRADUN)
JMG

Copy for information to:

- (i) The Controller of Mines (North Zone), Indian Bureau of Mines, Udaipur.
- (ii) The Director of Mines Safety, Srinagar.
- (iii) The Director, Geological wing, Deptt of Industries, Himachal Pradesh (K.A- State Geologist).

Esigned by: NITIN
Date: 19/05/2026 12:34:22 PM