



भारत सरकार/ GOVERNMENT OF INDIA
खान मंत्रालय/ MINISTRY OF MINES
भारतीय खान ब्यूरो/ INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय/
OFFICE OF REGIONAL CONTROLLER OF MINES



फैक्स: (080) 23371027 / 23373287

दूरभाष: 080-23371027 / 23375366/67

Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब ॥ स्टेज,, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर,
बेंगलुरु -560022

सं. / No. KNT/BLR/FE/408/BNG/VOL-II

दिनांक/Date: 09/09/2022

सेवा में/ To,

Sri. Shantesh Gureddi, Nominated Owner,
M/s. Sri Kumaraswamy Mineral Exports Pvt. Ltd.,
No.462, 14th Ward, SMIORE Colony,
Near Fire Station,
Sandur-583 119, Karnataka.
riom@skmepl.co / nishantnatiye2001@gmail.com

विषय/Subject: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your **Ramanadurga Iron ore Mine (ML No. 2141) having Mine code: 30KAR03101,** over an area of **59.36 Ha** (as per CEC) in Ramanadurga Range (Yeshwanthnagar village), Sandur Taluk, Ballari District, Karnataka state.

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection carried out by the undersigned along with Sri. H.M.Shivakumar-Assistant Mining Engineer in presence of Sri. Nishanth Bhanudas Natiye - Mines Manager & Sri Govinda Rao- Mining Engineer on 23/08/2022.

Rule	Nature of violations observed
Rule 45(7)	<p>(i) As part -II A 1. (i) of the Annual Returns submitted for FY 2021-22, Capital Structure- value of Land given is incorrect as the entire Mining Lease area falls under Forest Area.</p> <p>(ii) As part -II A 1. (iv) of the Annual Returns submitted, Capitalised Expenditure such as pre-production exploration is not accounted for the exploration carried out during the year.</p> <p>(iii) As part -III-5 of the Annual Returns, Taxes and Cesses: the Amount of DMF and NMET contributions made during the year should be reflected under "(iii)(c) -others-specify". Accordingly part VII for Cost of Production per tonne be corrected including Royalty, DMF & NMET.</p> <p>(iv) Part - V: General Geology & Mining (Sec 1/2 for Iron Ore): Under 4.2 (C) open cast Mining operations during the year: Total quantity of Overburden/Waste removed during the year (tonnes) is shown as '0' is incorrect.</p> <p>(v) As per part VII of the Annual Returns submitted, DMF & NMET paid details have not been furnished and accounted for arriving at the cost of Production.</p>

सं. / No. KNT/BLR/FE/408/BNG/VOL-II

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

(सुरेश प्रसाद/Suresh Prasad)

क्षेत्रीयखाननियंत्रक/Regional Controller of Mines
भारतीयखानब्यूरो/Indian Bureau of Mines

प्रतिलिपिसूचनार्थ /Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khanija bhavan, R.C. Road, Bangalore-560 001.

(सुरेश प्रसाद/Suresh Prasad)

क्षेत्रीयखाननियंत्रक/Regional Controller of Mines
भारतीयखानब्यूरो/Indian Bureau of Mines