

Government of India
Ministry of Mines
Indian Bureau of Mines
Office of the Regional Controller of Mines, Jabalpur

File No.: M.P/SATNA/LST-296 Mine Code -38MPR35230 Jabalpur, Dated: 24.11.2021

To,

6287-6288
Shri Sanjeev Beri (Director),
M/s S N S (Minerals) Limited,
Tilaura limestone Mine,
Sunderson House, Rewa Road, N H -7, Maihar,
Distt – Satna (M.P.)
Email – snsahr@gmail.com

Subject: Violation of provisions of provisions of Mineral Conservation & Development Rules, 2017 in respect of your **Tilaura Limestone Mine (3.774 Hect.)** in **Satna** district of **M.P. State**.

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mentioned mine during the inspection by Shri Abhishek Ranjan Gautam, Assistant Mining Engineer on 08.11.2021 in presence of Shri. Kumar Shyamal Kishor, Manager as under:-

नियम स.	पाए गए उल्लंघन की विस्तृत प्रकृति
Rule 11 (1)	<p>According to this rule-No holder of a mining lease shall commence or carry out mining operation in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Govt. pursuant to the provisions to clause (b) of Sub Section (2) of Section 5 or approved by the competent authority of the Atomic Minerals Directorate for exploration and Researching respect of minerals specified in Part B of the First Schedule of the Act where the grade of such atomic minerals is equal to or above the threshold value limit declared under schedule-A of the Atomic Mineral Concession Rules 2016.</p> <p>The Review of Mining Plan of above mentioned mine was approved vide this office letter No-MP/SATNA/LST/RMP-49/2019-20 dated 30.06.2020 incorporating the proposals of working from 2020-21 to 2024-25. During the inspection it was found that following provisions of rule have been violated.</p> <ol style="list-style-type: none"> It was proposed to remove 920 cubic meter of over burden in the year 2020-21 but the mine development was not done as per the approved proposal. Backfilling & plantation is not done within 7.5m barrier zone as per the approved proposal. Boundary pillars are not maintained properly as per rule.
Rule 46	<p>The holder of the prospecting license or prospecting license cum mining lease or the mining lease shall,— when any new appointment of an agent, mining engineer, geologist or any person is made under sub-rule (1) of rule 55; or (b) when the employment of any such person is terminated or any such person leaves the said employment; or (c) when any change occurs in the address of any such person, within fifteen days from the date of such appointment, termination, leaving or change in address, give a notice in Form H of the Schedule to the authorised officer, as the case may be.</p> <p>During the inspection it was found mine Geologist and Mining engineer were appointed in the mine but intimation of their appointments were not sent to the Regional Controller of Mine, Jabalpur till the date of inspection.</p>

File No.: M.P/SATNA/LST-296

01. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR-2017.
02. Non-compliance of the rule 11(1) of MCDR-2017 may lead to suspension of Mining operations under the provisions of rule 11(2) and 35(4) of MCDR-2017.
03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

भवदीय
(नरेश कुमार कटारिया)
24/11/21
उप खान नियंत्रक
भारतीय खान ब्यूरो

NOO:

प्रतिलिपि प्रेषित ::

01. The Director of Geology & Mining, Govt. of Madhya Pradesh, Khanij Bhavan, 29-A, Arera Hills, Bhopal(M.P.) for information and further necessary action.
02. The District Collector, Satna (M.P.) for information.

(नरेश कुमार कटारिया)
24/11/21
उप खान नियंत्रक
भारतीय खान ब्यूरो

प्रतिलिपिप्रेषित :

खान नियंत्रक (मध्य), भारतीय खान ब्यूरो, नागपुर को सूचनार्थ प्रेषित। (ईमेल)

(नरेश कुमार कटारिया)
24/11/21
उप खान नियंत्रक
भारतीय खान ब्यूरो

पता : योजनाक्रमांक 11, कमलानेहरु नगर, जबलपुर 482002 (मध्य) / फोन 2416780 / 2416589 / 2416231 फैक्स 0761- 2416780
Address : Scheme No 11, Kamla Nehru Nagar, Jabalpur 482002 (M.P) Phone 2416780 / 2416589 241631 Fax : (0761) 2416780 E Mail :
ro.jabalpur@ibm.gov.in

~~उत्तर~~
les