



**GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
OFFICE OF THE REGIONAL CONTROLLER OF MINES**



Tel No.080 23371027
Fax No.080 23373287
Email ID: ro.bangalore@ibm.gov.in, rcombng@rediffmail.com

29, Industrial Suburb, IInd Stage
Tumkur Road, Goruguntapalya
Yeshwantpur, Bangalore-560022

.No. IBM/BLR/Fe/52/BNG/Vol. VI/2015/

Dated: 04th Dec; 2015

Shri PV Prakash,
M/s PB Shetty & Sons,
#PB No. 03, Hampi Road,
HOSPET – 583 201
Distt. Bellary (Karnataka)

Fax : 08394-226555

Subject:- Violation of provisions of MCDR 1988 in respect of Karadikola (Suresh) Iron Ore Mine (ML No. 2502) over an extent of 42.11 hectares in Bellary District.....reg.

Dear Sir,

The following provisions of the Mineral Conservation & Development Rules 1988 were found violated in above mine during the inspection conducted by the undersigned in presence of Shri YV Ramakrishna Reddy, Mines Manager on dated 14.11.2015.

Rule 13(1)	Scheme of Mining was approved vide letter No. KNT/GLB/MS/Lst-193-SZ/236 dated 28.03.2013. The deviations observed in mining operations vis-a-vis approved document are given below:- (i) The mineral stock is lying at number of places also in addition to the earmarked place. (ii) Environment data's are not being maintained in a bound paged register.
Rule 21	The HEMM equipment wise log book in respect of each machine as per the provisions under the rule has not found maintained.
Rule 48	The particulars of boreholes drilled are not being maintained in a bound paged register as per form-K, as required under the rule.

02. In this connection, it is to bring to your notice that the above violations constitute an offence punishable under Rule 58 of MCDR 1988. Further, the violation of Rule 13(1) of MCDR may also attract provision of Rule 13(2) of MCDR 1988 regarding suspension of mining operations till the compliance of the violations.
03. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (forty five) days from the date of issue of this letter.

Yours faithfully,

Sd/-
(**Pukhraj Nenival**)
Dy. Controller of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), IBM, Bangalore.
2. The Director, Dept. of Mines & Geology, Govt. of Karnataka, Khanij Bhavan, Race Course Road, Bangalore 560 001.

Sd/-
(**Pukhraj Nenival**)
Dy. Controller of Mines