

GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
Office of the Regional Controller of Mines, Hyderabad

No. APVZNR/Mn-22/Hyd

603, 6th Floor, CGO Towers,
Kavadiguda, Secunderabad
Date:15/6/2017

To
Sri Manavendra Mor,
Nominated Owner,
M/s RBSSD & FN Das,
P.O.Sreeram Nagar,Garividi R.S.,
Vizianagaram District-535101,
Andhra Pradesh.

Sub: Violation of provisions of MCDR, 2017 in respect of Garividi Manganese mine over an area of 21.587 ha in Garividi Village & Mandal, Vizianagaram District, AP State.

Sir,
The following provisions of Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection on 25.5.2017 by Shri M.Pratap Reddy AMG in the presence of Sri P.S.K.Kishore, Mines Manager (Mines).

Rule No.	Nature of Violation
11(1)	The following mining operations carried in the mine were not in accordance with the approved document vide this Office Ir.vo.AP/VZNR/MS/Mn-105/Hyd dated 3.6.2015 and there by violating the provisions of MCDR 2017: “Against proposal of drilling 8 Boreholes in the year 2015-16, no such exploration has been carried out so far as proposed vide Para 1(I)) of approved document.”
26(2)	The owner ,agent, manager or mining engineer shall submit to the Regional Controller of Mines, a yearly report before 1 st July of every year setting forth extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan, and if there is any deviation ,reasons thereof. But the same not submitted in this office for 2015-16.
28 (1)	During the Inspection, it was found that the work in the mine is discontinued for a period exceeding ninety days, but notice thereof in Form-E as required under this Rule has not been submitted to the Regional Controller of Mines, Indian Bureau of Mines, Hyderabad so far.

02. In this connection, it is brought to your notice that the above said violations constitute an offence punishable under Rule-62 of MCDR, 2017. Besides, inability to comply the provision of Rules 11(1) is also liable for suspension of mining operations under the provision of Rule 11(2) of MCDR, 2017.

03. You are advised to rectify the above violations immediately and intimate the position to this office within forty five days from the date of issue of this letter.

Yours faithfully,

(Manish K Maindiratta)
Deputy Controller of Mines

मूल प्रति पर नहीं/Not on the Original:

1. खान नियंत्रक (द),भारतीय खान ब्यूरो, बेंगलोर को प्रतिलिपि सूचनार्थ अग्रेषित।
2. निदेशक, खान एवं भूविज्ञान विभाग, तेलंगाना सरकार, हैदराबाद।
3. The ADMG, Vizinagaram District, Andhra Pradesh.

(मनीष के मेन्दीरत्ता)
उप खान नियंत्रक।