



**GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
OFFICE OF THE REGIONAL CONTROLLER OF MINES**



Tel No.080 23371027
Fax No.080 23373287
Email ID: ro.bangalore@ibm.gov.in, rcombng@rediffmail.com

29, Industrial Suburb, IInd Stage
Tumkur Road, Goruguntapalya
Yeshwantpur, Bangalore-560022

No. KNT/BLR/FE-403/BNG/

Dated: 01st July 2015

To
Shri Faisal Sareef,
M/s Nadeem Minerals,
'Alfa Manor' No. 227,
1st Floor, Greenglen Layout,
Off Outer Ringroad, Bellandur,
Varthur Hobli, **Bengaluru** - 103

Fax: 080-41105775

Subject:- Violation of provisions of MCDR 1988 in respect of your Donimalai Iron Ore Mine (ML No. 2526) over an extent of 52.82 hectares (As per CEC Survey) in Sandur Taluk of Bellary District (Karnataka).....reg.

Dear Sir,

The following provisions of the Mineral Conservation & Development Rules 1988 were found violated in above mine during the inspection conducted by the undersigned in presence of Shri Bharthidasan, Mines Manager on dated 18.06.2015.

Rule 13(1)	Modifications in the Scheme of Mining was approved vide letter No. 279/591/97/BNG dated 23.04.2014. The deviations observed in mining operations vis-a-vis approved document are given below: (i) The development work carried out is 4.55 Lakh Tonnes against the proposals of 5.47 Lakh Tonnes, distorting the stripping ratio to 1:1.11 from proposal of 1:1.33. (ii) Due to lagging behind in development work, High wall benches are created in the Northern pit. (iii) In para 4.2, it was proposed to drill total 10 nos. (total 886 mtrs) of RC bore holes during 2014-15, but the drilling has not been carried out so far.
Rule 42(i)(c)	Every holder of a mining lease shall employ a whole time Geologist also but was not employed.

02. In this connection, it is to bring to your notice that the above violations constitute an offence punishable under Rule 58 of MCDR 1988. Further, the violation of Rule 13(1) of MCDR may also attract provision of Rule 13(2) of MCDR 1988 regarding suspension of mining operations till the compliance of the violations.

P.T.O.

03. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (forty five) days from the date of issue of this letter.

Yours faithfully,

Sd/-
(Pukhraj Nenival)
Dy. Controller of Mines

Copy for kind information to :

1. The Controller of Mines (SZ), IBM, Bangalore.
2. The Director, Dept. of Mines & Geology, Govt. of Karnataka, Khanij Bhavan, Race Course Road, Bangalore 560 001.

Sd/-
(Pukhraj Nenival)
Dy. Controller of Mines