



भारत सरकार Government of India

खान मंत्रालय Ministry of Mines

भारतीय खान ब्यूरो Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines

100, ओल्डनेहरू कालोनी, देहरादून (उत्तराखंड) 248001 / 100 Old Nehru Colony, Dehradun (U.K.)248001

TEL- 0135-2676350 / 2671896, E-mail – ro.dehradun@ibm.gov.in



फाईल संख्या File No: HP/SRM/LST- 24

Mine Code: 38HPR10008

दिनांक, 03, October 2022

सेवा में To : मैसर्स जय सिंह ठाकुर एण्ड संस,
बोहार चूनापत्थर खान,
निवास- 119/10 देवी नगर,
पांवटा साहिब, जिला-सिरमौर, हि.प्र.

E-mail: akchhabra2005@yahoo.com

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Bohar Limestone Mine, Mining Lease over an area of 4.15ha located near Village –Bohar, Tehsil- Paonta Sahib, District- Sirmour H.P State.

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection made by the undersigned along with SMG on 14.09.2022 in the presence of Shri.Ashok Das Mine Manager and Mr. A K Chhabra, Owner Representative.

RULE NO.	NATURE OF VIOLATION OBSERVED
11(1)	Mining Operation has not been carried out in accordance with the approved Review and Updation of Mining Plan of vide letter no. 614(2)/MP-B-237/06-DDN dated 31-03-2020 to the following extent: a) In the PMCP proposal: (i) Total 65 meters long wire crated gravity wall at the base of the dump along with boundary pillars BP-1, BP-2 to BP-3 was proposed but during inspection same was not found. (ii) On page 48, as per proposal 125 no.s plantation proposed during year 2022-2023 but no plantation was carried out. (iii) On page 48, as per proposal 100meter fencing and 90meter parapet wall around the plantation area but no such fencing and parapet wall constructed. (iv) On page protective and stabilization measures proposed to prevent rolling of rocks and flow of wash off material but such protective measures not observed during inspection.
Rule 33	The holder of a mining lease shall, on or before the 30th day of June every year submit to the authorized officer, as the case may be, and the State Government, a digital copy along with a print copy of the surface geological plans and sections maintained under rule 32. In your case it is found that you have not submitted updated plan and sections till the date of inspection.
Rule 42	Restoration of flora. – Every holder of prospecting license, prospecting license cum mining lease or a mining lease shall carry out prospecting or mining operations, as the case may be, in accordance with applicable laws and in such a manner so as to cause least damage to the flora of the area held under prospecting license, prospecting license cum mining lease or mining lease and the nearby areas. In your case it is observed that as per proposed in the PMCP chapter you have not done / achieved the proposed plantation and survival rate of the plantation is too low.
34A(2)	Every lessee, other than those covered under sub-rule (1), shall submit soft copy of high resolution Geo-referenced Ortho-rectified Multispectral satellite images of the leased area and upto hundred metres outside the lease boundary taken in the month of April to June of every year, to the Controller General on or before 1st day of July of the that year in the standards formats such as GeoTIFF along with metadata or any other format as may be specified by the Indian Bureau of Mines in this regard: On perusal of office records, it is observed that desired output image in a specified format has not been submitted to the competent authority by the holder of the lease in the prescribed till date

- इस संबंध में, यह आपके संज्ञान में लाया जाता है कि नियम 11(1), 33 और 34A(2) और 42 का उल्लंघन नियम 62(1) के तहत दंडनीय अपराध है।
- एमसीडीआर 2017 के नियम/उप नियम 11(1) का पालन न करने की स्थिति में नियम 11(2) के तहत खनन कार्य को निलंबित भी किया जा सकता है।

जायस

4. आपको सलाह दी जाती है कि उपरोक्त उल्लंघनों में तत्काल सुधार करें और इस पत्र के जारी होने की तारीख से 45 दिनों के भीतर इस कार्यालय को अनुपालन स्थिति से अवगत कराएं।

भवदीय Yours faithfully

दामोदर
03.10.2022

(दामोदर प्रसाद शर्मा /D P Sharma)

सहायक खान नियंत्रक /Assistant Controller of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- 2- निदेशक उद्योग निदेशालय, हि0 प्र0 सरकार, उद्योग भवन, शिमला (हि0 प्र0). (geologicalwing@gmail.com)
- 3- गार्ड फाइल

सहायक खान नियंत्रक /Assistant Controller of Mines