

I/19770/2023

भारत सरकार

खान मंत्रालय

भारतीय खान ब्यूरो

क्षेत्रीय खान नियंत्रक का कार्यालय

कर्मयोगी भवन, चतुर्थ माला, ब्लॉक-2, सी

विंग, सेक्टर-10A गांधीनगर, गुजरात, 382010



Government of India

Ministry of Mines

Indian Bureau of Mines

Office of Regional Controller of Mines  
Karmayogi Bhavan, 4<sup>th</sup> Floor, Block-2, Sector10A,

Gandhinagar, Gujarat-382010

Tel- 079 29750358 /29750359; ई -मेल/E-mail:ro.gandhinagar@ibm.gov.in

फाईलसंख्या/File No MCDR-MiFLOLST/273/2022-GNR-IBM\_RO\_GNR  
38GUJ13002

ID- दिनांक: .11.2023

RJK/LST-002

सेवामेंTo : Owner/Agent/Manager/Mining Engineer  
प्रेषित: Sh. Hardashbhai Govindbhai Bhimbha  
Village- Tanasva, TA.- Upleta,  
Dist.- Rajkot, Gujarat-360490

E-mail: [hardashbhaibhimbha@gmail.com](mailto:hardashbhaibhimbha@gmail.com),  
[kanaiyatransport@gmail.com](mailto:kanaiyatransport@gmail.com)

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Vadekhan Limestone Mine{81/p} over an area of 4.00 ha. located near Village- Vadekhan, Tehsil- Upaleta, District-Rajkot in Gujarat.

महोदय,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection carried out by Sh. Snehalkumar Patel, AME on 06/09/2023 in the presence of your representative Shri. Hardashbhai Govindbhai Bhimbha & Team.

RULE NO.	NATURE OF VIOLATION OBSERVED
11(1)	The Mining operation are being carried out in violation of the following provision of the approved mining plan, which was approved vide letter no. 684(4)(1)/MP-334/2021-22-GNR Dated-17-08-2021 for the period 2021-22 to 2023-24. (a) It was proposed that in the year 2022-23, Plantation of plants were proposed as 150 and Fencing was proposed as 950m., however, it was observed that the above proposals were not carried out as proposed in the approved Review of Mining Plan. (b) Proposed bench height given 3M, however, it was observed that the bench height is approx. 8-9 m & all bench/pits are in irregular shape & height.

- इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है।
- खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम संख्या 11(1) तथा अन्य नियमों की पालना नहीं होने से व्यवस्थित एवं वैज्ञानिक तरीके से खनन पर विपरीत प्रभाव पड़ता है। अतः उपरोक्त नियमों की पालना नहीं करने पर नियम 11(2) के अंतर्गत खनन क्रियाएं स्थगित (निलंबित) की जा सकती हैं अथवा राज्य सरकार को उचित कार्यवाही करने की अनुशंसा भी की जा सकती है।
- अतः आपको निर्देशित किया जाता है कि आप उपरोक्त उल्लंघनों का अति शीघ्र सुधार कर इसके सुधार की स्थिति की सूचना इस पत्र के जारी होने की तिथि से 45 (पैंतालिस) दिनों के भीतर इस कार्यालय को प्रेषित करें।
- यह उल्लंघन पत्र क्षेत्रीय खान नियंत्रक के अनुमोदन पश्चात जारी किया जा रहा है।

भवदीय Yours faithfully,

(मनीष गुप्ता /Manish Gupta)

सहायक खान नियंत्रक/Assistant Controller of Mines

प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाई हेतु प्रेषित :-

- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर।([zo.udaipur@ibm.gov.in](mailto:zo.udaipur@ibm.gov.in))
- आयुक्त, भूविज्ञान एवं खनन, निदेशालय, गुजरात को सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित ।  
([cgm@gujarat.gov.in](mailto:cgm@gujarat.gov.in))
- MCDR/गाई फाइल

सहायक खान नियंत्रक/Assistant Controller of Mines

Violation 38GUJ13002

Page 1 of 1