

1



भारत सरकार GOVERNMENT OF INDIA
खान मंत्रालय MINISTRY OF MINES
भारतीय खान ब्यूरो INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक के कार्यालय
OFFICE OF THE REGIONAL
CONTROLLER OF MINES



BY REGD POST A/
D

Phone: 0674-2352463
Tele Fax: 0674-2352490
E-mail: ro.bhubaneshwar@ibm.gov.in

Plot No.149, Pokhariput
BHUBANESWAR-751020

दिनांक -
04/12/2024

प्रेषित- Shri Gajraj Singh Rathore, Nominated Owner
M/s JSW Steel Limited.
Plot No.15, Bhusgaon,
At-Bhadrasi, PS-Barbil,
Dist. Keonjhar-758035 Email:gajraj.rathore@jsw.in,
विषय- ओडिशा राज्य के सुंदरगढ़ जिले में स्थित आपकी गोरुमहिसानी लौह अयस्क खदानखदान 776.96 हे० में खनिज संरक्षण एवं विकास नियमावली 2017 के नियमों के उल्लंघन के संबंध में-
महोदय

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated during inspection of the above mine on 07.11.2024 by undersigned accompanied by Shri Ram Shankar Sharma(Agent) & Shri Padmaraja Tumati, QP.

Rule	Nature of Violation observed
11(1)	Mining operations should have been undertaken in accordance with the Mining Plan/ Review of Mining Plan. The Modified Mining Plan was approved vide letter no. MPM/A/03-ORI/BHU/ 2021-22/251dated 31.05.2021 and following deviation was observed during inspection 1. In last plan period 2021-22 exploration proposal given for 105 nos of bore holes but till 2023-24 only 61 bore holes reported. 2. The production proposed for 2023-24 was given 14.998 million tons Iron ore and against which only 4.232323 million tons of Iron ore production reported which was only 28% of the proposal. 3. The OB generation for 2023-24 proposed 1833187 m3 but only 433476 OB generations reported. 4. The production was proposed in 5 pit but actually not done as per proposal. The kanusahi pit not developed and MDH quarry work beyond proposal in eastern direction. The dumping also not done as per proposal and in katasahi dump coir matting proposal given not done.
45(5)(c)	While scrutiny of Annual returns'24 few discrepancies observed 1. It was observed the ex-mine price of fines of 55-58% FE is more than the fines of 58-60%FE, 60-62%Fe & 62-65% Fe.. 2. The Ex-mine price of 55-58%Fe fines is nearly same of below 60%Fe CLO.

- 2 इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है। एवम इस नियम का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) एवम 45(7)(क) के अंतर्गत
(क) खान की सारी खनन संक्रियाएं बंद की जा सकती है।
(ख) आपके विरुद्ध अभियोग दायर किया जा सकता है।
(ग) खनन पट्टे को निरस्त करने की सिफारिस राज्य सरकार से की जा सकती है।
3 अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का अतिशिघ्र सुधार करें एवम इसके सुधार की सूचना इस पत्र के जारी होने से 45 दिन के भीतर इस कार्यालय को सूचित करें।

भवदीय

(राजेश कुमार दास)
उप खान नियंत्रक

भारतीय खान ब्यूरो, भुवनेश्वर

Copy forwarded for kind information to:

- (1) The Director of Mines, Directorate of Mines, Government of Odisha, Heads of Department Building, Bhubaneswar-751 001
- (2) The Controller of Mines (EZ), Indian Bureau of Mines, CP-13, Sector V Salt Lake City, Kolkata- 700 091.

(राजेश कुमार दास)

उप खान नियंत्रक

भारतीय खान ब्यूरो, भुवनेश्वर