

भारत सरकार  
खान मंत्रालय  
भारतीय खान ब्यूरो  
क्षेत्रीय खान नियंत्रक कार्यालय  
कर्मयोगी भवन, चतुर्थ माला, ब्लॉक-2, सी विंग,  
सेक्टर-10A, गांधीनगर, गुजरात, 382010



Government of India  
Ministry of Mines  
Indian Bureau of Mines  
Office of Regional Controller of Mines  
Karmayogi Bhavan, 4<sup>th</sup> Floor, Block-2, C Wing, Sec 10A  
Gandhinagar, Gujarat-382010

Tel- 079 29750358 /29750359; ई-मेल/ E-mail: ro.gandhinagar@ibm.gov.in

File No:- JMNG/LST-054

Computer No. \_\_\_\_\_

Date:-

प्रेषित/To :

Chandradev Prakash Thakore  
Thakore Farm N.H 8b  
Dhoraji Road Near Upleta Bye Pass Board,  
Upleta, Rajkot  
Gujarat- 360490

Email:- [chandradevthakore@gmail.com](mailto:chandradevthakore@gmail.com)

**Sub;** Violation of provisions of Mineral Conservation and Development Rules, 2017, in respect to Malavada Limestone Mines (4.90 hectare) Mine Code 38GUJ07077 in District Jamnagar of Gujarat State.

महोदय/ महोदया, Sir/Madam,

The undersigned has inspected your aforesaid mine in the presence of Chandradev Prakash Thakore along with C.M. Dwivedi(QP ) on 15-10-2024 Following provisions of MCDR 2017 were found violated in your mines at the time of inspection.

नियम सं.	पाए गए उल्लंघन की विस्तृत प्रकृति																								
34(A)	<p>Every lessee having-</p> <p>(a) an annual excavation plan of one million tonne or more in a particular year; or</p> <p>(b) leased area of fifty hectare or more, shall carry out a drone survey of the leased area and up to hundred meters outside the lease boundary in the month of April or May every year and submit the processed output [digital elevation model (DEM) and Orthomosaic] images obtained from such survey or any other format as may be specified by the Indian Bureau of Mines in this regard to the Controller General on or before 1st day of July every year.</p> <p>OR</p> <p>In the Digital Aerial Images submitted under Rule 34(A), it is observed that the processed Drone survey output data submitted to Indian Bureau of Mines does not meet the parameters specified in the SOP for submission of Digital Aerial Images under the said Rule. The deviations in the data submitted is as follows:-</p> <table border="1"> <thead> <tr> <th>Sl. No.</th> <th>Data type</th> <th>Check Point parameters as per SOP</th> <th>Submitted in proper format (Yes/No)</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>Orthomosaic image of lease area including 100m buffer zone.</td> <td>Resolution 5cm</td> <td>No</td> <td>Not Submitted</td> </tr> <tr> <td>2</td> <td>Digital Elevation Model (3D) – DTM &amp; DSM</td> <td>Resolution 15cm</td> <td>No</td> <td>Not Submitted</td> </tr> <tr> <td>3</td> <td colspan="4">In addition to this no permanent GCP were found at the Mine site during the inspection. GCPs shall be present as per the SOP issued in this regard.</td> </tr> </tbody> </table>					Sl. No.	Data type	Check Point parameters as per SOP	Submitted in proper format (Yes/No)	Remarks	1	Orthomosaic image of lease area including 100m buffer zone.	Resolution 5cm	No	Not Submitted	2	Digital Elevation Model (3D) – DTM & DSM	Resolution 15cm	No	Not Submitted	3	In addition to this no permanent GCP were found at the Mine site during the inspection. GCPs shall be present as per the SOP issued in this regard.			
Sl. No.	Data type	Check Point parameters as per SOP	Submitted in proper format (Yes/No)	Remarks																					
1	Orthomosaic image of lease area including 100m buffer zone.	Resolution 5cm	No	Not Submitted																					
2	Digital Elevation Model (3D) – DTM & DSM	Resolution 15cm	No	Not Submitted																					
3	In addition to this no permanent GCP were found at the Mine site during the inspection. GCPs shall be present as per the SOP issued in this regard.																								
45(5)(c) read with 45(7)	<p>The holder of a mining lease shall submit online Annual Returns in respect of each mine to the Regional Controller or any other authorised officer of the Indian Bureau of Mines which shall be submitted before the 1<sup>st</sup> day of July each year for the preceding financial year, which shall be complete, correct and true in all aspects.</p> <p>However in your case following deficiencies have been found in the scrutiny of the annual return submitted</p>																								

1. In part 3(ii) of PART-VI (PRODUCTION, DESPATCHES AND STOCKS) (LIMESTONE), production and dispatch of 10 MT is shown however
  - a) No Royalty, DMF & NMET amount is shown in point 2. Royalty, Rents and Payments made to DMF and NMET of PART-III (Consumption of Materials)
  - b) No depletion of reserves has been shown in point 2. Reserves and Resources estimated (in tonnes) (LIMESTONE) of PART-V (General Geology & Mining)
  - c) No details have been shown in 5. Sales- Despatches effected for Domestic Purpose and for exports.

1. In this connection, it is brought to your kind notice that :-
  - a) the above violations constitute an offence punishable under Rule 62 of MCDR 2017 and/or;
  - b) Mining operations can be suspended as per rule 11(2) of MCDR 2017 in case of non-compliance of above rules as these violations also affects provisions of Rule11(1) of MCDR 2017 and/or;
  - c) You are advised to rectify the above violation of above Rules immediately and intimate the compliance position to this office, within a period of 45 days for violated rules from date of issue of this letter.
2. In case of violation of Rule 34(A), you are advised to rectify the above violations immediately and upload data online on DDMS portal **within 45 (Forty Five) days** from the date of issue of this letter
3. In case of violation of Rule 45,
  - a) You are also liable to pay such amount as prescribed under MCDR 2017 for delay of each day as per **Schedule-II**, read with Rule **45(7A)** in case of non-compliance of various provisions of Rule 45.
  - b) As per provision of Rule **45(7) and/or 45(7A)(ii)** the Regional Controller of Mines may take appropriate action including order of suspension of **all mining operations and dispatches** on non-compliance of various provisions of Rule 45.
4. In context to the violations of Rule 45, this letter has been considered as show cause notice where you are advised to rectify above violation immediately. You are therefore directed to show cause within a period of **30 days** for violations of Rule 45 from the date of issue of this letter as to why the action under Rules **45(7) and/or 45(7A)** shall not be taken against you. No further notice will be given to you in this regard.
5. This letter is being issued with the approval of Regional Controller of Mines.

भवदीय /Yours faithfully

Signed by Mohammad Nimar

(मोहम्मद निमर Date: 07-12-2024 12:03:35

(उप खान नियंत्रक Deputy Controller of Mines)

प्रतिलिपि सूचनार्थ हेतु प्रेषित/ Copy for favor and information:-

1. Controller of Mines(NZ), Udaipur
2. Commissioner of Geology and Mining, Gandhinagar
3. DDG, MMS Division, Nagpur
4. District Geologist, District: Jamnagar
5. Guard File

(उप खान नियंत्रक Deputy Controller of Mines)