

## स्पीड पोस्ट उल्लंघन पत्र

भारत सरकार  
खान मंत्रालय  
भारतीय खान ब्यूरो  
क्षेत्रीय खान नियंत्रक कार्यालय  
कर्मयोगी भवन, चतुर्थ माला, ब्लॉक-2, सी विंग,  
सेक्टर-10A, गांधीनगर, गुजरात, 382010



Government of India  
Ministry of Mines  
Indian Bureau of Mines  
Office of Regional Controller of Mines  
Karmayogi Bhavan, 4<sup>th</sup> Floor, Block-2, C Wing,  
Sec 10A  
Gandhinagar, Gujarat-382010

Tel- 079 29750358 /29750359; ई-मेल/ E-mail: ro.gandhinagar@ibm.gov.in

पत्रावली संख्या: AMR/BXT-001

Mine code 07GUJ02001

दिनांक:

To

Shri Pratapsinh Abhalbhai Mori,  
Village-Pipli, Taluka-Kodinar,  
District-Gir Somnath, Gujarat-362720  
Phone No. +91-98249-40540,  
Email-rajhans.mori83@gmail.com

**विषय:** गुजरात राज्य के जिले- Amreli की तालुका- Jafarabad में स्थित आपकी Chhelana Bauxite, White Clay Mine , क्षेत्रफल- 12.6767 हे. (Mine code 07GUJ02001) में खनिज संरक्षण एवं विकास नियमावली, 2017 के नियमों का उल्लंघन।

महोदय,

आपकी उपरोक्त खान का स्टार रेटिंग निरीक्षण अधोहस्ताक्षरी द्वारा दिनांक 19.12.2024 को Hiren Oza and Suresh Pipariya की उपस्थिति में किया गया तथा उक्त निरीक्षण के समय खनिज संरक्षण एवं विकास नियमावली, 2017 के निम्नलिखित नियमों का उल्लंघन पाया गया-

नियम सं./ Rule No	उल्लंघन के प्रकार का विस्तृत ब्यौरा/ Detailed description of the type of violation
11(1)	The following mining operations were not carried out as per the Approved Modified Mining plan No. 684(4)(1)/MP-418/2022-23-GNR, Dated: 03.06.2022. a) Chapter-6, Progressive Mine Closure Plan (PMCP) proposal, there was a provision to plant 250 trees for afforestation (green belt development) over an area of 0.25 hectares and to install 609 meters of fencing during FY 2023-24. However, these planned PMCP activities were not observed at the specified location during the inspection.
26(2)	The holder of mining lease shall submit to the competent authority a yearly report as per the format specified by the Indian Bureau of Mines, before 1 <sup>st</sup> day of July report every year [along with annual return] setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan, and if there is any deviation, reasons thereof: However, in your case no details given in the submitted PMCP report, which is a violation of Rule 26(2) of the MCDR 2017.

- In this connection, it is brought to your kind notice that :-
  - the above violations constitute an offence punishable under Rule 62 of MCDR 2017 and/or;
  - Mining operations can be suspended as per rule 11(2) of MCDR 2017 in case of non-compliance of above rules as these violations also affects provisions of Rule11(1) of MCDR 2017 and/or;
  - You are advised to rectify the above violation of above Rules immediately and intimate the compliance position to this office, within a period of 45 days for violated rules from date of issue of this letter.
- This letter is being issued with the approval of Regional Controller of Mines.

भवदीय/ Yours faithfully,

Dr. Debajyoti Nayak  
Junior Mining Geologist  
Indian Bureau of Mines

प्रतिलिपि सूचनार्थ हेतु प्रेषित/ Copy for favor and information:-

- Controller of Mines(NZ), Udaipur
- Commissioner of Geology and Mining, Gandhinagar

Guard File

कनिष्ठ खनन भविज्ञानी  
Signed by Debajyoti Nayak  
भारतीय खान ब्यूरो  
Date: 17-03-2025 14:47:58