

उल्लंघन पत्र

भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खान नियंत्रक कार्यालय
कर्मयोगी भवन, चतुर्थ माला, ब्लॉक-2, सी विंग,
सेक्टर-10A, गांधीनगर, गुजरात, 382010



Government of India
Ministry of Mines
Indian Bureau of Mines
Office of Regional Controller of Mines
Karmayogi Bhavan, 4th Floor, Block-2, C Wing, Sec10A
Gandhinagar, Gujarat-382010

Tel- 079 29750358 /29750359; ई-मेल/ E-mail: ro.gandhinagar@ibm.gov.in

पत्रावली संख्या: MCDR-MiFLOBXT/95/2022-GNR-IBM_RO_GN Mine code 07GUJ07012 ID_ दिनांक: _/02/2025

सेवा में :

मै. सौराष्ट्र केलसाइन बोक्साइट & अलाइड
इंडस्ट्रीस, हर्ष रोड, पो.ओ.-भाटिया, तालुका-
कल्याणपुर, जिला- देवभूमि-द्वारका, 361315
गुजरात-361315

M/s Saurashtra Calcine Bauxite & Allied Ind.
Harsha Road, P.O-Bhatia, Ta-Kalyanpur, Dist-Devbhumi
Dwarka, Gujarat 361315
Ph No- 02891-2331997
Mobile:

ई-मेल: scabal@gmail.com, scabalindia@gmail.com, scabalbhatiya@gmail.com

विषय: गुजरात राज्य के देवभूमि-द्वारका जिले की कल्याणपुर तालुका में केनेडी ग्राम के निकट स्थित आपकी केनेडी-505/P
बॉक्साइट खान, क्षेत्रफल- 3.44 हे. में खनिज संरक्षण एवं विकास नियमावली, 2017 के नियमों का उल्लंघन।

महोदय,

आपकी उपरोक्त खान का खनिज संरक्षण एवं विकास नियमावली, 2017 और स्टार रेटिंग निरीक्षण अधोहस्ताक्षरी द्वारा
दिनांक 18.12.2024 को श्री विशाल कामलिया, खनन अभियंता और श्री विमल, सर्वेयर की उपस्थिति में किया गया तथा उक्त
निरीक्षण के समय खनिज संरक्षण एवं विकास नियमावली, 2017 के निम्नलिखित नियमों का उल्लंघन पाया गया-

नियम सं.	उल्लंघन के प्रकार का विस्तृत ब्यौरा
11(1)	No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines but in your case the following work is not being done as per the Approved Review of Mining plan No. MCDR-684(4)(1)/MP-426(406)/2022-23 dated 08.08.2022:- (i) According to Table No. 2.2.5.3 of the approved mining plan, the exploration work was proposed by pitting of 5 pits but at the time of inspection, it was found that no such exploration work has been carried out. (ii) According to Table No. 6.2.3.2 of the approved mining plan, it was proposed to plant 100 No. plants during the year 2023-24 but at the time of inspection it was found that 40 plants were survived.

- In this connection, it is brought to your kind notice that ;
 - the above violations constitute an offence punishable under Rule 62 of MCDR 2017 and/or;
 - Mining operations can be suspended as per rule 11(2) of MCDR 2017 in case of non-compliance of provisions of Rule 11(1) of MCDR 2017 and/or;
- You are advised to rectify the above violation of above Rules immediately and intimate the compliance position to this office, within a period of 45 days for violated rules from date of issue of this letter.
- This letter is being issued with the approval of Regional Controller of Mines.

भवदीय
Signed by Sunil Kumar
Sharma
Date: 28-02-2025 10:49:55
(सुनील कुमार शर्मा)
वरिष्ठ सहायक खान नियंत्रक

भारतीय खान ब्यूरो

प्रतिलिपि-

1. Controller of Mines(NZ), Udaipur
2. Commissioner of Geology and Mining, Gandhinagar
3. DDG, MMS Division, Nagpur
4. District Geologist, District: Devbhumi-Dwarka
5. Guard File

वरिष्ठ सहायक खान नियंत्रक
भारतीय खान ब्यूरो