

Violation Notice Letter

By e-mail

**भारत सरकार / GOVERNMENT OF INDIA**  
**खान मंत्रालय / MINISTRY OF MINES**  
**भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES**  
**क्षेत्रीय खान नियंत्रक कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES,**  
**HYDERABAD**

**File No.:** MCDR-Misc/13/2026-HYD-IBM

Date : 17/03/2026

To: Shri/M/s. N/A, Nominated Owner,  
NANDYALA, 64, PLEASANT VILLE  
,BACHUPALLY JUNCTION,  
QUTHBULLAPUR, Ramanthapur Village &  
Mandal, Medak district, Telangana,- 500090

**Subject:** Violation of provision of Mineral Conservation and Development Rules, 2017 in respect of your RAMANTHAPUR QTZ.MINE (49APR13022) over an extent of 4.906 ha in Ramanthapur in HYDERABAD, Medak, Telangana.

Sir, The following provisions of the Mineral Conservation and Development Rules, 2017 were found to be violated in your mine during the inspection carried out on 05.03.2026 by Shri Rakesh Kumar Arya, Assistant Mining Engineer, in the presence of Shri N. Ravinder Reddy, Mines Owner.

**Summary of Violations :**

Items for Reporting	As Per Plan	Actual	Deviation	Rule	Reason
(Copies of notices and returns and reports to be maintained)	The holder of a mining lease shall maintain the labour attendance register, production and dispatch register, royalty assessment register, sub-grade or mineral reject stack register.	Registers are not available at the mine site.	Lessee has not maintained any registers as required under rule 54	Rule 54,	
Mining Operations (Machinery and Plant)	Where heavy earth moving machineries is used in mines, the holder of a mining lease shall maintain logbooks duly authenticated by the manager or mining engineer.	Logbooks are not available at mine site.	Lessee has not maintained logbooks of heavy earth moving machineries as required under rule 19(1)	Rule 19(1),	
Annual Return: Appointment of Mining Engineer & Geologist as per provisions of Rule 55 of MCDR,2017	As per the provisions of MCDR, 2017, a Mining Engineer and a Geologist are required to be appointed on a full-time/part-time basis.	Not appointed of Mining Engineer & Geologist as per provisions of Rule 55 of MCDR,2017	It was observed that the lessee has not appointed of Mining Engineer & Geologist as required under the provisions Rule 55 (1) of MCDR, 2017.	Rule 55(1),	
Exploitation - Opencast Mine: Whether height of benches in Overburden & mineral suitable for method of mining proposed in mining plan	Height of the bench proposed is 6 m.	Height of the bench observed in pit nos. 3 is around 10-12 m and excavation is done without formation of the benches.	Excavation done in the year 2024-25 has not followed approved mining plan.	Rule 11(1),	

2. In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under Rule 62 of MCDR, 2017. 3. The mining operations can be suspended under Rule 11(2), if compliance of MCD Rules 2017 is not found satisfactory, or prosecution can be made, or both can be done. 4. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (Forty-five) days from the date of issue of this letter.

Yours faithfully,

(Nilabh Panchal, HYDERABAD)  
ACOM

ESIGNED BY: NILABH  
DATE: 18/03/2026 10:24:58 AM