

**Show Cause Notice Letter**

**By e-mail**

**भारत सरकार / GOVERNMENT OF INDIA  
खान मंत्रालय / MINISTRY OF MINES  
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES  
क्षेत्रीय खान नियंत्रक कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES,  
DEHRADUN**

**File**

Date : 08/04/2026

**No.:** MCDR-MiFL0LST/10/2023-DDN-IBM\_RO\_DDN

To: Shri/M/s. N/A,  
Nominated Owner, Rajinder,  
M/s Bharwana Lime Stone  
Mine ,Village Ranfua, P.O.  
Andheri, Tehsil Sangrah,  
Andheri (147) Village &  
Mandal, Sirmaur district,  
Himachal Pradesh,- 173011

**Subject :** Violation of provision of Mineral Conservation and Development Riles, 2017 in respect of your 38HPR10037(38HPR10037) over an extent of 2.9 ha in Andheri (147) in , Sirmaur, Himachal Pradesh

Sir, The above mine was inspected on 17.12.2025 by the undersigned in the presence of Shri Shri Ravi Bhusan Singh (Mining Engineer) and Shri Prakash Singh (Mine Manager) and during the inspection, the following provisions of the Mineral Conservation and Development Rules, 2017 were found to be violated.

**Summary of Violations :**

--	--	--	--	--	--	--

Items for Reporting	As Per Plan	Actual	Deviati on	Rule	Reason	Status
Annual Return: Scrutiny of Annual return on sale value, Ex. Mine price & production cost	propose d	sale value- 335 Rs Ex. Mine price- 342 Rs product ion cost- 283.98 Rs	yes	Rule 45(7),	The sale value, ex-mine price, and cost of production have been reported as 335 rs per tonne, 342 rs per tonne, and 283.98 rs per tonne respectively. The figures indicate inconsistency, as the ex-mine price is higher than the sale value, which is not in conformity with standard pricing norms. Therefore, the information furnished appears to be incorrect and requires review and correction in the submitted annual returns.	Not Complied
Annual Return: Whether incomplete or false or wrong returns submitted (Rule 45(7))	Proposa l has been given for not providi ng wrong and inc omplete informa tion in annual return.	informa tion sub mitted in the annual return not as per the proposa l.	yes	Rule 45(7),	The details of the mineral reject have been furnished under the waste generation head in the submitted Annual Return for the reporting year	Not Complied
Development - Opencast: Location of	A proposa l has	During the insp ection,	yes	Rule 11(1),	Accordingly, a violation of Rule 11(1) is being	Not Complied

<p>development w.r.t. lease area</p>	<p>been given for developmental work from 1415 mRL to 1405 mRL, with the formation of two benches in the SSW to NNE direction. The proposed development lies within the latitude range of 304139.23 N to 304141.71 N and the longitude range of 7727 29.82 E to 7727 38.17 E.</p>	<p>it was observed that ROM production was being carried out from a location other than the approved/proposed area, though within the lease area. The production was thus not in conformity with the approved mining plan, as extraction was undertaken from a different place than the one proposed.</p>		<p>pointed out for not carrying out mining operations as per the approved mining plan.</p>	
--------------------------------------	---	---	--	--	--

1) In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017. 2) The mining operations can be suspended under the rule 11(2) of MCDR-2017, if compliance of rule 11(1) of MCDR-2017 is not found satisfactory. 3) You are advised to rectify the above violations immediately and intimate the position to this office within 30 days from the date of issue of this letter.

Yours faithfully,

(NITIN SINGH, DEHRADUN)  
JMG

Esigned by: NITIN Date: 15/04/2026 11:01:27 AM
---