



भारत सरकार/Government of India  
खान मंत्रालय/Ministry of Mines  
भारतीय खान ब्यूरो/Indian Bureau of Mines  
नागपुर क्षेत्रीय कार्यालय/Nagpur Regional Office

**By Speed Post/Email**

छटवी मंजील, बी एव सी ब्लॉक,  
इंदीरा भवन, सिविल लाइन्स, नागपुर-44001  
6<sup>th</sup> Floor, 'B' & 'C' Block  
Indira Bhawan, Civil Lines,  
Nagpur-440001  
दुरभाष / Telephone- 562794  
2565089 (Tel/Fax)  
ईमेल- rcom.nr@ibm.gov.in

**No. MAH/NAG/Mn-312/NGP**

**Date: 25.03.2022**

To,

Shri. Shakeel Ahmed Aqueel Hussain,  
Aqueel Mansion, Teen Nal Chowk, Itwari,  
**District:-NAGPUR-4400002 (Maharashtra)**  
Email:- shakeelaqueelhusain@gmail.com

Sub:- Violation of provision of Mineral Conservation and Development Rule 2017 in respect of your Wadegaon Manganese Mine (2.49 Hect) of Shri Shakeel Ahmed Aqueel Hussain, situated in Nagpur district of Maharashtra State - reg.

Sir,


The following provisions of Mineral Conservation and Development Rule, 2017 (MCDR, 2017) were found violated in respect of the above said mine during inspection on 16-03-2022 by Shri. R. M. Khadse, Assistant Mining Engineer.

Rule	Nature of Violation observed
11(1)	<p>No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5 or approved by the competent authority of the Atomic Minerals Directorate for Exploration and Research, in respect of minerals specified in Part B of the First Schedule to the Act where the grade of such atomic minerals is equal to or above the threshold value limits declared under Schedule-A of the Atomic Minerals Concession Rules, 2016.</p> <p>In this connection following deficiencies are observed during the inspection of your above referred mine:-</p> <ol style="list-style-type: none"><li>1. Further during inspection it is observed that "No environmental monitoring" is being carried out and no records in this regard are made available at your mines.</li></ol> <p>Hence, there is deviation from the approved mining plan and violations of provision of MCDR-2017 (amended to 2021).</p>
55(1)(c)	<p>For the purpose of carrying out reconnaissance, prospecting or mining operations in accordance with these rules,-</p> <p>(c) every holder of a mining lease shall employ, in case of-</p> <ol style="list-style-type: none"><li>(i) category 'A' mines, a whole-time mining engineer and a geologist;</li><li>(ii) category 'B' mines, a part-time mining engineer and a part-time geologist;</li></ol> <p>During inspection of your mine on 16<sup>th</sup> March, 2022 Shri. Ashish W. Barapatre, Mining Engineer was present at mine site, but from office records it is observed that notice of his appointment was not submitted to this office in Form-H under MCDR-2017.</p> <p>In view of above, it is appeared that, the mining operations are being carried out without Geologist. This attracts the violation of provisions of Rule 55(1)(c) of Mineral Conservation Development Rules, 2017.</p>

..2..

03. In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under Rule 62 of MCDR, 2017.
04. The mining operations can be suspended under Rule 11(2), if compliance of MCD Rules 2017 is not found satisfactory, or prosecution can be made, or both can be done.
05. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (Thirty) days from the date of issue of this letter.

Yours faithfully,

  
25/8/22  
(R. R. Dongre)

Regional Controller of Mines



Copy to.

1. The Controller of Mines (CZ), Indian Bureau of Mines, Nagpur.
2. The Director, Directorate of Geology & Mining, Government of Maharashtra, Khanij Bhwan, 27-Shivaji Nagar, Cement Road, Nagpur-440010 (MS).

  
25/8/22  
(R. R. Dongre)

Regional Controller of Mines

