

**INDIAN BUREAU OF MINES
MINERALS DEVELOPMENT AND REGULATION DIVISION**

MCDR inspection REPORT

Nagpur regional office

Mine file No : MP/DHR/LST-56/NGP

Mine code : 38MPR12072

- (i) Name of the Inspecting : **CQ05**) **ROBERT SIMON C**
Officer and ID No.
- (ii) Designation : Assistant Controller Mine
- (iii) Accompanying mine :
Official with
Designation
- (iv) Date of Inspection : 25-JUN-21
- (v) Prev.inspection date : 16-JUL-19

PART-I : GENERAL INFORMATION

1. (a) **Mine Name** : **GHURSAL**
- (b) **Registration NO.** : **IBM/20034/2015**
- (c) Category : B Manual
- (d) Type of Working : Opencast
- (e) Postal address :
State : MADHYA PRADESH
District : DHAR
Village : GHURSAL
Taluka : MANAWAR
Post office : MANAWAR
Pin Code :
FAX No. :
E-mail :
Phone :
- (f) Police Station :
- (g) First opening date : 25-SEP-13
- (h) Weekly day of rest : SUN
2. Address for : 50, SHANTI NIKETAN,
correspondance BEHIND BOMBAY HOSPITAL,
INDORE-452010
3. (a) Lease Number : MPR2165
- (b) Lease area : 3
- (c) Period of lease : 30
- (d) Date of Expiry : 24-NOV-35
4. Mineral worked : LIMESTONE Main

5. Name and Address of the

Lessee : MOHAN LAL BANSAL
50, SHANTI NIKETAN, BEHIND
BOMBAY HOSPITAL INDORE
INDORE MADHYA PRADESH
Phone:9425064203
FAX :0731-4075937

Owner : MOHAN LAL BANSAL
MOHAN LAL BANSAL DHAR MP
DHAR MADHYA PRADESH
Phone:
FAX :

Agent : MOHAN LAL BANSAL
MOHAN LAL BANSAL DHAR,MP
DHAR MADHYA PRADESH
Phone:
FAX :

6. Date of approval of Mining	:	Fresh under rule 22 MCR1960	16-DEC-96
Plan/Scheme of Mining	:	MP modif under MCR 1960	08-AUG-16

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	No proposals	Nil	
1b	Exploration over lease area for geological axis 1 or 2	No proposals	G2 - 2.14 ha previously explored.	
1c	Exploration Agencies and Expenditure in lakh rupees during the year	NA	NA	
1d	Balance area to be explored to bring Geological axis in 1 or 2	No proposals	G2 - 2.14 ha to be explored in G1.	
1e	Balance reserve as on 01/04/20	No proposals	122 = 172843 tonnes	
1f	General remarks of inspecting officers on geology, exploration etc			No proposals as there was no approved document for the year 2020-21.

Development :

Sl.No.	Item	Proposals	Actual work	Remarks
2a	Location of development w.r.t.lease area	No proposals	Nil	
2b	Separate benches in topsoil, overburden and minerals (Rule 15)	No proposals	Nil	
2c	Stripping ratio or ore to OB ratio	NA	NA	
2d	Quantity of topsoil generation in m3	No proposals	Nil	

2e	Quantity of overburden generation in m3	No proposals	Nil	
2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc			No proposals on development of pit as there was no approved document for the year 2020-21.

Exploitation:

Sl.No.	Item	Proposals	Actual work	Remarks
3a	Number of pit proposed for production	No proposals	Nil	
3b	Quantity of ROM mineral production proposed	No proposals	Nil	
3c	Recovery of sailable/usable mineral from ROM production	No proposals	Nil	
3d	Quantity of mineral reject generation	No proposals	Nil	
3e	Grade of mineral rejects generation and threshold value declared.	No proposals	Nil	
3f	Quantity of sub grade mineral generation.	No proposals	Nil	
3g	Grade of sub grade mineral generation	NA	NA	
3h	Manual / Mechanised method adopted for segregating from ROM	No proposals	Nil	

3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	No proposals	NA	
3j	Provision of drilling and blasting in mineral benches	No proposals	Nil	
3k	Provision of mining machineries in mineral benches	No proposals	Nil	
3l	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	NA	NA	
3m	Total area covered under excavation/pits	No proposals	1.38 ha previously excavated.	
3n	Ore to OB ratio for the pit/mine during the year.	NA	NA	
3o	Total area put in use under different heads at the end of year	No proposals	1.416 ha	
3p	Production of ROM mineral during the last five year period as applicable	2017-18 49875 2018-19 48915 2019-20 49753 2020-21 NIL	2017-18 37154 2018-19 47315 2019-20 NIL 2020-21 NIL	
3q	General remarks of inspecting officers on method of mining etc.			No proposals on method of mining as there was no approved document for the year 2020-21.

Solid Waste Management - Dumping:

Sl.No.	Item	Proposals	Actual work	Remarks
--------	------	-----------	-------------	---------

4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	No proposals	Nil	
4b	Location of topsoil, OB and mineral reject dumps	NA	NA	
4c	Number of dumps within lease area and outside of lease area	No proposals	Nil	
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	NA	NA	
4e	Number of active and alive dumps.	Nil	Nil	
4f	Number of dead dumps.	Nil	Nil	
4g	Number of dumps established.	Nil	Nil	
4h	Whether Retaining wall or garland drain all along dumps are there.	NA	NA	
4i	Length of Retaining wall or garland drain all along dumps	Nil	Nil	
4j	Number of settling ponds	Nil	Nil	
4k	Specific comments of inspecting officer on waste dump management			No proposals as there was no approved document for the year 2020-21

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
--------	------	-----------	-------------	---------

5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	No proposals	Nil	
5b	Area under backfilling of mined out area	No proposals	Nil	
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	No proposals	Nil	
5d	Total area fully reclaimed and rehabilitated	No proposals	Nil	
5e	General remarks of inspecting officers on backfilling and reclamation etc.			No proposals on backfilling and reclamation as there was no approved document for the year 2020-21.

Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
6a	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).		not submitted	violation pointed out under rule 26(2) of MCDR 2017.
6b	Area available for rehabilitation (ha) .	NA	NA	

6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (Lx B x D	NA	NA	
6m	Compliance of rehabilitation of waste land within lease (i)afforestation	NA	NA	
6p	Compliance of environmental monitoring (core zone and buffer zone)	Not proposed	Not done	
6q	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.			No proposals on PMCP as there was no approved document for the year 2020-21.

Mineral Conservation:

Sl.No.	Item	Proposals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	No proposals	Nil	
7b	Method of grade-wise mineral sorting i.e. manual or mechanical.	No proposals	Nil	
7c	Different grade of mineral sorted out at mines.	No proposals	Nil	
7d	Any beneficiation process at mines	No proposals	Nil	

7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues	No proposals on Mineral conservation & beneficiation as there was no approved document for the year 2020-21.
----	--	--

Environment:

Sl.No.	Item	Proposals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	No proposals	Nil	
8b	Concurrent use or storage of topsoil	NA	NA	
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	No proposals	Nil	
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	No proposals	Nil	
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	No proposals	Nil	

8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	No proposals	NA	
8g	Survival rate	NA	NA	
8h	Water sprinkling on roads to control airborne dust	No proposals	Nil	
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area			No proposals as there was no approved document for the year 2020-21.

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns		Annual return for the year 2020-21 was not submitted.	violation pointed out under rule 45(5) (c) of MCDR 2017.
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	AR not submitted	NA	
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	NA	NA	
9d	Scrutiny of Annual return on afforestation	NA	NA	
9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	NA	NA	

9f	Scrutiny of Annual return on ROM stock and/or graded ore	NA	NA
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost	NA	NA
9h	Scrutiny of Annual return on fixed assets	NA	NA
9k	Scrutiny of Annual return on mining machineries	NA	NA

Details of violations observed during current inspection and compliance position of violation pointed out

Violation observed			Show cause position		
Rule NO.	Issued on	Compliance on	Rule NO.	Issued on	Compliance on
MCDR17	Rule 26(2)	26-JUL-21			
MCDR17	Rule 28(1)	26-JUL-21			
MCDR17	Rule 45(7) (a)	26-JUL-21			

Date :

(ROBERT SIMON C)

Indian Bureau of Mines