

**INDIAN BUREAU OF MINES
MINERALS DEVELOPMENT AND REGULATION DIVISION**

MCDR INSPECTION REPORT

Hyderabad regional office

Mine file No : AP/ADB/Mn-28/HYD

Mine code : 40APR01017

- (i) Name of the Inspecting : **RK13**) A.V.Ramesh Kumar
Officer and ID No.
- (ii) Designation : Assistant Mining Geologis
- (iii) Accompanying mine : Sri Ganesh, Rep. of Lessee
Official with
Designation
- (iv) Date of Inspection : 17/09/2016
- (v) Prev.inspection date : 12/03/2015

PART-I : GENERAL INFORMATION

1. (a) **Mine Name** : **KUMBHAZARY(63.41 HA)**
- (b) **Registration NO.** :
- (c) **Category** : B Manual
- (d) **Type of Working** : Opencast
- (e) **Postal address**
- State : TELANGANA
- District : ADILABAD
- Village : KUMBHAZARY
- Taluka : ADILABAD
- Post office : KUMBHAZARY
- Pin Code : 504001
- FAX No. : 08732-220508,
- E-mail :
- Phone : 9849204381
- (f) **Police Station** : ADILABAD
- (g) **First opening date** : 01/11/2010
- (h) **Weekly day of rest** : SUN
2. **Address for correspondance** : SURESH AGARWAL, SRI JAGADAMBA MINING (p) LTD.,
D.NO. 4-1-2011, DEVICHAND CHOWK, MGROAD,
ADILABAD
3. (a) **Lease Number** :
- (b) **Lease area** :
- (c) **Period of lease** :
- (d) **Date of Expiry** :
4. **Mineral worked** : MANGANESE ORE Main

5. Name and Address of the

Lessee : SURESH AGARWAL
C/O JAGADAMBA OIL MILLS,
RAMPUR (V), PONNARI ROAD
ADILABAD ADILABAD TELANGANA
Phone:08732-230751,9849204381
FAX :

Owner : SURESH AGARWAL
C/O JAGADAMBA OIL MILL,
RAMPUR (V), PONNARI ROAD
ADILABAD ADILABAD TELANGANA
Phone: 9849204381
FAX :

Mining Engineer

Name : P.M.PIMPALSHENDE,Part Time
Qualification : B.E.(MINING)
Appointment/ : 01/11/2010
Termination date

6. Date of approval of Mining : Fresh under rule 22 MCR1960 27/10/2008
Plan/Scheme of Mining

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	No proposal for exploration as there is no approved document	No exploration was carried out during the year 2015-16.	A violation cum Show cause notice issued under rule 13(1) of MCDR, 1988 for not having a valid document on 21.09.2016.
1b	Exploration over lease area for geological axis 1 or 2	None	None	None
1c	Exploration Agencies and Expenditure in lakh rupees during the year	None	None	None
1d	Balance area to be explored to bring Geological axis in 1 or 2	None	14 ha	None
1e	Balance reserve as on 01/04/20	None	The reserves as on 1.4.2016 is 48780 tonnes under (111) and 29160 tonnes under (121) and 14580 tonnes of resources under (334).	None
1f	General remarks of inspecting officers on geology, exploration etc	None	None	None

Development :

Sl.No.	Item	Proposals	Actual work	Remarks
2a	Location of development w.r.t. lease area	None	Three pits were noticed in the lease during the inspection	No production reported during the year 2015-16
2c	Stripping ratio or ore to OB ratio	None	None	None
2d	Quantity of topsoil generation in m3	None	None	None
2e	Quantity of overburden generation in m3	None	None	None

2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc	None	None	None
----	---	------	------	------

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	None	During the course of inspection, three pits were noticed with following dimensions 1.25x10x2m 2.50x10x2m 3.25x8x2m Apart of this three trial pits were noticed.	None
3b	Quantity of ROM mineral production proposed	None	No production reported duirng the year 2015-16	None
3c	Recovery of sailable/usable mineral from ROM production	None	None	None
3d	Quantity of mineral reject generation	None	None	None
3e	Grade of mineral rejects generation and threshold value declared.	None	None	None
3f	Quantity of sub grade mineral generation.	None	None	None
3g	Grade of sub grade mineral generation	None	None	None
3h	Manual / Mechanised method adopted for segregating from ROM	None.Earlier it was proposed as manual mine	Manual mine	None
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	None	None	None

3j	Provision of drilling and blasting in mineral benches	None	None	None
3k	Provision of mining machineries in mineral benches	None	None	None
3l	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	None	It was noticed that there is one bench in OB and one bench in ore.	None
3m	Total area covered under excavation/pits	None	1 ha	None
3n	Ore to OB ratio for the pit/mine during the year.	None	None	None
3o	Total area put in use under different heads at the end of year	None	1 ha	None
3p	Production of ROM mineral during the last five year period as applicable	2011-12-4179 tonnes 2-12-13-4131 tonnes 2013-14-4536 tonnes 2014-15-Nil	2011-12-645 tonnes 2012-13-230 tonnes 2013-14-Nil 2014-15-150 tonnes 2015-16-Nil	None
3q	General remarks of inspecting officers on method of mining etc.	None	None	None

Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	None	One bench in topsoil and one bench in ore was noticed	None
4b	Location of topsoil, OB and mineral reject dumps	None	None	None

4c	Number of dumps within lease area and outside of lease area	None	None	None
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	None	None	None
4e	Number of active and alive dumps.	None	None	None
4f	Number of dead dumps.	None	None	None
4g	Number of dumps established.	None	None	None
4h	Whether Retaining wall or garland drain all along dumps are there.	None	None	None
4i	Length of Retaining wall or garland drain all along dumps	None	None	None
4j	Number of settling ponds	None	None	None
4k	Specific comments of inspecting officer on waste dump management	None	None	None

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	None	None	None
5b	Area under backfilling of mined out area	none	A total of 0.20 ha has been backfilled since opening of mine	None
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	None	None	None

5d	Total area fully reclaimed and rehabilitated	None	A total of 0.20 ha has been backfilled	None
5e	General remarks of inspecting officers on backfilling and reclamation etc.	None	None	None

Progressive Mine Closure Plan:

Sl.No.	Item	Proposals	Actual work	Remarks
6a	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	None	None	None
6b	Area available for rehabilitation (ha) .	None	None	None
6c	afforestation done (ha).	None	None	None
6d	No. of saplings planted during the year	None	None	None
6e	Cumulative no .of plants	None	A cumulative of 150 plants were afforested	None
6f	Any other method of rehabilitation	None	None	None
6g	Cost incurred on watch and care during the year	None	None	None
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (L x B x D	None	None	None
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	None	None	None

6j	Compliance on reclamation and rehabilitation by backfilling (iii) Afforestation on on backfilled area	None	None	None
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	None	None	None
6l	Compliance on reclamation and rehabilitation by backfilling (v) any other specific means.	None	None	None
6m	Compliance of rehabilitation of waste land within lease (i) afforestation	None	None	None
6n	Compliance of rehabilitation of waste land within lease (ii) Area rehabilitation (ha)	None	None	None
6o	Compliance of rehabilitation of waste land within lease (iii) Method of rehabilitation	None	None	None
6p	Compliance of environmental monitoring (core zone and buffer zone)	None	None	None
6q	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.	None	None	None

Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
--------	------	-----------	-------------	---------

7a	ROM Mineral dispatch or grade-wise sorting within lease area	No proposal as there is no valid document	No production was reported during the year 2015-16.	None
7b	Method of grade-wise mineral sorting i.e. manual or mechanical.	None	None	None
7c	Different grade of mineral sorted out at mines.	None	None	None
7d	Any beneficiation process at mines	None	None	None
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues	None	None	None

Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	None	None	None
8b	Concurrent use or storage of topsoil	None	None	None
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	None	None	None
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	None	None	None

8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	None	None	None
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	None	it is observed that other than the area under pits, rest of the area is under cultivation of cotton crop.	None
8g	Survival rate	None	None	None
8h	Water sprinkling on roads to control airborne dust	None	None	None
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area	None	None	None

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns	Only Monthly returns are being submitted regularly. Annual returns are not being submitted since 2014-15 onwards.	A violation letter for non submission of Annual returns is issued based on office records on 04.08.2016	None
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Annual return for 2014-15 and 2015-16 not submitted.	None	None
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	None	None	None

9d	Scrutiny of Annual return on afforestation	None	None	None
9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	None	None	None
9f	Scrutiny of Annual return on ROM stock and/or graded ore	None	None	None
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost	None	None	None
9h	Scrutiny of Annual return on fixed assets	None	None	None
9k	Scrutiny of Annual return on mining machineries	None	None	None

Details of violations observed during current inspection and compliance position of violation pointed out

Violation observed			Show cause position		
Rule NO.	Issued on	Compliance on	Rule NO.	Issued on	Compliance on
Rule 13(1)	21/09/2016				

Date :
(A.V.Ramesh Kumar)

Indian Bureau of Mines