

**INDIAN BUREAU OF MINES
MINERALS DEVELOPMENT AND REGULATION DIVISION**

MCDR INSPECTION REPORT

Bhubaneshwar regional office

Mine file No : ORI/CR/JJP/MCDR-1/BBS-9/3/2001

Mine code : 11ORI19003

- (i) Name of the Inspecting : **VPD**) **VIKRAM DESHPANDE**
Officer and ID No.
- (ii) Designation : Assistant Controller Mine
- (iii) Accompanying mine : Shri Deepak Ranjan, Mines Manager, Jyoti Maharana, Qu
Official with
Designation
- (iv) Date of Inspection : 04/05/2024
- (v) Prev.inspection date : 21/02/2023

PART-I : GENERAL INFORMATION

1. (a) **Mine Name** : **KALIAPANI(OMC)**
- (b) **Registration NO.** :
- (c) Category : A Manual
- (d) Type of Working : Opencast
- (e) Postal address
State : ORISSA
District : JAJPUR
Village : KALIAPANI
Taluka : SUKINDA
Post office : KALIAPANI
Pin Code : 755047
FAX No. :
E-mail :
Phone : 06726-68701
- (f) Police Station :
- (g) First opening date : 08/07/1967
- (h) Weekly day of rest : SUN
2. Address for : AT/PO:KALIAPANI,
correspondance DIST:JAJPUR
ORISSA-
3. (a) Lease Number : ORI0237
- (b) Lease area : ~~971.25~~623.394 Ha
- (c) Period of lease :
- (d) Date of Expiry : 07/07/2037
4. Mineral worked : CHROMITE Main

5. Name and Address of the

Lessee : M/S Orissa Mining Corporation Ltd
P.O.NO.34 OMC House
Bhubaneswar KHURDA ORISSA
Phone:
FAX :

Owner : m/s ORISSA MINING CORPORATION LTD
OMC HOUSE P.B.No.34
BHUBNESHWAR ORISSA
Phone: 2393431
FAX : 2391629

Manager

Name : Deepak Ranjan
Qualification : BTECH Mining
Appointment/ :
Termination date

6. Date of approval of Mining	:	Mining Scheme rule 12 MCDR1988	09/08/2000
Plan/Scheme of Mining		Mining Scheme rule 12 MCDR1988	12/06/2007
		Renewal under rule 24 MCR1960	12/03/2008
		Mining Scheme rule 12 MCDR1988	17/02/2012

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
1b	Exploration over lease area for geological axis 1 or 2	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.

1c	Exploration Agencies and Expenditure in lakh rupees during the year	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
1d	Balance area to be explored to bring Geological axis in 1 or 2	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.

1e	Balance reserve as on 01/04/20	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
1f	General remarks of inspecting officers on geology, exploration etc			The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.

Development :

Sl.No.	Item	Propasals	Actual work	Remarks
--------	------	-----------	-------------	---------

2a	Location of development w.r.t.lease area	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
2b	Separate benches in topsoil, overburden and minerals (Rule 15)	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.

2c	Stripping ratio or ore to OB ratio	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
2d	Quantity of topsoil generation in m3	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.

2e	Quantity of overburden generation in m3	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc			The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
--------	------	-----------	-------------	---------

3a	Number of pit proposed for production	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
3b	Quantity of ROM mineral production proposed	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.

3c	Recovery of sailable/usable mineral from ROM production	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016- 17.
3d	Quantity of mineral reject generation	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016- 17.

3e	Grade of mineral rejects generation and threshold value declared.	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
3f	Quantity of sub grade mineral generation.	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.

3g	Grade of sub grade mineral generation	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
3h	Manual / Mechanised method adopted for segregating from ROM	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.

3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
3j	Provision of drilling and blasting in mineral benches	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.

3k	Provision of mining machineries in mineral benches	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
3l	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.

3m	Total area covered under excavation/pits	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
3o	Total area put in use under different heads at the end of year	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.

3p	Production of ROM mineral during the last five year period as applicable	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
3q	General remarks of inspecting officers on method of mining etc.			The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.

Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
--------	------	-----------	-------------	---------

4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
4b	Location of topsoil, OB and mineral reject dumps	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.

4c	Number of dumps within lease area and outside of lease area	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.

4e	Number of active Nil and alive dumps.	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
4f	Number of dead Nil dumps.	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.

4g	Number of dumps established.	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
4h	Whether Retaining wall or garland drain all along dumps are there.	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.

4i	Length of Retaining wall or garland drain all along dumps	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
4j	Number of settling ponds	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.

4k	Specific comments of inspecting officer on waste dump management	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
----	--	---

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.

5b	Area under backfilling of mined out area	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.

5d	Total area fully reclaimed and rehabilitated	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
5e	General remarks of inspecting officers on backfilling and reclamation etc.	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.

Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
--------	------	-----------	-------------	---------

6a	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. the last approved document was for the period of 2012-13 to 2016-17.
6b	Area available for rehabilitation (ha) .	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.

6c	afforestation done (ha).	Nil	Nil	<p>The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.</p>
6d	No. of saplings planted during the year	Nil	Nil	<p>The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.</p>

6e	Cumulative no .of plants	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.
6f	Any other method of rehabilitation	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.

6g	Cost incurred on Nil watch and care during the year	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.
6h	Compliance on Nil reclamation and rehabilitation by backfilling (i) Voids available for backfilling (Lx B x D	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.

6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.
6j	Compliance on reclamation and rehabilitation by backfilling (iii) Afforestation on backfilled area	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.

6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.
6l	Compliance on reclamation and rehabilitation by backfilling (v)any other specific means.	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.

6m	Compliance of rehabilitation of waste land within lease (i)afforestation	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.
6n	Compliance of rehabilitation of waste land within lease (ii)Area rehabilitation (ha)	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.

6o	Compliance of rehabilitation of waste land within lease (iii)Method of rehabilitation	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.
6p	Compliance of environmental monitoring (core zone and buffer zone)	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.

6q	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.
----	---	---

Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.

7b	Method of grade- Nil wise mineral sorting i.e. manual or mechanical.	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016- 17.
7c	Different grade Nil of mineral sorted out at mines.	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016- 17.

7d	Any beneficiation process at mines .	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues			The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.

Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
--------	------	-----------	-------------	---------

8a	Separate removal and utilization of topsoil (Rule 32)	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.
8b	Concurrent use or storage of topsoil	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.

8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.

8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	Nil	Nil	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.

8g	Survival rate	Nil	Nil	<p>The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.</p>
8h	Water sprinkling on roads to control airborne dust	Nil	Nil	<p>The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.</p>

8i	General remarks of inspecting officer on aesthetic beauty in and around mines area	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.
----	--	---

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns	AR for 2023-24 is not due for submission.	Monthly Return has been submitted till April 2024.	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.

- 9b Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager AR for 2023-24 Nil not due for submission
- The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.
- 9c Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc. AR for 2023-24 Nil not due for submission.
- The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.
-

- 9d Scrutiny of AR for 2023-24 Nil
Annual return on not due for
afforestation submission.
- The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.
- 9e Scrutiny of AR for 2023-24 Nil
Annual return on not due for
mineral reject submission.
generation
(Grade and
quantity)
- The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.
-

9f	Scrutiny of AR for 2023-24 Nil Annual return on not due for ROM stock and/or submission. graded ore	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.
9g	Scrutiny of AR for 2023-24 Nil Annual return on not due for sale value, Ex. submission. Mine price and production cost	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.

9h	Scrutiny of Annual return on fixed assets	AR for 2023-24 Nil not due for submission.	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.
9k	Scrutiny of Annual return on mining machineries	AR for 2023-24 Nil not due for submission.	The mine is not in operation since 08.07.2007 due to absence of statutory clearance i.e. Forest Clearance. Further the mine is under suspension since 04.04.2016 under the provision of MCDR. As on date, there is no valid mining plan document of the lease area since 01.04.2017. The last approved document was for the period of 2012-13 to 2016-17.

Details of violations observed during current inspection and compliance position of violation pointed out

Violation observed		Show cause position	
Rule NO.	Issued on Compliance on	Rule NO.	Issued on Compliance on

Date :

(VIKRAM DESHPANDE)

Indian Bureau of Mines