

INDIAN BUREAU OF MINES

--:-- Inspection Report --:--

Part-I : General Information

1.1.1 Mine Details

Name of the Mine :	38GUJ08341	Lease Area (Ha) :	51.92
Forest Area (Ha) :	51	Mine Code :	38GUJ08341
Registration Number :	IBM/280/2011	Name of lessee :	SAURASHTRA CEMENT LTD
Address of lessee :	Near Railway Station, Ranavav ,Ranavav, Ranavav	Phone of lessee :	2801-234200
Email of lessee :	Pkdeshpande@mehtagroup.com	Fax Number :	N/A
Village :	Bhetali	Taluka / Mandal :	Patan-Veraval
District :	Gir Somnath	Pincode :	360550
State :	Gujarat	Post Office :	N/A
Nearest Police Station :	Talala	Nearest Railway Station :	Veraval
Date of Grant of Mining Lease :	2002-04-17	Date of Mining Lease Execution :	2002-04-17
Date of opening in the mine :	2017-04-05		

Nominated Owner Details			
Name of the Nominated Owner :	Mr MOHINDERPAL SINGH GILOTRA	Nominated Owner Address:	Flat No.903, Maitri Heights, Mumbai East
Nominated Owner Mobile :	9979848701	Nominated Owner Email :	Msgilotra@mehtagroup.com
Nominated Owner Fax Number :	Nil	Date of Nominated Owner Appointment :	1995-11-01
Mining Engineer Details			
Name of the Mining Engineer :	Mr. Santosh Kumar Singh,	Qualification of Mining Engineer :	BE- Mining Engineer (Experience: 17 Years)
Address of Mining Engineer :	M/s Saurashtra Cement Ltd, Sidheegram, Off Veraval-Kodinar Highway, Taluka: Sutrapada, P.O. Prashanawada, District: Gir- Somnath, Gujarat: 362 275.	Phone of Mining Engineer :	7898908472
Email of Mining Engineer :	Santosh.singh@mehtagroup.com	Fax Number of Mining Engineer :	N/A
Date of Mining Engineer Appointment :	2024-03-01		
Geologist Details			
Name of the Geologist :	Rajput Akashsingh Kuldipsingh	Qualification of Geologist :	M. Sc Geology
Address of Geologist :	M/s Saurashtra Cement Ltd, Sidheegram, Off Veraval-Kodinar Highway, Taluka: Sutrapada, P.O. Prashanawada, District: Gir- Somnath, Gujarat: 362 275.	Phone of Geologist :	7895337542
Email of Geologist :	Akash.rajput@mehtagroup.com	Fax Number of Geologist :	N/A
Date of Geologist Appointment :	2024-07-17		
Mine Manager Details			
Name of the Mine Manager :	Mr. Santosh Kumar Singh,	Qualification of Mine Manager :	BE- Mining Engineer (Experience: 17 Years)

Address of Mine Manger :	M/s Saurashtra Cement Ltd, Sidheegram, Off Veraval-Kodinar Highway, Taluka: Sutrapada, P.O. Prashanawada, District: Gir- Somnath, Gujarat: 362 275.	Phone of Mine Manger :	2876286540
Email of Mine Manger :	Santosh.singh@mehtagroup.com	Fax Number of Mine Manger :	N/A
Date of Mine Manger Appointment :	2024-03-01		
Mineral(s) granted in lease and proved for mining :	LIMESTONE	Date of Approval of Mining Plan / Modified Mining Plan / ROMP with five-year period :	2023-01-19 (2022 - 2026)
Method of mining :	Open Cast	Category :	OTHER THAN MECHANISED
Nature of Use :	Captive		

Part-II : Other Information

2.1.1 : Inspection Details

Inspecting Officer :	Mohammad Nimar
Designation :	Deputy Controller Of Mines
Name of the Accompanying Official from Mine :	Mr. Santosh Kumar Singh
Designation of the Accompanying Official :	Mining Engineer
Type of Inspection :	MCDR,STR
Date of Inspection :	10/07/2025
Review year considered for MCDR Inspection :	2024-2025

Final Submitted

2.2.1 : Exploration Details

S.N.	Items for Reporting		As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Number of Core Boreholes		Not Proposed	Not Applicable	Nil	No Violation	Entire lease Area is explored in G1 level	Nil
2	Number of DTH Boreholes		Not Proposed	Not Applicable	Nil	No Violation	Nil	Nil
3	Number of exploratory pits / trial pits		Not Proposed	Not Applicable	Nil	No Violation	Nil	Nil
4	Number of exploratory Trenches		Not Proposed	Not Applicable	Nil	No Violation	Nil	Nil
5	Lateral exploration status for the lease area	G1	51.9215Ha	51.9215Ha	Nil	No Violation	Entire lease Area is explored in G1 level	Nil
6		G2	Not Proposed	Not Applicable	Nil	No Violation	Nil	Nil
7		G3	Not Proposed	Not Applicable	Nil	No Violation	Nil	Nil
8		G4	Not Proposed	Not Applicable	Nil	No Violation	Nil	Nil
9	UNFC category wise reported Resources/Reserves as per MP/MMP ROMP Total Reserves (111, 121 & 122) and Total Mineral Resources (331, 332 &		LIMESTONE - Total Reserve = 6664666.11 , Total Resource = 323436.34	7.7193 (111), 2.4615 (221), Total: 10.1908	Very less	No Violation	Nil	Nil

	333 upto 334)					
--	---------------	--	--	--	--	--

2.3.1 : Development - Opencast Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Location of development w.r.t. lease area	Pit : Virgin Area & Direction : South block	Latitude: 2318101.96 N To 2318425.94 N Longitude: 659797.75 E To 660141.62 E	With proposed area	No Violation	Nil	Nil
2	Quantity of overburden generation in m3	Not proposed	Not Applicable	Nil	No Violation	Nil	Nil
3	Quantity of topsoil generation in m3	24222	24222	0.000	No Violation	Nil	Nil
4	Stripping ratio : ore to OB ratio	1: 0.000	1: 0.000	Nil	No Violation	Nil	Nil

2.4.1 Exploitation - Opencast Mine Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Number of pits / Blocks proposed for production	Pit ID : Virgin area	Pit ID: 1	Nil	No Violation	Nil	Nil
2	Quantity of ROM mineral production proposed (in T)	1000000	90776.810	909223.190	No Violation	Capacity of Environment Clearance is 1,44,000 MT. Application for enhancement of EC is under process.	Nil
3	Recovery of salable/usable mineral quantity from ROM production in T)	1000000	90776.810	909223.190	No Violation	Nil	Nil
4	Quantity of mineral reject/Sub-grade generation	0.00	0	0.000	No Violation	Nil	Nil
5	Grade of mineral reject/sub-grade generation as per threshold value declared	Not Proposed	Not Proposed	Nil	No Violation	Nil	Nil
6	Manual/Mechanised method adopted for segregating subgrade/mineral rejects from ROM	Not Proposed	Not Proposed	Nil	No Violation	Nil	Nil
7	Whether height of benches in Overburden& mineral suitable for method of mining proposed in mining plan	Proposed 5.5 meters	within 5.5 meter	Nil	No Violation	Nil	Nil
8	Any analysis or beneficiation study proposed & carried out for sub-grade mineral and reject	Not Proposed	Not applicable	Nil	No Violation	Nil	Nil

2.4.3 : Exploitation - Dump Working Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Number of dumps proposed for production	Not Proposed	Not Applicable	Nil	No Violation	Nil	Nil
2	Quantity of dump material handling Proposed (in Tonne)	Not Proposed	Not Applicable	Nil	No Violation	Nil	Nil
3	Recovery of salable/usable mineral from dump production (in Tonne)	Not Proposed	Not Applicable	Nil	No Violation	Nil	Nil
4	Production from dump(s) during the year	Not Proposed	Not Applicable	Nil	No Violation	Nil	Nil
5	Quantity of mineral reject generation	Not Proposed	Not Applicable	Nil	No Violation	Nil	Nil
6	Grade of mineral reject generation and threshold value declared	Not Proposed	Not Applicable	Nil	No Violation	Nil	Nil
7	Any analysis or beneficiation study proposed & carried out for mineral reject	Not Proposed	Not Applicable	Nil	No Violation	Nil	Nil
8	Manual / Mechanized method adopted for dump working	Not Proposed	Not Applicable	Nil	No Violation	Nil	Nil

2.5.1 : OB/Waste Dumps Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Separate dumping of topsoil, OB & mineral rejects, fines, tailings (Rule 36,37)	No proposal	Not Applicable	Nil	No Violation	Nil	Nil
2	Location of Topsoil, OB/Waste, Mineral Reject dumps, Tailings and Fines	Pit-1,2,3	Pit-1,2,3	Nil	No Violation	Generated Topsoil utilized for concurrent use in plantation	Nil
3	Number of active & Inative dumps	No proposal	Not Applicable	Nil	No Violation	Nil	Nil
4	Number of dead dumps	No proposal	Not Applicable	Nil	No Violation	Nil	Nil
5	Number of dumps proposed for stabilished	No proposal	Not Applicable	Nil	No Violation	Nil	Nil
6	Stabilization Technique (Terracing, plantation, geo-textiles etc.)	No proposal	Not Applicable	Nil	No Violation	Nil	Nil

Final Submitted

2.6.1 : Solid Waste Management - Backfilling (Opencast) Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Status on part or full extraction of mineral from mined out area before starting backfilling	No proposal	Not Applicable	Nil	No Violation	Nil	Nil
2	Year-wise area under backfilling of mined out area	No proposal	Not Applicable	Nil	No Violation	Nil	Nil
3	Year-wise topsoil generation, Utilization and Stored proposal (in m3)	Generated :24222 Utilized :24222 Stored :0.00	Generated :24222 Utilized :24222 Stored :0.00	Nil	No Violation	Nil	Nil
4	Total area fully reclaimed & rehabilitated	No proposal	Not Applicable	Nil	No Violation	Nil	Nil
5	Locations of proposed reclamation & rehabilitated	No proposal	Not Applicable	Nil	No Violation	Nil	Nil

Final Submitted

2.7.1 : Progressive Mine Closure Plan (PMCP) Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Compliance on reclamation and rehabilitation by backfilling/Other means Total area and numbers of plantation proposed.	Plantation : Location :West, Area : 0.1000, No. of Plant : 100 Plantation : Location :Central, Area : 0.1000, No. of Plant : 100	Plantation : Location :West, Area : 0.1000, No. of Plant : 250 Plantation : Location :Central, Area : 0.25 Ha No. of Plant : 100	Nil	No Violation	Plantation around the road side done	Nil
2	Rehabilitation by making water reservoir	No Proposal	Not Applicable	Nil	No Violation	Nil	Nil
3	Compliance of Rehabilitation of waste land within lease i) Afforestation ii) Area rehabilitated (ha) iii) Method of rehabilitation	No Proposal	Not Applicable	Nil	No Violation	Nil	Nil
4	Compliance of Environmental monitoring (core zone & buffer zone)	As per the Statute	Carried out quarterly through NABL accredited lab	Nil	No Violation	Nil	Nil

Final Submitted

2.8.1 : Mineral Conservation Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	ROM Mineral dispatch or grade-wise sorting within lease area	1000000.00	113268.810	886731.190	No Violation	Opening Stock of 22292 T was available at Mine head	Nil
2	Different grade of mineral sorted out at mines	1000000.00	1000000.00	0.000	No Violation	Nil	Nil
3	Any beneficiation process at mines	No Proposal	Not Applicable	Nil	No Violation	Nil	Nil
5	Utilization of Mineral Rejects or Sub-grade (Blending at ROM stage, Blending after Processing etc.)	No Proposal	Not Applicable	Nil	No Violation	Nil	Nil

Final Submitted

2.9.1 : Environment Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Separate removal and utilization of topsoil	24222.00	24222.00	0.000	No Violation	Nil	Nil
2	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	No Proposal	Not Applicable	Nil	No Violation	Nil	Nil
3	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	No Proposal	Not Applicable	Nil	No Violation	Nil	Nil
4	Plantation & Survival rate	Plantation : 100, Survial Rate : 80	Plantation : 250 Survial Rate : 80	Nil	No Violation	Plantation around total road side area in done.	Nil
5	Water sprinkling on roads to control airborne dust	Through Water Tanker	Through Water Tanker	Nil	No Violation	Nil	Nil

2.10 : Annual Return Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Submission of Online Monthly and Annual returns in prescribed period or	Within Stipulated time period	Annual Return 2024-25 was	Nil	No Violation	Nil	Nil

	not		submitted on 06-06-2025, Monthly returns are being submitted within the time frame				
2	Appointment of Mining Engineer & Geologist as per provisions of Rule 55 of MCDR,2017	Geologist : Rajput Akashsingh Kuldipsingh & Date of Appointment : 2024-07-17 Mine Engineer : Santosh Kumar Singh & Date of Appointment : 2024-03-26	Geologist : Rajput Akashsingh Kuldipsingh & Date of Appointment : 2024-07-17 Mine Engineer : Santosh Kumar Singh & Date of Appointment : 2024-03-01	Nil	No Violation	Nil	Nil
3	Whether incomplete or false or wrong returns submitted (Rule 45(7))	Water tanker was proposed.	No water tanker reported	Water tanker not shown	Rule 45(7)	Water Tanker for dust suppression is not shown as proposed.	Nil
4	Status of Approval of FMPCP u/r 24, 25 of MCDR,2017	Not Applicable	Validity of lease is up to 16.04.2052	Nil	No Violation	Nil	Nil
5	Notices and Returns for the lease area submitted or not where fine applicable	Not Applicable	submitted within the time frame	Nil	No Violation	Nil	Nil
6	Scrutiny of Annual return on sale value, Ex. Mine price & production cost	Ex-mine price : 385.42 Captive Consumption	Ex-mine price : 385.42 Captive Consumption	Nil	No Violation	Nil	Nil

Final
Submitted

2.11 : SDF Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Start Ratings accorded for mine during last 3 years	To be submitted within stipulated time period. Star 2023-2024 , Rating: 3 Star	Year of Submission : Star Rating for the year 2021-22 2022-23 not submitted Star 2023-2024 , Rating: 3 Stars	Nil	No Violation	For the year 2021-22 SCN was issued and complied. for the year 2022-23 working days were less than 180 days. so Star Rating couldnt be submitted	Nil

Part-III : Other Reports

3.1.1 : Upload Other Reports

S.N.	Reports File	Remark File Description
1	Nil	Mine is working as per the proposal

Final Submitted

Part-IV : Summary Details

4.1 : Summary of Violations

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Annual Return : Whether incomplete or false or wrong returns submitted (Rule 45(7))	Water tanker was proposed.	No water tanker reported	Water tanker not shown	Rule 45(7)	Water Tanker for dust suppression is not shown as proposed.	Nil

Final Submitted

Esigned by:  Mohammad Nimar
Date: 27/11/2025 05:04:32 PM